

REG. BY: Thuan 1 Ntuc

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No _____
Claims No _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.
Bal or Market Value: _____
IDAC Accident Report: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est Repairs: 2 days / Res.: Yes or No
Lum Sum: _____ % / J Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____
Vehicle: IN / OUT

N/S	O/S

Veh No: SH4601P Yr Bagn: 13/12/17
Type: M.Car / M.Cycle / Bus / Van / Lorry / Auto Prime Mover /
Truck / Trailer or
Make: Hyundai 140 cc 1685
Colour: blue AC: Insured / Std / NI / NA
Sp. Reading: 511231 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: hmt1LB41umt1uo98598
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Good / Jammed / Leaked / Burnt or
Brake: Good / Jammed / Leaked / Burnt or
Mod: Nil / S/Rim / STD NRIm or
Tyre Size: F: 206/60R16
R: 206/60R16
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Westlake
Front: _____ Rear: _____
R/Bal. 5 mm R/Bal. 5 mm
L/Bal. 5 mm L/Bal. 5 mm
D.O.A. 29/12/21 D.O.I. 31/12/21 1115
Survey held at CDGE
Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Rebate: 3/013</u>

Case/Time File Pass to? ☐ : Procl. Report
1) ☐ : Final Report
Date/Time File Return to? _____
Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invq (\$ _____)
☐ : V/A & Rpt (\$ _____)
Days Of Repair: _____
Resurvey No. of Trip: _____
Survey Fee:

Transportation:	_____
S + RS: \$	_____
Finch	_____
Other	_____
Total	_____

COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATE

DATE: 31-Dec-21

MODEL: Hyundai i40

VEHICLE NO.: SH 9601P ✓

LKK-

INSURANCE: CHINA TAIPING (45)

MVA: LIM T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Bumper	1		\$553.00 X
	Rear Bumper Under Cover	1		\$228.00 X SUC
	Rear Bumper Sponge	1		\$119.50 X NN
	Rear Bumper Reinforcement	1		\$428.40 X NN
	Rear Bumper Reinforcement Bracket RH / LH	2	\$80.30	\$160.60 X NN
	Rear Bumper Clips	10	\$2.20	\$22.00 / nec ✓
	SUB TOTAL			\$1,511.50
	LESS 20%			\$302.30
	DISCOUNTED TOTAL			\$1,209.20
	Rear Fender Adv.Sticker RH / LH	2	\$100.00	\$200.00 / nec
	Rear Bumper Adv.Sticker	1		\$50.00 / nic
	Reverse Sensors	1		\$135.70 / cut
	Rear Bumper Mat	1		\$50.00 X SUC ✓
	NETT TOTAL			\$435.70
	SPARE PARTS TOTAL			\$1,644.90
	<u>Labour Charge</u>			
	Panel Beating			\$300.00 280
	Spray Painting Charge			\$300.00 250
	R/I Reverse Sensors			\$120.00 20
	Towing Fee - chit attached			\$60.00 ✓
	TOTAL LABOUR			\$780.00
	ESTIMATE TOTAL			\$2,424.90

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Thevan @Chhanto-10m

822 35767

31/12/21 1115

L/S after repair photo

2 days wp ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: