

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

HL Assurance Pte Ltd
11 Keppel Road, #11-01 ABI Plaza
Singapore 089057

Our File No: CS/HLA22000465/EVF3E2

Date: 23/02/2022

REFERENCE

Insured/Claimant:	LOW LAI LENG FLORENCE	Policy No:	MP301419	
Date of Loss:	11/01/2022	Nature of Claim:	OD	Claim No: MPC03096/OD

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKV7288U		
Make & Model:	NISSAN QASHQAI, 1.2 DIG-T CVT ABS 2WD 5DR (A)	Engine No:	HRA2184222A
Reg. Date:	30/09/2015 (Man. Year: 2015)	Chassis No:	SJNFEAJ11U1472188
Colour:	Brown	Odometer:	62184 km
Engine Capacity:	1197 cc		
Market Value/New Car Price:	S\$44,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R17	Rear Tyre Size:	215/60 R17
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,724.75	2,094.75	630.00	23.12
Miscellaneous Items	910.75	120.00	790.75	86.82
Labour	1,550.00	810.00	740.00	47.74
Paintwork Labour	900.00	600.00	300.00	33.33
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,085.50	3,624.75	2,460.75	40.44
Approved Total (Overridden) (S\$)		2,900.00		
- Excess (S\$)	0.00	250.00	-250.00	
(S\$)	6,085.50	2,650.00	3,435.50	56.45
+ GST 7.00/7.00% (S\$)	425.99	185.50	240.49	56.45
Nett Amount (S\$)	6,511.49	2,835.50	3,675.99	56.45

INSPECTION

Date of Assignment:	13/01/2022 Present Location:	Accord Auto Services Pte Ltd (HQ) Accord Auto Services Pte Ltd (HQ) 10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point Singapore 568047
Date Inspected:	14/01/2022 Inspected At:	
Estimated Period of Repair:	5.0 days	

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Feb 2022)
Parts:	M1-SUV	NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKV7288U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RH FENDER (WCP)	Not Necessary	380.00 F	*- F
2	1		*FRONT RH FENDER WHEEL ARCH (WCP)	Not Necessary	220.00 F	*- F
3	1		*FRONT RH DOOR (WCP)	Dented	600.00 F	*600.00 F
4	1		*FRONT RH DOOR LOWER GARNISH (WCP)	Cut	250.00 F	*250.00 F
5	1		*FRONT RH DOOR STICKER(@SIDE PANEL) (WCP)	Necessary	40.00 F	*40.00 F
6	1		*REAR RH DOOR (WCP)	Dented	600.00 F	*600.00 F
7	1		*REAR RH DOOR LOWER GARNISH (WCP)	Cut	220.00 F	*220.00 F
8	2		*REAR RH DOOR STICKER(@SIDE LH & RH) (WCP)	Necessary	65.00 F	*65.00 F
9	1		*REAR RH FENDER WHEEL ARCH (WCP)	Cut	220.00 F	*220.00 F
F=Franchise part.						
Sub Total (\$\$)					2,595.00	1,995.00
+ Margin on L,N Items 5.00/5.00% (\$\$)					129.75	99.75
Total Parts (\$\$)					2,724.75	2,094.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	DOOR INNER TRIM BOARD CLIPS (NECESSARY)	50.00	20.00
2	1	FRONT & REAR FENDER SHIELD CLIPS (NOT NECESSARY)	30.00	0.00
3	1	RIM (CUT)	600.00	100.00
4	1	TYRE (NOT NECESSARY)	230.75	0.00
Sub Total (\$\$)			910.75	120.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	SPRAY PAINTING TO ALL AFFECTED AREAS	New	900.00	600.00
Labour Items				
2	LABOUR CHARGE REMOVE/REFIX ACCIDENT DAMAGES PARTS TO KNOCK,JACK,CUT WELD & REALIGN AFFECTED AREA	New	1,000.00	600.00
3	ANTI RUST TREATMENT	New	100.00	30.00
4	TO CHECK & ADJUST WHEEL ALIGNMENT	New	100.00	60.00
5	TO REMOVE/REPLACE TYRE & RIM	New	50.00	20.00
6	TO REMOVE/REFIX/REPLACE FRONT & REAR LH DOOR INNER COMPARTMENT, WINDOW GLASS, MECHEMISM & ASSY TO NEW DOOR	New	300.00	100.00
Gross Labour Cost (\$\$)			2,450.00	1,410.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >