

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBF 1377B

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	AXLE WHEEL FRONT	SERVICEABLE	26.00	-
1	SET BALANCER (UNIVERSAL-HEAVY)	CUT	91.00	91.00
1	BAR FOOTREST FRONT LH (CUT)	NOT CONSISTENT WITH THE IMPACT	16.00	-
1	BAR FOOTREST FRONT RH	CUT	16.00	16.00
1	BAR HANDLE	BENT	47.00	47.00
1	BOLT FOOTREST REAR	NOT NECESSARY	6.00	-
1	BOLT FOOTREST REAR	NOT NECESSARY	6.00	-
1	HEADLAMP ASSY	CRACKED	166.00	166.00
1	LAMP SIGNAL FRONT LH	CRACKED	24.00	24.00
1	LEVER BRAKE	BENT	16.00	16.00
1	METER IU (12V) NEW MODEL (CUT)	NOT CONSISTENT WITH THE IMPACT	300.00	-
1	MIRROR LH	SERVICEABLE	28.00	-
1	MUDGUARD FRONT (BLACK)	CUT	104.00	104.00
1	PEDAL BRAKE	BENT	25.00	25.00
1	PLUG OIL LEVEL	CUT	10.00	10.00
1	STAY HEADLIGHT	BENT	61.00	61.00
1	SET STEERING CONE	NOT NECESSARY	73.00	-
1	SWING ARM REAR	NOT NECESSARY	231.00	-
1	CLAMP EXHAUST (ADDITIONAL)	CUT	84.00	84.00
1	EMBLEM SET SQUARE C SUS/TI YOSHIMURA (ADDITIONAL)	NECESSARY	126.00	126.00
1	RE-COVER MUFFLER (ADDITIONAL)	DENTED	480.00	480.00
1	SWITCH NEUTRAL (ADDITIONAL)	NECESSARY	14.00	14.00
	LESS 10% DISCOUNT		-	-126.40
			1,950.00	1,137.60
	SPECIAL NETT ITEMS			
1	FORK (SN) (LOCAL REPAIR)	BENT	90.00	60.00
			90.00	60.00

Report Ref No. CS/UOI22000469/Uqy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	LABOUR			
	LABOUR.		552.00	280.00
			552.00	280.00
	GRAND TOTAL		2,592.00	1,477.60

RECOMMENDED COST OF LUMP SUM REPAIRS		1,150.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/UOI22000469/Uqy3e2

CHUA KANG SENG

Licensed Appraiser