

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22000474/UGA3Q2**Date:** 14/07/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070052821
Claimant Vehicle No :	SKN4264A	Insured Vehicle No :	SMT440D
Date of Loss:	21/01/2022	Nature of Claim:	TP
		Claim No:	9084469871SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKN4264A	Engine No:	CAXE42908
Make & Model:	VOLKSWAGEN JETTA, 1.4 TSI 1622G5 (A)	Chassis No:	WVWZZZ16ZEM036421
Reg. Date:	12/06/2014 (Man. Year: 2014)	Odometer:	91380 km
Colour:	Silver		
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40Z R18	Rear Tyre Size:	225/40Z R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,048.00	13,881.07	9,166.93	39.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,200.00	3,630.00	4,570.00	55.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	31,248.00	17,511.07	13,736.93	43.96
Approved Total (Overridden) (S\$)		14,000.00		
Nett Amount (S\$)	31,248.00	14,000.00	17,248.00	55.20
+ Loss of Use (4.0 x S\$50.00/day) (S\$)		200.00		
+ Car Rental (22.0 x S\$100.00/day) (S\$)		2,200.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		16,407.45		

INSPECTION

Date of Assignment:	26/01/2022		
Date Inspected:	26/01/2022	Inspected At:	Sin Hwee Motor Pte Ltd (HQ) Blk 3023A, Ubi Road 1, #01-59 Singapore 408717
Estimated Period of Repair:	20.0 days		

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER R/H	Badly Dented	650.00 F	*540.85 FN
2	1		*FRONT DOOR R/H	Badly Dented	2,300.00 F	*1,963.45 FN
3	1		*REAR DOOR R/H	Badly Dented	2,300.00 F	*1,562.25 FN
4	1		*SIDE SKIRT R/H	Distorted	485.00 F	*485.00 FN
5	1		*ROCKER PANEL R/H	Dented	587.00 F	*587.00 FN
6	1		*FRONT DOOR PILLAR R/H	Dented	568.00 F	*568.00 FN
7	1		*CENTRE DOOR PILLAR R/H	Dented	468.00 F	*468.00 FN
8	1		*FRONT DOOR POWER WINDOW GEAR	Bent	470.00 F	*436.95 FN
9	1		*FRONT DOOR POWER WINDOW MOTOR	Jammed	680.00 F	*640.55 FN
10	1		*FRONT DOOR INNER TRIM	Serviceable	1,480.00 F	*- FN
11	1		*FRONT DOOR INNER LOCK	Jammed	580.00 F	*357.30 FN
12	4		*DOOR HINGE	Serviceable	600.00 F	*- FN
13	1		*ROOF LINING	Deformed / Torn	1,700.00 F	*1,615.00 FN
14	2		*DOOR IMPACT SENSOR	Not Necessary	540.00 F	*- FN
15	2		*FRONT SAFETY BELT	Activated / Jammed	2,100.00 F	*1,721.30 FN
16	1		*CURTAIN AIR BAG	Activated	2,140.00 F	*1,800.00 FN
17	1		*AIR BAG CONTROL UNIT	Serviceable	2,000.00 F	*- FN
18	1		*DRIVER SEAT AIR BAG	Activated	2,500.00 F	*1,866.00 FN
19	2		*DOOR TOP MOULDING	Not Necessary	300.00 F	*- FN
20	2		*DOOR RUBBER	Not Necessary	600.00 F	*- FN

F=Franchise part. N=NettItemDisc.

Sub Total (S\$)	23,048.00	14,611.65
- Nett Item Discount on N Items 0.00/5.00% (S\$)	0.00	730.58
Total Parts (S\$)	23,048.00	13,881.07

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TRANSFER FRONT /REAR DOOR MECHANISMS FITTINGS AND TRIMS TO NEW DOORS	New	300.00	120.00
2	TO REMOVE AND REFIX DASHBOARD TO FACILITATE REPAIR WORK	New	650.00	0.00
3	TO REMOVE AND REFIT FRONT WINDSCREEN	New	200.00	0.00
4	WINDSCREEN SEALANT	New	150.00	0.00
5	TO REPLACE ,FRONT /DOOR DOOR PILLARS AND ROCKER PANEL INCLUDE KNOCKING ,CUTTING AND WELDING TO REPLACE ,INSTALL AND ALIGN AFFECTED PARTS TO SYMMETRICAL SPEC	New	3,800.00	2,000.00
6	TO DISMOUNT INNER CARPET ,SEATS AND ROOF LINING TO FACILITATE REPAIR WORK	New	450.00	200.00
7	TO REPLACE AND INSTALL CURTAIN AIR BAG AND CONTROL UNIT TO CARRY OUT AIR BAG SYSTEM PROGRAMMING AND CODING	New	250.00	200.00
8	TO SPRAY PAINT FRONT DOOR ,REAR DOOR ,ROCKER PANEL ,DOOR PILLARS ,FRONT FENDER AND SIDE SKIRT	New	2,000.00	1,000.00
9	TO CARRY OUT WIRE CHECKING AND RESET FAULT CODES	New	200.00	30.00
10	TUFF KOTE	New	200.00	80.00
Gross Labour Cost (\$\$)			8,200.00	3,630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >