



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJS 9559C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BONNET	BENT	1,140.40	1,140.40
1	FRONT BUMPER	BUCKLED / DENTED	564.60	489.60
1	FRONT GRILLE	CRACKED	559.50	466.10
	LESS 25% DISCOUNT		-566.13	-524.03
			1,698.37	1,572.07
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	FRONT NUMBER PLATE (SN)	BENT	20.00	20.00
1	FRONT NUMBER PLATE FRAME (SN)	BENT	20.00	20.00
			40.00	40.00
	<b><u>LABOUR</u></b>			
	KNOCKING PUSH OUT FRONT ACCIDENT PARTS STRIP / REFIT ABOVE ACCESSORIES.		400.00	320.00
	SPRAY PAINT & SPRAY ANTI-TUFF-KOTE ON FRONT ACCIDENT AFFECTED AREAS.		480.00	400.00
			880.00	720.00
	<b>GRAND TOTAL</b>		<b>2,618.37</b>	<b>2,332.07</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>1,850.00</b>

Report Ref No. CS/AIS22000475/Kvf3e2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.