

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
	AXA INSURANCE I	PTE LTD	Ref:	CS3/ASM22000477/Rvy3e2
	8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811		Date:	15/03/2022
	ATTN: LYNN KHON	NG	Code:	ASM
1.	Policy Particulars :- (THIRD PARTY CLAIM)			
	Insured Veh.	SHC 3536R	Veh. Inspected	SMC 8939U
	Policy No.	VFX/P2419138	Coverage (\$)	0.00
	Claim No.	S1M03NE0	Excess (\$)	0.00
	Assign From	LYNN KHONG	Assign Date	13/01/2022
2. Vehicle Particulars & Condition				
	Make & Model	NISSAN NV350 CARAVAN 2.5	c.c	2488
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	JN1UC4E26Z0022569	Colour	WHITE
	Odometer	52000 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15C	ҮОКОНАМА	6 mm
	L/H Front Tyre	195 R15C	YOKOHAMA	6 mm
	R/H Rear Tyre	195 R15C	YOKOHAMA	6 mm
	L/H Rear Tyre	195 R15C	YOKOHAMA	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.			
5.	General Information			
	Accident Date	29/11/2021	Inspect Date / Time	07/03/2022 (02:21 PM)
	Survey held at	BLK 160 SIN MING AUTOCITY #	#02-16 S(575722)	
	Repairer CMK MOTOR SERVICE REPAIR			
5a.	Remarks			
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000			
5b.	Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days			

Report Ref No. CS3/ASM22000477/Rvy3e2

Inspected By

Automotive Assessor

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser