

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL 64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711			Ref: <del>CS3/GRB21012831/R1vf3-1</del> Date: <del>20/12/2021</del> Code: GRB	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SNC 2169C	Veh. Inspected	SKR 8909B
	Policy No.		Coverage (\$)	0.00
	Claim No.		Excess (\$)	0.00
	Assign From	<del>SHIVANE SHARMA</del> CARINE KEK	Assign Date	<del>20/12/2021</del>
2. Vehicle Particulars & Condition				
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	-	Steering	
	Brakes		Modification	
	General			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4. Description of Damages				
5. General Information				
	Accident Date	17/12/2021	Inspection Date	20/12/2021
	Survey held at	KOI MOTOR WORKS BLK 176 SIN MING DRIVE #04-12 SIN MING AUTOCARE SINGAPORE 575721		
5a. Remarks				
	A) THE REPAIR ESTIMATE WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

(08/11/13) wef

ASS. REC. BY: John

REF:

CS3/WRB 21012831/RV3-1

851B

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKR 8909B  
 at Workshop m/s KOI MOTORWORKS  
 of 176 SIN MIN DR #04-12  
 Insured: SNC 2169C III

Policy No. D21MFL0000447Claims No. MFL2021D0005532


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.

Bal. or Market Value: 42K

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SKR 8909BYr Regn: 2015 / MARType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: HONDA VIZAL 1.5X AUTO c.c. 1496Colour: WHITEA/C: Insured / Std / NI / NASp. Reading: 137124T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: RUI1013706Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: \_\_\_\_\_

R: \_\_\_\_\_

215/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

TRIANGLE

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 17/12/21D.O.I. 20/12/21

Survey held at

KOI MOTORWORKS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

REAR N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 18K

22/12/21 Submit PRS

7/2/22 Submit LS \$6400 (red 3600, 36%)

ESTIMATE RANGE OF REPAIR - (3K-4K) / 5 days

Date/Time, File Pass to?

☐

: Prell. Report

Days Of Repair: 7

1)

☐

: Final Report

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Date/Time, File Return to?

Transportation: \_\_\_\_\_

2) 7/2/22-typist

Add Fee: ☐

: Site Insp (\$

) : S + RS, SI

☐ : Interview (\$

) : Photos

☐ : Tech. Invs (\$

) : Others

Report Format: TP

# PRESTIGE APPRAISER SERVICES

Vehicle No : SKR 8909 B

Our Ref :

PS/018/12/21

Qty	Descriptions	Conditions	Repairer's Est.	Our Revised.
<u>LIST ITEMS</u>				
1	rear bumper	dented	\$ 1,062.70	\$ 1,062.70 <b>589</b>
2	rear bumper bracket	dented	64.00	64.00 <b>32</b>
2	rear bumper side retainer <b>xnn</b>	necessary	65.00	65.00 <b>x</b>
8	rear bumper clip	necessary	44.00	44.00 <b>✓</b>
1	R/H rear bumper reflector	serviceable	121.00	-
1	L/H rear bumper reflector	broken	121.00	121.00 <b>81</b>
<b>2</b> 1	rear bumper side <b>LH @195</b>	dented/cracked	630.00	630.00 <b>195</b>
1	rear bumper lower dust cover	dented/distorted	265.00	265.00 <b>250</b>
1	rear end panel	dented	514.00	514.00 <b>✓</b>
1	rear end panel top garnish	dented/cracked	335.00	335.00 <b>132</b>
4	rear end panel top garnish clip	necessary	44.00	44.00 <b>✓</b>
<b>2</b> 1	taillamp <b>LH @460</b>	grazed/cut	1,360.00	1,360.00 <b>460</b>
2	taillamp panel	dented - repair	370.00	-
1	tailgate	dented/distorted	1,320.90	1,320.90 <b>1100</b>
1	tailgate weatherstrip	distorted	196.00	196.00 <b>97</b>
1	tailgate top lock	dented	258.00	258.00 <b>180</b>
1	tailgate lower lock	dented	95.00	95.00 <b>55</b>
<b>2</b>	tailgate reflector <b>LH @390</b>	grazed/cut	950.00	950.00 <b>390</b>
2	tailgate absorber	serviceable	420.00	-
1	tailgate outer garnish	serviceable	421.20	-
1	tailgate emblem ' VEZEL '	necessary	55.00	55.00 <b>✓</b>
1	tailgate inner trimboard	holder cracked	653.20	653.20 <b>376</b>
1	tailgate lock sensor	damaged	215.00	215.00 <b>105</b>
1	spare wheel panel	dented	1,030.00	1,030.00 <b>✓</b>
1	spare wheel top cover <b>xnn</b>	dented/distorted	398.00	398.00 <b>x</b>
1	spare wheel sponge	cracked	355.00	355.00 <b>320</b>
1	L/H spare wheel side panel <b>repair</b>	dented	105.00	105.00 <b>x</b>
1	L/H rear fender	dented - repair	1,265.00	-
1	L/H rear fender inner garnish	dented/distorted	425.00	425.00 <b>325</b>
1	rear windscreen moulding	necessary	165.00	165.00 <b>95</b>
	<b>6469</b>		13,323.00	10,725.80
	<b>20%</b>	Less 20%	-	2,145.16
	<b>5175.20</b>		\$ 13,323.00	\$ 8,580.64
<u>S/NETT ITEMS</u>				
1	rear windscreen sealant	necessary	60.00	45.00 <b>30</b>
2	reverse sensor	damaged	350.00	280.00 <b>200</b>
1	rear number plate <b>xnn</b>	dented	60.00	50.00 <b>x</b>
				<b>230</b>
<u>Labour Charges &amp; Misc</u>				
	To dismantle & replace damaged parts, panel beat where necessary.		1,900.00	1,600.00 <b>1200</b>
	To putty, apply primer & spray-paint on the affected portion.		1,400.00	1,200.00 <b>1000</b>
	To apply rust-proofing on repaired, replaced panel.		220.00	180.00 <b>80</b>
	To remove/refit rear windscreen glass to facilitate repairs.		220.00	160.00 <b>120</b>
	To remove/refit rear cushion seat, speaker board, roof upholstery to facilitate repairs.		200.00	160.00 <b>100</b>
	Balance c/f	\$	17,733.00	\$ 12,255.64
				<b>2500</b>

# PRESTIGE APPRAISER SERVICES

Vehicle No : SKR 8909 B

Our Ref : PS/018/12/21


Qty	Descriptions	Conditions	Repairer's Est.	Our Revised.	
		Balance b/d	\$ 17,733.00	\$ 12,255.64	
	To remove/transfer tailgate components.		160.00	120.00	<b>60</b>
	To remove/renew reverse sensor.		80.00	60.00	<b>40</b>
	To check wiring functions.		90.00	70.00	<b>30</b>
			<u>\$ 18,063.00</u>	<u>\$ 12,505.64</u>	<b>130</b>
			<b>5175.20</b>		
			<b>230.00</b>		
			<b>2500.00</b>		
			<b>130.00</b>		
			<b>8035.20</b>		
			<b>20%</b>		
			<b>6428.16</b>		
			<b><u>L/S-\$6,400.00/7DAYS</u></b>		

**Note:** The repairer has agreed to undertake the repairs at our adjusted amount of **\$10,000.00 lump sum** corresponding to supply of parts, labour and spray-painting charges.

Under normal circumstances, the estimated repair period would be **EIGHT ( 8 )** days.

Pursuant to your instruction we have **not** authorised repairs on your behalf.

PRESTIGE APPRAISER SERVICES



LOUIS S C NG CAE AMIMI (UK)

Licensed Appraiser

Dip. MTM. Automotive Engineer

## SKR 8909B

589.00	30.00	1200.00	5175.20
32.00	200.00	1000.00	230.00
44.00	230.00	80.00	2630.00
81.00		120.00	8035.20
195.00		100.00	0.80
250.00		60.00	6428.16
514.00		40.00	
132.00		30.00	
44.00		2630.00	
460.00			
1100.00			
97.00			
180.00			
55.00			
390.00			
55.00			
376.00			
105.00			
1030.00			
320.00			
325.00			
95.00			
6469.00			
0.80			
5175.20			



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL  
64 CECIL STREET  
#05-02 IOB BUILDING SINGAPORE 049711

Ref: CS3/GRB21012831/Rvf3e2-1

Date: 10/02/2022

Code: GRB

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SNC 2169C	<b>Veh. Inspected</b>	SKR 8909B
<b>Policy No.</b>	D21MFL0000447	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	MFL2021D0005532	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	CARINE KEK	<b>Assign Date</b>	11/01/2022

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	HONDA VEZEL 1.5X AUTO	<b>c.c</b>	1496
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2015
<b>Chassis No.</b>	RU11013706	<b>Colour</b>	WHITE
<b>Odometer</b>	137124 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	FAIR		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	215/60 R16	TRIANGLE	6 mm
<b>L/H Front Tyre</b>	215/60 R16	TRIANGLE	6 mm
<b>R/H Rear Tyre</b>	215/60 R16	TRIANGLE	6 mm
<b>L/H Rear Tyre</b>	215/60 R16	TRIANGLE	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	17/12/2021	<b>Inspection Date</b>	20/12/2021
<b>Survey held at</b>	KOI MOTOR WORKS BLK 176 SIN MING DRIVE #04-12 SIN MING AUTOCARE SINGAPORE 575721		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **7 Working Days**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKR 8909B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER	DENTED	1,062.70	589.00
2	REAR BUMPER BRACKET	DENTED	64.00	32.00
2	REAR BUMPER SIDE RETAINER	NOT NECESSARY	65.00	-
8	REAR BUMPER CLIP	NECESSARY	44.00	44.00
1	R/H REAR BUMPER REFLECTOR	SERVICEABLE	121.00	-
1	L/H REAR BUMPER REFLECTOR	BROKEN	121.00	81.00
2	REAR BUMPER SIDE	N/S DENTED / CRACKED	630.00	195.00
1	REAR BUMPER LOWER DUST COVER	DENTED / DISTORTED	265.00	250.00
1	REAR END PANEL	DENTED	514.00	514.00
1	REAR END PANEL TOP GARNISH	DENTED / CRACKED	335.00	132.00
4	REAR END PANEL TOP GARNISH CLIP	NECESSARY	44.00	44.00
2	TAILLAMP	N/S GRAZED / CUT	1,360.00	460.00
2	TAILLAMP PANEL	TO REPAIR SEE LABOUR	370.00	-
1	TAILGATE	DENTED / DISTORTED	1,320.90	1,100.00
1	TAILGATE WEATHERSTRIP	DISTORTED	196.00	97.00
1	TAILGATE TOP LOCK	DENTED	258.00	180.00
1	TAILGATE LOWER LOCK	DENTED	95.00	55.00
2	TAILGATE REFLECTOR	N/S GRAZED / CUT	950.00	390.00
2	TAILGATE ABSORBER	SERVICEABLE	420.00	-
1	TAILGATE OUTER GARNISH	SERVICEABLE	421.20	-
1	TAILGATE EMBLEM 'VEZEL'	NECESSARY	55.00	55.00
1	TAILGATE INNER TRIMBOARD	HOLDER CRACKED	653.20	376.00
1	TAILGATE LOCK SENSOR	DAMAGED	215.00	105.00
1	SPARE WHEEL PANEL	DENTED	1,030.00	1,030.00
1	SPARE WHEEL TOP COVER	NOT NECESSARY	398.00	-
1	SPARE WHEEL SPONGE	CRACKED	355.00	320.00
1	L/H SPARE WHEEL SIDE PANEL	TO REPAIR SEE LABOUR	105.00	-

Report Ref No. CS3/GRB21012831/Rvf3e2-1



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	L/H REAR FENDER	TO REPAIR SEE LABOUR	1,265.00	-
1	L/H REAR FENDER INNER GARNISH	DENTED / DISTORTED	425.00	325.00
1	REAR WINDSCREEN MOULDING	NECESSARY	165.00	95.00
	LESS 20% DISCOUNT		-	-1,293.80
			13,323.00	5,175.20
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	60.00	30.00
2	REVERSE SENSOR (SN)	DAMAGED	350.00	200.00
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	60.00	-
			470.00	230.00
	<b><u>LABOUR</u></b>			
	TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY. INCLUSIVE OF THE REPAIR OF TAILLAMP PANEL, L/H SPARE WHEEL SIDE PANEL AND L/H REAR FENDER.		1,900.00	1,200.00
	TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.		1,400.00	1,000.00
	TO APPLY RUST-PROOFING ON REPAIRED, REPLACED PANEL.		220.00	80.00
	TO REMOVE / REFIT REAR WINDSCREEN GLASS TO FACILITATE REPAIRS.		220.00	120.00
	TO REMOVE / REFIT REAR CUSHION SEAT, SPEAKER BOARD, ROOF UPHOLSTERY TO FACILITATE REPAIRS.		200.00	100.00
	TO REMOVE / TRANSFER TAILGATE COMPONENTS.		160.00	60.00
	TO REMOVE / RENEW REVERSE SENSOR.		80.00	40.00
	TO CHECK WIRING FUNCTIONS.		90.00	30.00
			4,270.00	2,630.00
<b>GRAND TOTAL</b>			<b>18,063.00</b>	<b>8,035.20</b>



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			<b>6,400.00</b>
---	--	--	-----------------

Report Ref No. CS3/GRB21012831/Rvf3e2-1

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.