

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22000482/KVF3N2**Date:** 22/03/2022**REFERENCE**Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00058402100

**Claimant Vehicle  
No :** SGY4978M**Insured  
Vehicle No :** SJP5790S

Date of Loss: 10/01/2022

Nature of Claim: TP

Claim  
No: SNM22D200290/C02/LEEPG**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SGY4978M**

Make &amp; Model: TOYOTA VIOS E, 1.5 (A)

Engine No: 1NZX603173

Reg. Date: 27/09/2007 (Man. Year: 2007)

Chassis No: MR053HY9305020246

Colour: White

Odometer: 395214 km

Engine Capacity: 1497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

**CONDITION OF TYRES**

Front Tyre Size: 185/65R15

Rear Tyre Size: 185/65R15

Front Left Side: KAPSEN 8 mm

Rear Left Side: Sumitomo 8 mm

Front Right Side: KAPSEN 8 mm

Rear Right Side: Sumitomo 8 mm

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                    | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                    | 7,611.14          | 2,425.99          | 5,185.15          | 68.13         |
| Miscellaneous Items                      | 0.00              | 0.00              | 0.00              |               |
| Labour                                   | 2,100.00          | 1,360.00          | 740.00            | 35.24         |
| Paintwork Labour                         | 0.00              | 0.00              | 0.00              |               |
| Towing                                   | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>      | <b>9,711.14</b>   | <b>3,785.99</b>   | <b>5,925.15</b>   | <b>61.01</b>  |
| <b>Approved Total (Overridden) (S\$)</b> |                   | <b>3,000.00</b>   |                   |               |
| <b>(S\$)</b>                             | 9,711.14          | 3,000.00          | 6,711.14          | 69.11         |
| <b>+ GST 7.00/7.00% (S\$)</b>            | 679.78            | 210.00            | 469.78            | 69.11         |
| <b>Nett Amount (S\$)</b>                 | <b>10,390.92</b>  | <b>3,210.00</b>   | <b>7,180.92</b>   | <b>69.11</b>  |

**INSPECTION**

Date of Assignment: 13/01/2022

Date Inspected: 13/01/2022 Inspected At:

Thiam Heng Huat Pte Ltd (SIN MING)  
176 SIN MING DRIVE, #05-14  
Singapore 575721

Estimated Period of Repair: 5.0 days

**Adjuster:** KENNETH KONG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                      |                                                                                                                                                                              |                                                         |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------|
| <b>Part Source:</b>  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 20 Mar 2022)           |
| <b>Parts:</b>        | 143                                                                                                                                                                          | TOYOTA VIOS E 1.5 (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                       |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SGY4978M)                                                                                                                                    |                                                         |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                         |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                         |

### Recommended Parts

| No. | Qty | Part No. | Particulars                          | Condition       | Repairer's  | Amount     |
|-----|-----|----------|--------------------------------------|-----------------|-------------|------------|
| 1   | 1   |          | *REAR BUMPER ASSY                    | Bent            | 495.70 FL   | *495.70 FL |
| 2   | 1   |          | *SET REAR BUMPER CLIPS               | Necessary       | 80.00 FL    | *50.00 FL  |
| 3   | 1   |          | *REAR BUMPER REFLECTORS              | O/s Mtg Cracked | 190.00 FL   | *95.00 FL  |
| 4   | 1   |          | *REAR BUMPER SIDE RETAINERS          | O/s Distorted   | 205.60 FL   | *102.80 FL |
| 5   | 1   |          | *REAR END PANEL                      | Bent            | 698.50 FL   | *590.00 FL |
| 6   | 1   |          | *REAR END PANEL GARNISH              | Mtg Distorted   | 225.50 FL   | *158.60 FL |
| 7   | 1   |          | *SET REAR END PANEL GARNISH CLIPS    | Necessary       | 50.00 FL    | *50.00 FL  |
| 8   | 1   |          | *SPARE TRYE COMPARTMENT PANEL        | Repair          | 637.70 FL   | *- FL      |
| 9   | 1   |          | *TAIL LAMPS                          | O/s Cracked     | 684.80 FL   | *283.75 FL |
| 10  | 1   |          | *TAIL LAMPS GASKET                   | O/s Necessary   | 70.20 FL    | *35.10 FL  |
| 11  | 2   |          | *TAIL LAMP PANELS                    | Repair          | 233.00 FL   | *- FL      |
| 12  | 2   |          | *REAR FENDERS                        | Repair          | 1,670.60 FL | *- FL      |
| 13  | 2   |          | *REAR FENDER INNER GARNISH           | Serviceable     | 495.50 FL   | *- FL      |
| 14  | 2   |          | *SET REAR FENDER INENR GARNISH CLIPS | Not Necessary   | 100.00 FL   | *- FL      |
| 15  | 1   |          | *REAR BOOT ASSY                      | Bent            | 720.60 FL   | *681.20 FL |
| 16  | 2   |          | *REAR BOOT HINGES                    | Repair          | 130.90 FL   | *- FL      |
| 17  | 1   |          | *REAR BOOT LOCK                      | Dented          | 109.50 FL   | *109.50 FL |
| 18  | 1   |          | *REAR BOOT LATCH                     | Repair          | 13.55 FL    | *- FL      |
| 19  | 1   |          | *REAR BOOT LOGO                      | Necessary       | 53.90 FL    | *53.90 FL  |
| 20  | 1   |          | *REAR BOOT OUTER HANDLE              | Serviceable     | 181.70 FL   | *- FL      |
| 21  | 1   |          | *REAR EMBLEM VIOS                    | Necessary       | 51.90 FL    | *51.90 FL  |
| 22  | 1   |          | *REAR EMBLEM E                       | Necessary       | 40.20 FL    | *40.20 FL  |
| 23  | 1   |          | *REAR BOOT RUBBER (50%)              | Dented/Cut      | 146.63 FS   | *97.75 FS  |
| 24  | 1   |          | *SET REVERSE SENSORS                 | Shorted         | 280.00 FS   | *200.00 FS |
| 25  | 1   |          | *REAR BUMPER LOWER SKIRT             | No such part    | 800.00 FS   | *- FS      |
| 26  | 1   |          | *REAR BOOT TOP SPOILER               | No such part    | 800.00 FS   | *- FS      |
| 27  | 1   |          | *REAR NUMBER PLATE                   | Serviceable     | 80.00 FS    | *- FS      |
| 28  | 1   |          | *REAR EMBLEM SPORT                   | No such part    | 50.00 FS    | *- FS      |
| 29  | 1   |          | *PANEL SEALANT                       | Necessary       | 100.00 FS   | *30.00 FS  |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                            |                 |                 |
|------------------------------------------------------------|-----------------|-----------------|
| <b>Sub Total (\$\$)</b>                                    | <b>9,395.98</b> | <b>3,125.40</b> |
| <b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b> | 1,784.84        | 699.41          |
| <b>Total Parts (\$\$)</b>                                  | <b>7,611.14</b> | <b>2,425.99</b> |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No                              | Particulars    | Lab.Type | Repairer's      | Amount          |
|---------------------------------|----------------|----------|-----------------|-----------------|
| <b>Labour Items</b>             |                |          |                 |                 |
| 1                               | PANEL BEATING  | New      | 1,000.00        | 600.00          |
| 2                               | SPRAY PAINTING | New      | 1,000.00        | 700.00          |
| 3                               | ANTI RUST      | New      | 100.00          | 60.00           |
| <b>Gross Labour Cost (\$\$)</b> |                |          | <b>2,100.00</b> | <b>1,360.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >