



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKM 395L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER (WCP)	BENT / CRACKED	800.00	800.00
1	REAR BUMPER RETAINER RH (WCP)	DISTORTED	140.00	140.00
1	REAR BUMPER REINF SUPPORT (WCP)	SERVICEABLE	400.00	-
1	REAR FENDER PANEL RH (WCP)	BENT	2,600.00	2,600.00
1	REAR WHEEL INNER SHIELD COVER RH (WCP)	CRACKED	150.00	150.00
1	SIDE LOWER PANEL RH (WCP)	BENT	480.00	480.00
1	REAR CROSSMEMBER (WCP)	BENT	2,200.00	2,200.00
1	REAR WHEEL KNUCKLE RH (WCP)	BENT	650.00	650.00
1	REAR LOWER ARM RH (WCP)	NO SUCH PARTS	450.00	-
1	REAR WHEEL HUB RH (WCP)	BENT	280.00	280.00
1	REAR STABILIZER ROD (WCP)	* CHECK	90.00	-
1	REAR SHOCK ABSORBER RH (WCP)	BENT	180.00	180.00
1	REAR ABSORBER SPRING COIL RH (WCP)	DISTORTED	450.00	450.00
1	REAR BRAKE CALIPER ASSY RH (WCP)	* CHECK	750.00	-
1	REAR ALLOY RIM RH (WCP)	DENTED	1,300.00	1,300.00
1	TAIL LAMP ASSY RH (WCP)	SERVICEABLE	550.00	-
	COST PLUS 10%		1,147.00	923.00
			12,617.00	10,153.00
1	REAR TIRE RH (SN) (30%)	PUNCTURE	600.00	180.00
	COST PLUS 10%		60.00	-
			660.00	180.00
	<u>SPECIAL NETT ITEMS</u>			
1	REVERSE SENSOR RH (SN)	SERVICEABLE	350.00	-
1	ENGINE ECU RE-SETTING (SN)	* CHECK	450.00	-
			800.00	-
	<u>LABOUR</u>			
	PANEL BEAT, BODY REPAIR & STRAIGHTEN - ACCIDENT AREA.		1,200.00	1,000.00

Report Ref No. CS/AIS22000486/Kqf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPRAY PAINT - REAR BUMPER, REAR FENDER (INNER / OUTER) & LOWER PANEL.		1,200.00	800.00
	REMOVE & REFIT REAR BUMPER COMPONENTS.		150.00	50.00
	ALIGN REAR BRAKE & TEST BRAKING.		150.00	150.00
	ALIGN REVERSE SENSOR & TEST WIRING.		100.00	50.00
	ALIGN TAIL LAMP & TEST WIRING.		80.00	20.00
	RUST PROOFING.	NOT INSURED	80.00	-
			2,960.00	2,070.00
GRAND TOTAL			17,037.00	12,403.00

RECOMMENDED COST OF REPAIRS (EXCLUDE CHECK ITEMS S\$1,374.00 NETT)			12,403.00
LESS EXCESS			-600.00
NETT LIABILITY			11,803.00

Report Ref No. CS/AIS22000486/Kqf3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.