1/24/22, 8:24 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22000495/KVF3N2

24/01/2022 Date:

REFERENCE

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: DMHCSNW00011392101

Insured

Claimant Vehicle No:

SMJ7679P

Vehicle No:

SLZ3255H

Date of Loss:

Colour:

09/01/2022

Nature of Claim: TP

Claim

Chassis No:

Odometer:

SNM22D200230/C02/LEEPG

JTDKB3FU103080017

186071 km

DESCRIPTION & IDENTIFICATION OF VEHICLE

SMJ7679P Reg No:

TOYOTA PRIUS, 1.8 5DR HATCHBACK (A) Make & Model:

2ZR2C09122 Engine No:

Reg. Date: 20/03/2019 (Man. Year: 2018)

Metallic Pearl White

Engine Capacity: 1798 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): **Engine Modification:** Pre-accident Condition: Yes Nο

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15 Front Left Side: Rear Left Side: Davanti 8 mm Davanti 8 mm Front Right Side: Rear Right Side: Davanti 8 mm Davanti 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,063.24	1,250.55	1,812.69	59.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,300.00	990.00	310.00	23.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,363.24	2,240.55	2,122.69	48.65
+ GST 7.00/7.00% (S\$)	305.43	156.84	148.59	48.65
Nett Amount (S\$)	4,668.67	2,397.39	2,271.28	48.65

INSPECTION

Date Inspected:

Date of Assignment: 14/01/2022

ComfortDelGro Engineering Pte Ltd (Braddell)

14/01/2022 Inspected At: 205 Braddell Road

Singapore 579701

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG Manager: **VERON CHEN**

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Different 1 cents -Finalise confirm amount: \$2,145.68

1/24/22, 8:24 AM Adjuster Report

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 24 Jan 2022)

Parts: 144 TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List) **Print Code:** (Unsubmitted, no print-code for SMJ7679P)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR BUMPER	Buckled	556.70 FL	*556.70 FL	
2	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	117.30 FL	*- FL	
3	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	117.30 FL	*- FL	
4	1		*REAR BUMPER REINFORCEMENT	Bent	339.70 FL	*339.70 FL	
5	1		*REAR BUMPER LOWER	Dented/Distorted	586.70 FL	*586.70 FL	
6	2		*REAR BUMPER SENSOR	Serviceable	576.00 FL	*- FL	
7	1		*REAR BUMPER CLIPS (10 Pcs)	Necessary	57.80 FL	*57.80 FL	
8	1		*TAILGATE GARNISH	Repair	925.60 FL	*- FL	
9	1		*TAILGATE EMBLEM HYBRID	Necessary	64.30 FL	*64.30 FL	
10	1		*TAILGATE EMBLEM PRIUS	Necessary	62.20 FL	*62.20 FL	
F=Fra	nchise	part. L=ListIte	mDisc.		0.400.00	4 007 40	
				Sub Total (S\$)	3,403.60	1,667.40	
	- List Item Discount on L Items 10.00/25.00% (S\$)					416.85	
				Total Parts (S\$)	3,063.24	1,250.55	
	Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount	
Lab	our Items				
1	TO KNOCK,STRAIGHTEN AND RENEW ACCIDENT AREA SUCH AS REAR BUMPER,TAILGATE,REAR END PANEL AND ETC	New	500.00	240.00	
2	TO PUTTY AND RESPRAY ACCIDENT AREA SUCH AS TAILGATE, TAILGATE GARNISH, REAR BUMPER, REAR END PANEL AND ETC	New	800.00	750.00	
	Gross Labou	r Cost (S\$)	1,300.00	990.00	
Report was unsubmitted during this print-out.					

< END OF ESTIMATES >