

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22000502/EGA3Q2**Date:** 31/05/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800018601
Claimant Vehicle No :	SJP6594K	Insured Vehicle No :	SKS7001X
Date of Loss:	12/01/2022	Nature of Claim:	TP
		Claim No:	3636304910SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJP6594K	Engine No:	MR20658876A
Make & Model:	NISSAN TEANA, 2.0 CVT (A)	Chassis No:	JN1BDUJ32Z0000347
Reg. Date:	31/03/2009 (Man. Year: 2008)	Odometer:	184607 km
Colour:	Silver		
Engine Capacity:	2496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 4 mm	Rear Left Side:	Dunlop 4 mm
Front Right Side:	Dunlop 4 mm	Rear Right Side:	Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,256.60	1,838.00	1,418.60	43.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,660.00	1,060.00	600.00	36.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,916.60	2,898.00	2,018.60	41.06
Approved Total (Overridden) (S\$)		2,300.00		
(S\$)	4,916.60	2,300.00	2,616.60	53.22
+ GST 7.00/7.00% (S\$)	344.16	161.00	183.16	53.22
Nett Amount (S\$)	5,260.76	2,461.00	2,799.76	53.22
+ Loss of Use (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,863.00		

INSPECTION

Date of Assignment:	19/01/2022	
Date Inspected:	19/01/2022 Inspected At:	Woon Meng Motor Pte Ltd (Bukit Batok) 50 Bukit Batok Street 23,, #01-06 Midview Building Singapore 659578
Estimated Period of Repair:	3.0 days	

Adjuster: CHEN TSUE YEE**Manager:** Chong Pui Lin*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Broken	935.00 FL	*935.00 FL
2	1		*REAR BUMPER RETAINER O/S	Broken	40.00 FL	*40.00 FL
3	1		*REAR BUMPER OUTER MOULDING O/S	Cut	474.00 FL	*200.00 FL
4	1		*REAR LAMP O/S	Broken	645.00 FL	*645.00 FL
5	1		*REAR MUDGUARD O/S	Repair	1,280.00 FL	*- FL
6	1		*SET REAR SENSOR	Torn	220.00 FS	*200.00 FS
					Sub Total (S\$)	3,594.00 2,020.00
					- List Item Discount on L Items 10.00/10.00% (S\$)	337.40 182.00
					Total Parts (S\$)	3,256.60 1,838.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REPLACE ,REPAIR & WELD REAR DAMAGED PARTS	New	800.00	400.00
2	TO R&R SENSOR WIRING	New	100.00	30.00
3	TO R&R LIGHT WIRING	New	60.00	30.00
4	TO PUTTY & SPRAY PAINTING	New	700.00	600.00
Gross Labour Cost (\$\$)			1,660.00	1,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >