

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22000506/AGS3Q2**Date:** 01/07/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070168750
Claimant Vehicle No :	SMQ4944G	Insured Vehicle No :	SMW6738R
Date of Loss:	11/01/2022	Nature of Claim:	TP
		Claim No:	4733671476SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMQ4944G	Engine No:	L15B4172135
Make & Model:	HONDA GRACE, 1.5 (A)	Chassis No:	GM61101680
Reg. Date:	20/11/2019 (Man. Year: 2019)	Odometer:	71277 km
Colour:	Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Crucero 6 mm	Rear Left Side:	Crucero 6 mm
Front Right Side:	Crucero 6 mm	Rear Right Side:	Crucero 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,478.56	5,458.88	5,019.68	47.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,510.00	2,170.00	2,340.00	51.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,988.56	7,628.88	7,359.68	49.10
Approved Total (Overridden) (S\$)		6,100.00		
(S\$)	14,988.56	6,100.00	8,888.56	59.30
+ GST 7.00/7.00% (S\$)	1,049.20	427.00	622.20	59.30
Nett Amount (S\$)	16,037.76	6,527.00	9,510.76	59.30
+ Loss of Use (8.0 x S\$50.00/day) (S\$)		400.00		
(S\$)		6,927.00		
Liabe Amount (90.00%) (S\$)		6,234.30		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		6,241.75		
Global Sum Settlement (S\$)		6,200.00		

INSPECTION

Date of Assignment: 12/01/2022

Date Inspected: 12/01/2022 Inspected At:

MG Solution Pte Ltd (HQ)

23 KAKI BUKIT AVE 4

#04-01

VICOM INSPECTION CENTRE,
SINGAPORE 415933

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Repair	955.60 FL	*- FL
2	1		*FRONT BUMPER	Deformed	680.00 FL	*460.00 FL
3	1		*FRONT BUMPER SIDE RETAINER	N/S Damaged	131.80 FL	*28.00 FL
4	1		*HEADLAMP LH	Cut	1,533.90 FL	*1,320.00 FL
5	1		*FRONT FENDER	Dented	480.00 FL	*480.00 FL
6	1		*FRONT FENDER INNER COWLING	Deformed	160.00 FL	*160.00 FL
7	1		*FRONT SHOCK ABSORBER	Bent	480.00 FL	*480.00 FL
8	1		*FRONT LOWER ARM	Bent	280.20 FL	*280.20 FL
9	1		*FRONT KNUCKLE ARM	Damaged	255.60 FL	*255.60 FL
10	1		*FRONT KNUCKLE ARM BEARING	Damaged	180.20 FL	*180.20 FL
11	1		*FRONT DOOR LH	Distorted	1,355.20 FL	*898.00 FL
12	2		*FRONT DOOR HINGE	Bent	160.40 FL	*160.40 FL
13	1		*FRONT DOOR CHECKER	Damaged	130.00 FL	*130.00 FL
14	1		*FRONT DOOR LOCK	Damaged	320.00 FL	*320.00 FL
15	1		*DFRONT DOOR OUTER HANDLE	Cut	130.50 FL	*130.50 FL
16	1		*FRONT DOOR OUTER HANDLE (END)	Not Necessary	80.00 FL	*- FL
17	1		*FRONT DOOR INNER BOARD	Cracked	450.60 FL	*450.60 FL
18	1		*FRONT DOOR OUTER CHANNEL	Bent	144.60 FL	*144.60 FL
19	1		*FRONT DOOR WEATHERSTRIPE	Not Necessary	280.50 FL	*- FL
20	1		*FRONT DOOR POWER WINDOW MOTOR	Not Necessary	325.20 FL	*- FL
21	1		*FRONT DOOR POWER WINDOW REGULATOR	Damaged	280.50 FL	*280.50 FL
22	1		*FRONT DOOR STICKER	Necessary	90.00 FL	*90.00 FL
23	1		*REAR DOOR LH	Repair	1,255.60 FL	*- FL
24	1		*ROCKER PANEL	Not Necessary	820.30 FL	*- FL
25	1		*SET FRONT BUMPER CLIP	Necessary	20.00 FS	*20.00 FS
26	1		*SET FRONT FENDER INNER COWLING CLIPS	Necessary	20.00 FS	*20.00 FS
27	1		*SET FRONT DOOR INNER BOARD CLIPS	Necessary	20.00 FS	*20.00 FS
28	1		*WHEEL TYRE LH	Not Necessary	450.00 FS	*- FS
29	1		*WHEEL RIM LH	Cut	1,200.00 FS	*400.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	12,670.70	6,708.60
- List Item Discount on L Items 20.00/20.00% (\$)	2,192.14	1,249.72
Total Parts (\$)	10,478.56	5,458.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING REMOVAL AND REPLACING PARTS	New	1,800.00	700.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,600.00	1,000.00
3	TUFF COAT	New	250.00	60.00
4	WIRING CHECK	New	180.00	30.00
5	TO REMOVE AND REFIX FRONT & REAR DOOR MECHANISM	New	240.00	80.00
6	REMOVE AND REFIX FRONT UNDERCARRIAGE	New	320.00	220.00
7	FOUR WHEEL ALIGNMENT	New	120.00	80.00
Gross Labour Cost (\$\$)			4,510.00	2,170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >