

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22000514/AQY3N2**Date:** 17/03/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00033632106	
Claimant Vehicle No :	GBK3771G	Insured Vehicle No :	GBC9678X	
Date of Loss:	12/01/2022	Nature of Claim:	TP	Claim No: SNM22D200335/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBK3771G		Engine No:	1KDB022569
Make & Model:	TOYOTA HIACE, 3.0 D TURBO 4DR (A)		Chassis No:	JTFHT02P000250124
Reg. Date:	18/06/2020 (Man. Year: 2019)		Odometer:	53746 km
Colour:	Silver			
Engine Capacity:	2982 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	36,382.40	21,303.62	15,078.78	41.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,130.00	6,530.00	2,600.00	28.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	45,512.40	27,833.62	17,678.78	38.84
Approved Total (Overridden) (\$\$)		22,200.00		
Nett Amount (\$\$)	45,512.40	22,200.00	23,312.40	51.22

INSPECTION

Date of Assignment:	26/01/2022	Automobile Hub Enterprise 1 KAKI BUKIT AVENUE 5, #2 -11 AUTOBAY @ KAKI BUKIT Singapore 417883
Date Inspected:	14/01/2022 Inspected At:	
Estimated Period of Repair:	21.0 days	

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 17 Mar 2022)	
Parts:	N/A	TOYOTA HIACE 3.0 D TURBO 4DR (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBK3771G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	580.60 F	*580.60 FL
2	2		*FRONT BUMPER SIDE HOLDER	Not Necessary	130.00 F	*- FL
3	1		*FRONT BUMPER LOWER GRILLE	Deformed	166.20 F	*166.20 FL
4	1		*FRONT BUMPER TOW COVER	Not Necessary	20.80 F	*- FL
5	2		*FRONT BUMPER SIDE GRILLE	Deformed	133.00 F	*133.00 FL
6	1		*FRONT BUMPER REINFORCEMENT	Bent	355.80 F	*355.80 FL
7	2		*FRONT BUMPER REINFORCEMENT BRACKET	Bent	310.00 F	*310.00 FL
8	1		*FRONT BUMPER BEAM	Bent	215.40 F	*215.40 FL
9	2		*FRONT BUMPER BRACKET	Bent	251.20 F	*251.20 FL
10	1		*FRONT GRILLE BASE	Cracked	457.20 F	*457.20 FL
11	1		*FRONT GRILLE UPPER GARNISH	Cracked	281.50 F	*281.50 FL
12	1		*FRONT GRILLE LOWER GARNISH	Cracked	330.80 F	*330.80 FL
13	2		*HEADLAMP	Cracked	1,507.40 F	*1,507.40 FL
14	1		*BONNET	Distorted	872.90 F	*872.90 FL
15	1		*BONNET LOCK	Damaged	88.90 F	*88.90 FL
16	2		*BONNET HINGE	Not Necessary	112.00 F	*- FL
17	1		*BONNET LOGO	Necessary	75.00 F	*75.00 FL
18	1		*FRONT SUPPORT PANEL	Buckled	464.20 F	*464.20 FL
19	1		*FRONT SUPPORT PANEL GARNISH	Deformed	187.40 F	*187.40 FL
20	1		*FRONT CORNER PANEL	O/s Buckled	753.00 F	*376.50 FL
21	1		*INTERCOOLER	Dented	1,289.00 F	*1,289.00 FL
22	1		*INTERCOOLER AIR GUIDE	Deformed	139.40 F	*139.40 FL
23	1		*AIR CON CONDENSER	Bent	1,216.10 F	*1,216.10 FL
24	1		*AIR CON LIQUID PIPE	Bent	205.60 F	*205.60 FL
25	1		*RADIATOR	Dented	1,495.00 F	*1,495.00 FL
26	1		*RADIATOR SPARE TANK	Cracked	140.90 F	*140.90 FL
27	1		*WIPER WASHER TANK	Deformed	188.30 F	*188.30 FL
28	1		*FAN COWLING	Cracked	295.00 F	*295.00 FL
29	2		*REAR NUMBER PLATE LAMP	Not Necessary	135.60 F	*- FL
30	1		*REAR BUMPER	Distorted	695.90 F	*695.90 FL
31	2		*REAR BUMPER SIDE HOLDER	Damaged	120.40 F	*120.40 FL
32	4		*REAR BUMPER LOWER BRACKET	Bent	120.00 F	*120.00 FL
33	1		*REAR END PANEL OUTER	Distorted	388.30 F	*388.30 FL
34	1		*REAR END PANEL INNER	Distorted	859.50 F	*859.50 FL
35	1		*REAR END PANEL TOP METAL STRIP	Bent	180.70 F	*180.70 FL
36	2		*TAILLAMP	Cracked	791.60 F	*791.60 FL
37	1		*TAILLAMP PANEL	O/s Dented	923.80 F	*461.90 FL
38	1		*TAILLAMP PANEL INNER	O/s Dented	782.80 F	*391.40 FL
39	2		*TAILLAMP LOWER APRON	Deformed	177.20 F	*177.20 FL
40	1		*TAILGATE	Distorted	1,890.50 F	*1,890.50 FL
41	1		*TAILGATE LOCK	Jammed	235.40 F	*235.40 FL
42	1		*TAILGATE LOCK STRIKER	Bent	68.60 F	*68.60 FL
43	1		*TAILGATE LOCK ACTUATOR	Damaged	290.90 F	*290.90 FL
44	1		*TAILGATE WEATHERSTRIPE	Cut	395.90 F	*395.90 FL
45	1		*TAILGATE OUTER MOULDING	Deformed	364.70 F	*364.70 FL
46	1		*TAILGATE OUTER HANDLE	Damaged	85.40 F	*85.40 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*TAILGATE INNER TRIM BOARD	Torn	186.70 F	*186.70 FL
48	2		*TAILGATE HINGE	Bent	179.00 F	*179.00 FL
49	2		*TAILGATE DAMPER	Damaged	575.80 F	*575.80 FL
50	1		*TAILGATE WIPER ARM	Not Necessary	98.20 F	*- FL
51	1		*TAILGATE WIPER MOTOR	Damaged	432.10 F	*432.10 FL
52	1		*TAILGATE GLASS	Shattered	1,115.20 F	*1,115.20 FL
53	1		*TAILGATE GLASS MOULDING	Necessary	172.50 F	*172.50 FL
54	1		*TAILGATE WIPER MOTOR COVER	Deformed	249.60 F	*249.60 FL
55	1		*TOYOTA LOGO	Necessary	65.90 F	*65.90 FL
56	1		*REAR RH BODY PANEL	Buckled	2,219.40 F	*2,219.40 FL
57	1		*REAR RH BODY INNER PANEL	Repair	1,069.10 F	*- FL
58	1		*REAR BODY PANEL INNER TRIM BOARD	O/s Torn	290.60 F	*145.30 FL
59	1		*REAR RH WHEEL HOUSING PANEL	Repair	1,114.70 F	*- FL
60	1		*FLOOR PANEL	Repair	1,850.90 F	*- FL
61	1		*SPARE TYRE CARRIER	Bent	384.60 F	*384.60 FL
62	1		*SPARE TYRE CARRIER LOCK SCREW	Bent	58.20 F	*58.20 FL
63	1		*REAR EXHAUST PIPE	Bent	591.40 F	*591.40 FL
64	1		*REAR EXHAUST PIPE MOUNTING	Not Necessary	35.40 F	*- FL
65	1		*REAR EXHAUST PIPE GASKET	Necessary	34.20 F	*34.20 FL
66	1		*CENTRE EXHAUST PIPE	Repair	1,829.10 F	*- FL
67	1		*FRONT NUMBER PLATE	Bent	30.00 FS	*30.00 FS
68	1		*FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
69	1		*FRONT GRILLE CLIPS	Necessary	20.00 FS	*20.00 FS
70	1		*FRONT SUPPORT PANEL GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
71	1		*RADIATOR COOLANT	Necessary	40.00 FS	*40.00 FS
72	1		*REAR NUMBER PLATE	Bent	30.00 FS	*30.00 FS
73	1		*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
74	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
75	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
76	1		*TAILGATE INNER TRIM BOARD CLIPS	Necessary	30.00 FS	*30.00 FS
77	1		*TAILGATE GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
78	1		*REAR CAMERA	Damaged	480.00 FS	*380.00 FS
79	1		*REAR BODY PANEL INNER TRIM BOARD CLIPS	Necessary	60.00 FS	*30.00 FS
80	1		*REAR RH WHEEL HOUSING CARPENTRY FURNITURE	Damaged	450.00 FS	*350.00 FS
81	1		*FLOOR PANEL TOP BOARD	Torn	580.00 FS	*480.00 FS
82	1		*FLOOR PANEL CARPET	Torn	680.00 FS	*350.00 FS
83	1		*SPARE TYRE	Not Necessary	180.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **36,382.40** **27,691.50**
- List Item Discount on L Items 0.00/25.00% (\$\$) **0.00** **6,387.88**

Total Parts (\$\$) **36,382.40** **21,303.62**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING (FRONT)	New	1,200.00	800.00
2	SPRAY PAINTING (FRONT)	New	1,200.00	1,000.00
3	WIRING (FRONT)	New	50.00	30.00
4	TO SPRAY TUFF COAT (FRONT)	New	150.00	60.00
5	TO REMOVE CONDENSER TO TOP UP AIR CON GAS	New	120.00	60.00
6	TO REMOVE RADIATOR AND TO TOP UP COOLANT	New	120.00	60.00
7	PANEL BEATING (REAR)	New	2,500.00	2,000.00
8	SPRAY PAINTING (REAR)	New	2,200.00	1,600.00
9	WIRING (REAR)	New	100.00	30.00
10	TO SPRAY TUFF COAT (REAR)	New	300.00	200.00
11	TO REAR UPHOLSTERY AND CARPENTRY FURNITURE	New	300.00	250.00
12	TO REMOVE REVERSE SENSOR	New	100.00	50.00
13	TO REMOVE REAR CAMERA	New	100.00	50.00
14	TO REMOVE EXHAUST PIPE (REAR AND CENTRE)	New	300.00	80.00
15	TO TRANSFER TAILGATE FITTINGS	New	150.00	80.00
16	TO REPLACE TAILGATE GLASS	New	180.00	120.00
17	TOWING FEES	New	60.00	60.00
Gross Labour Cost (\$\$)			9,130.00	6,530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >