



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile CS3/ASM21011562/Tvy3-1

AXA INSURANCE PTE LTD
8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811

Ref: ~~000/ASM21011562/Tvy3~~
Date: ~~12/11/2021~~ 10/01/2022
Code: ASM

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SLC 9082X	Veh. Inspected	SMQ 8898E
Policy No.		Coverage (\$)	0.00
Claim No.	S1M03LP2	Excess (\$)	0.00
Assign From	CHAN KIAN CHUAN	Assign Date	12/11/2021 10/01/2022

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	06/11/2021	Inspection Date	12/11/2021
Survey held at	MAX MOTORS 1 KAKI BUKIT AVE 6 #01-98 SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

Tvy3-1

ASS. REC. BY:

Tang JH

REF:

23/ASM21011562/Tvy3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / PD / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____


Insured: **SLC 9082X**Policy No. **GA357052**Claims No. **S1M03LP2**

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: **\$86K.**

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS **WP - PRS**

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: **SMQ8898E**Yr Regn: **2015, May**

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **Mercedes Benz E250**

c.c

1991Colour **Black**

A/C: Insured / Std / NI / NA

Sp. Reading **104755**

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: **WDP21203625-141529**

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: **245/40R18**

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. **6** mmR/Bal. **6** mmL/Bal. **6** mmL/Bal. **6** mmD.O.A. **6/11/21**D.O.I. **12/4/21**Survey held at **Maxim for**Des. of Damages: Frt / **Rear** / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Repair Range: **\$8000 - \$10,000****10 days**

15/11/21 Submit PRS, repair range \$7,000-\$8,000

18/2/22 Submit LS \$12,500 (red 4850, 27%)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) **18/2/22-typist**

Rep. Format: _____

Lump Sum / L.S. (\$) _____

Days Of Repair: **10**

Resurvey No. of Trip: _____

Add Fee: ☐

Site Insp (\$ _____)

☐

Interview (\$ _____)

☐

Tech. Invs (\$ _____)

☐

Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS \$ _____

Photos _____

Others _____

TOTAL

WG APPRAISAL SERVICES

Blk 224B, Compassvale Walk, #07-647, Singapore 542224
Email: winsongkk@hotmail.com Contact: 9747 0063
Company Register No. 53326249J

ACCIDENT DAMAGED VEHICLE INSPECTION REPORT

M/S : YUAN LONG GEN
C/O MAX MOTORS
1 Kakit Bukit Ave 6, #01-98
Autobay @ Kakit Bukit .Singapore 417883.

Date : 01 December 2021
Our Ref : WG/TP/2021-213

REFERENCE PARTICULARS

Date of Accident : 06 November 2021
Date of Inspection : 08 November 2021

Type of Inspection : Third Party Claim
Date of Re-Inspn : 15 November 2021

VEHICLE PARTICULARS

Registration No : SMQ8898E
Make : MERCEDES BENZ
Model : E 250 SEDAN (R17)
Year : 2014

Engine No : 27492030367356
Chassis No : WDD2120362B141529
Odometer : 104755km
Colour : Black

CONDITION OF VEHICLE (STATIC CHECKS AT TIME OF INSPECTION ONLY)

Engine condition : Good
Foot Brake : Serviceable
Hand Brake : Serviceable

General Body Work : Good
Steering : Serviceable
Lightings : Serviceable

TYRE CONDITION (Remaining estimated life of tyre in mm)

	<u>Make</u>	<u>Size</u>
Front Near side	: Bridgestone	255/55R17
Front Off Side	: Bridgestone	255/55R17
Rear Near Side	: Bridgestone	255/55R17
Rear off Side	: Bridgestone	255/55R17

<u>Thread Balance</u>
5 mm
5 mm
5 mm
5 mm

GENERAL DESCRIPTION OF DAMAGES

The vehicle sustained damage at the rear portions..
For details, refer to assessment for repairs and photographs attached.

ASSESSMENT SUMMARY

Our assessment of the repair costs to pre-accident condition was **S\$17,350.00** nett at lump sum basis.(Subject to GST if applicable)

Under normal circumstances, estimated period required for repairs : Twelve (12) working days.

Enclosed One hundred and thirty -one (131) photographs depicting damage to the vehicle.

Inspection conducted at : MAX MOTORS
1 Kakit Bukit Ave 6, #01-98 . Autobay @ Kakit Bukit .Singapore 417883.

In accordance to your instruction, we have **not authorise** repairs and inspection was conducted strictly on a "**WITHOUT PREJUDICE BASIS**".

VEHICLE NO : SMQ8898E
MODEL : E 250 SEDAN (R17)

Our Ref : WG/TP/2021-213

ASSESSMENT OF REPAIRS AND SPARE PARTS COSTS

DESCRIPTION OF PARTS AND NATURE OF REPAIRS

A)	SPARE PARTS	QTY PC/SET	ASSESSED CONDITION		ORIGINAL QUOTATION	REVISED QUOTATION	
01	REAR BUMPER	1	DEFORMED/CRACKED	\$	1,630.00	\$	1,630.00
02	REAR BUMPER TOP GUIDE	1	CRACKED	\$	155.00	\$	155.00
03	REAR BUMPER SIDE RETAINER LH	1	NECESSARY	\$	59.00	\$	59.00
04	REAR BUMPER SIDE RETAINER RH	1	NECESSARY	\$	59.00	\$	59.00
05	REAR BUMPER LOWER GARNISH	1	CRACKED	\$	313.00	\$	313.00
06	REAR BUMPER LOWER BRACKET	1	NECESSARY	\$	47.00	\$	47.00
07	REAR BUMPER INNER GUIDE	1	CRACKED	\$	230.00	\$	230.00
08	REAR BUMPER CHROME MOULDING LH	1	NECESSARY	\$	135.00	\$	135.00
09	REAR BUMPER CHROME MOULDING RH	1	NECESSARY	\$	135.00	\$	135.00
10	REAR BUMPER CENTRE CHROME MOULDING	1	NECESSARY	\$	198.00	\$	198.00
11	REAR BUMPER PDC SENSOR @180	4	MALFUNCTION	\$	1,080.00	\$	1,080.00 720
12	REAR BUMPER SENSOR HOLDER	6	NECESSARY	\$	180.00	\$	180.00
13	REAR BUMPER SENSOR WIRE HARNESS	1	MALFUNCTION	\$	305.00	\$	305.00
14	REAR BUMPWR TOW COVER	1	DEFORMED/CRACKED	\$	82.00	\$	82.00
15	REAR BUMPER REINFORCEMENT	1	DENTED	\$	810.00	\$	810.00 545.22
16	REAR EXHAUST SILENCER	1	REPAIR	\$	1,660.00	\$	- XR
17	REAR EXHAUST MOUNTING	2	NOT NECESSARY	\$	40.00	\$	XNN -
18	BOOTLID	1	DENTED	\$	2,190.00	\$	2,190.00 2110
19	BOOTLID EMBLEM LOGO	1	NECESSARY	\$	68.00	\$	68.00
20	BOOTLID EMBLEM - E250	1	NECESSARY	\$	78.00	\$	78.00
21	BOOTLID EMBLEM - 7G-TRONIC	1	NECESSARY	\$	80.00	\$	80.00
22	BOOTLID EMBLEM - C&C	1	NECESSARY	\$	85.00	\$	85.00
23	BOOTLID LOCK	1	JAMMED	\$	359.00	\$	359.00 254
24	BOOTLID LAMP LH	1	CRACKED	\$	545.00	\$	390 545.00
25	BOOTLID LAMP RH	1	CRACKED	\$	545.00	\$	545.00 390
26	BOOTLID WEATHERSTRIP	1	DEFORMED	\$	258.00	\$	232 258.00
27	TAILLAMP LH	1	CRACKED	\$	645.00	\$	645.00
28	TAILLAMP RH	1	CRACKED	\$	645.00	\$	645.00
29	END PANEL	1	DENTED	\$	1,330.00	\$	1,330.00 1215
30	END PANEL TOP GARNISH	1	CRACKED	\$	215.00	\$	215.00
31	FLOOR PANEL COMPARTMENT	1	DENTED	\$	1,440.00	\$	1,440.00 XR
32	REAR COMPARTMENT TOP BOARD	1	NOT NECESSARY	\$	345.00	\$	XNN -
33	REAR COMPARTMENT LOWER TRAY	1	CRACKED	\$	355.00	\$	355.00
34	REAR COMPARTMENT UNDER COVER LH	1	CRACKED	\$	45.00	\$	45.00
35	REAR COMPARTMENT UNDER COVER RH	1	CRACKED	\$	45.00	\$	45.00
36	REAR FENDER INNER TRIM LH	1	NOT NECESSARY	\$	331.00	\$	XNN -
37	REAR FENDER INNER TRIM RH	1	DEFORMED	\$	331.00	\$	331.00
38	REAR SPARE WHEEL CLAMP	1	CRACKED	\$	45.00	\$	45.00
39	REAR EXHAUST TIP	1	GRAZED	\$	65.00	\$	65.00
40	DRIVER HEADREST	1	DEPLOY	\$	1,211.00	\$	XR 1,211.00 local repair SN\$100
41	PASSENGER HEADREST	1	DEPLOY	\$	1,211.00	\$	XR 1,211.00 local repair SN\$100
42	DRIVER SEAT BELT	1	JAMMED	\$	341.00	\$	341.00
43	PASSENGER SEAT BELT	1	JAMMED	\$	341.00	\$	341.00
				\$	20,267.00	\$	17,891.00
				Less 10%	\$	\$	2,026.70
					\$	\$	18,240.30
						\$	16,101.90
							13078.22 SN\$200
							11770.40
B)	S/NETT ITEM						
44	REAR NUMBER PLATE	1	BENT	\$	90.00	\$	80.00 45
45	REAR BUMPER CLIP	1 SET	NECESSARY	\$	40.00	\$	30.00
46	REAR FENDER INNER TRIM CLIP	1 SET	NECESSARY	\$	30.00	\$	20.00
47	JOINT SEALANT	1	NECESSARY	\$	120.00	\$	100.00
				\$	280.00	\$	230.00
							195
				Parts Total :	\$	\$	18,520.30
					\$	\$	16,331.90

C) LABOUR CHARGES & MISC			
48	CHECK REAR WIRING AND LIGHTNING SYSTEM	\$ 100.00	\$ 90.00 60
49	REMOVE, REFIT REAR LINING, TRIM AND GARNISH	\$ 300.00	\$ 100 250.00
50	REMOVE AND RENEW REAR REVERSE SENSOR	\$ 150.00	\$ 120.00 40
51	REMOVE AND REFIT FUEL TANK	\$ 150.00	\$ 120.00 XNN
52	DIAGNOIS CHECK AND CLEAR FAULT CODE	\$ 500.00	\$ 280 400.00
53	REMOVE, RENEW BOTH HEADREST AND SEAT BELT	\$ 200.00	\$ 180.00
54	REMOVE AND RENEW REAR EXHAUST	\$ 150.00	\$ 100 130.00
55	TRANSFER PARTS, ATTACHMENT FROM OLD BOOTLID TO NEW	\$ 200.00	\$ 180.00 60
56	PANEL BEATING ON AFFECTED AREAS AND RENEW DAMAGE PARTS	\$ 2,000.00	\$ 1400 1,800.00
57	SPRAY PAINTING ON AFFECTED AREAS	\$ 2,000.00	\$ 1,900.00 1500
58	APPLY ANTI RUST ON AFFECTED AREAS	\$ 200.00	\$ 50 180.00
Labour Total :		\$ 5,950.00	\$ 5,350.00

3770

Total Parts and Laboure :	\$ 24,470.30	\$ 21,681.90
----------------------------------	---------------------	---------------------

FINAL LUMP SUM ADJUSTMENT

\$ 17,350.00

15935.40

L/\$12,700

10 DAYS

POINT OF IMPACT

The impact was confined to the rear portion of the vehicle.

The damages appeared to be consistent as per the accident report statement.

Please refer the attached schedule and photographs for details.

ADJUSTMENT/RECOMMENDATIONS

We have thoroughly inspected each and every item on the repairer's estimates against the actual damaged found on the vehicle. We have listed the breakdown of our findings and recommendations as per assessment above.

CONCLUSION

The repairer has agreed to undertake repair the vehicle at a lump sum basis of **\$S17,350.00 nett** corresponding to replacement of parts, spray painting and labour charges. We now revert for your decision on the above claim.

Yours faithfully
WG APPRAISAL SERVICES



Winson Goh
Automotive Appraiser

SMQ 8898E

1630.00	254.00	100.00	60.00	11491.40
155.00	390.00	100.00	100.00	395.00
59.00	390.00	45.00	40.00	3770.00
59.00	232.00	30.00	280.00	15656.40
313.00	645.00	20.00	180.00	0.80
47.00	645.00	100.00	100.00	12525.12
230.00	1215.00	395.00	60.00	
135.00	215.00		1400.00	
135.00	0.00		0.00	
198.00	355.00		1500.00	
720.00	45.00		50.00	
180.00	45.00		3770.00	
305.00	331.00			
82.00	45.00			
545.22	65.00			
2110.00	341.00			
68.00	341.00			
78.00	5554.00			
80.00				
85.00				
7214.22	7214.22			
	5554.00			
	12768.22			
	0.9			
	11491.40			



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: S1M03LP2

Date: 28th Feb 2022

Our Ref: CS3/ASM21011562/Tvy3e2-1

M/s Axa Insurance Pte Ltd

8 Shenton Way #24-01

Axa Tower

Singapore 068811

(The Motor Claims Department)

Attn: Chan Kian Chuan

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SMQ 8898E

INSURED VEHICLE: SLC 9082X

ACCIDENT DATE: 06/11/2021

We thank you for your instruction on 10/01/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SMQ 8898E from M/s WG Appraisal Services.
- b) Singapore Accident Statement of Vehicles SMQ 8898E and SLC 9082X.
- c) Police Report of Vehicles SLC 9082X.
- d) Final Repair Bill of SMQ 8898E from M/s Max Motors.
- e) Colour damaged vehicle photographs of SMQ 8898E.

Pre-Repair Inspection Date : 12/11/2021 at M/s Max Motors, 1 Kaki Bukit Ave 6 #01-98, Singapore 417883.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SMQ 8898E
Make & Model	: B.M.W. 730I LED SR NAV HUD
Year of Registration	: 2016
Chassis Number	: WBA7A02070GL97008
Engine Capacity	: 1998 cc

2. We recommend that the repairs of the entire damage require about 10 (Ten) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMQ 8898E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEFORMED / CRACKED	1,630.00	1,630.00
1	REAR BUMPER TOP GUIDE	CRACKED	155.00	155.00
1	REAR BUMPER SIDE RETAINER LH	NECESSARY	59.00	59.00
1	REAR BUMPER SIDE RETAINER RH	NECESSARY	59.00	59.00
1	REAR BUMPER LOWER GARNISH	CRACKED	313.00	313.00
1	REAR BUMPER LOWER BRACKET	NECESSARY	47.00	47.00
1	REAR BUMPER INNER GUIDE	CRACKED	230.00	230.00
1	REAR BUMPER CHROME MOULDING LH	NECESSARY	135.00	135.00
1	REAR BUMPER CHROME MOULDING RH	NECESSARY	135.00	135.00
1	REAR BUMPER CENTRE CHROME MOULDING	NECESSARY	198.00	198.00
6	REAR BUMPER PDC SENSOR	MALFUNCTION (4PCS ONLY)	1,080.00	720.00
6	REAR BUMPER SENSOR HOLDER	NECESSARY	180.00	180.00
1	REAR BUMPER SENSOR WIRE HARNESS	MALFUNCTION	305.00	305.00
1	REAR BUMPER TOW COVER	DEFORMED / CRACKED	82.00	82.00
1	REAR BUMPER REINFORCEMENT	DENTED	810.00	545.22
1	REAR EXHAUST SILENCER	TO REPAIR SEE LABOUR	1,660.00	-
2	REAR EXHAUST MOUNTING	NOT NECESSARY	40.00	-
1	BOOTLID	DENTED	2,190.00	2,110.00
1	BOOTLID EMBLEM LOGO	NECESSARY	68.00	68.00
1	BOOTLID EMBLEM - E250	NECESSARY	78.00	78.00
1	BOOTLID EMBLEM - 7G-TRONIC	NECESSARY	80.00	80.00
1	BOOTLID EMBLEM - C&C	NECESSARY	85.00	85.00
1	BOOTLID LOCK	JAMMED	359.00	254.00
1	BOOTLID LAMP LH	CRACKED	545.00	390.00
1	BOOTLID LAMP RH	CRACKED	545.00	390.00
1	BOOTLID WEATHERSTRIP	DEFORMED	258.00	232.00
1	TAILLAMP LH	CRACKED	645.00	645.00
1	TAILLAMP RH	CRACKED	645.00	645.00

Report Ref No. CS3/ASM21011562/Tvy3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	END PANEL	DENTED	1,330.00	1,215.00
1	END PANEL TOP GARNISH	CRACKED	215.00	215.00
1	FLOOR PANEL COMPARTMENT	TO REPAIR SEE LABOUR	1,440.00	-
1	REAR COMPARTMENT TOP BOARD	NOT NECESSARY	345.00	-
1	REAR COMPARTMENT LOWER TRAY	CRACKED	355.00	355.00
1	REAR COMPARTMENT UNDER COVER LH	CRACKED	45.00	45.00
1	REAR COMPARTMENT UNDER COVER RH	CRACKED	45.00	45.00
1	REAR FENDER INNER TRIM LH	NOT NECESSARY	331.00	-
1	REAR FENDER INNER TRIM RH	DEFORMED	331.00	331.00
1	REAR SPARE WHEEL CLAMP	CRACKED	45.00	45.00
1	REAR EXHAUST TIP	GRAZED	65.00	65.00
1	DRIVER SEAT BELT	JAMMED	341.00	341.00
1	PASSENGER SEAT BELT	JAMMED	341.00	341.00
	LESS 10% DISCOUNT		-1,784.50	-1,276.82
			16,060.50	11,491.40
1	DRIVER HEADREST (LOCAL REPAIR) (SN)	DEPLOY	1,211.00	100.00
1	PASSENGER HEADREST (LOCAL REPAIR) (SN)	DEPLOY	1,211.00	100.00
	LESS 10% DISCOUNT		-242.20	-
			2,179.80	200.00
	<u>SPECIAL NETT ITEMS</u>			
1	REAR NUMBER PLATE (SN)	BENT	90.00	45.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	40.00	30.00
1	SET REAR FENDER INNER TRIM CLIP (SN)	NECESSARY	30.00	20.00
1	JOINT SEALANT (SN)	NECESSARY	120.00	100.00
			280.00	195.00
	<u>LABOUR</u>			
	CHECK REAR WIRING AND LIGHTNING SYSTEM.		100.00	60.00
	REMOVE, REFIT REAR LINING, TRIM AND GARNISH.		300.00	100.00
	REMOVE AND RENEW REAR REVERSE SENSOR.		150.00	40.00
	REMOVE AND REFIT FUEL TANK.	NOT NECESSARY	150.00	-

Report Ref No. CS3/ASM21011562/Tvy3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	DIAGNOIS CHECK AND CLEAR FAULT CODE.		500.00	280.00
	REMOVE, RENEW BOTH HEADREST AND SEAT BELT.		200.00	180.00
	REMOVE AND RENEW REAR EXHAUST.		150.00	100.00
	TRANSFER PARTS, ATTACHMENT FROM OLD BOOTLID TO NEW.		200.00	60.00
	PANEL BEATING ON AFFECTED AREAS AND RENEW DAMAGE PARTS. INCLUSIVE OF THE REPAIR OF REAR EXHAUST SILENCER AND FLOOR PANEL COMPARTMENT.		2,000.00	1,400.00
	SPRAY PAINTING ON AFFECTED AREAS.		2,000.00	1,500.00
	APPLY ANTI RUST ON AFFECTED AREAS.		200.00	50.00
			5,950.00	3,770.00
GRAND TOTAL			24,470.30	15,656.40
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				12,500.00

Report Ref No. CS3/ASM21011562/Tvy3e2-1

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.