

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/FWD22000516/EPA3Q2**Date:** 20/01/2023REFERENCE

Handling Insurer:	FWD Singapore Pte. Ltd.	Policy No:	PNCV2020-00000082-01
<b>Claimant Vehicle No :</b>	SLQ9508L	<b>Insured Vehicle No :</b>	SMH6443U
Date of Loss:	08/01/2022	Nature of Claim:	TP
		Claim No:	1202200000560

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLQ9508L</b>	Engine No:	P520444591
Make & Model:	MAZDA 3, 1.5 SEDAN AT EU6 (A)	Chassis No:	JM6BN22A8H0152935
Reg. Date:	27/07/2017 (Man. Year: 2017)	Odometer:	327667 km
Colour:	Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Dunlop 4 mm	Rear Left Side:	Dunlop 4 mm
Front Right Side:	Dunlop 4 mm	Rear Right Side:	Dunlop 4 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,548.80	387.04	1,161.76	75.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,200.00	400.00	800.00	66.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>2,748.80</b>	<b>787.04</b>	<b>1,961.76</b>	<b>71.37</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>650.00</b>		
<b>(S\$)</b>	2,748.80	650.00	2,098.80	76.35
<b>+ GST 7.00/7.00% (S\$)</b>	192.42	45.50	146.92	76.35
<b>Nett Amount (S\$)</b>	<b>2,941.22</b>	<b>695.50</b>	<b>2,245.72</b>	<b>76.35</b>
<b>+ Car Rental (3.0 x S\$66.95/day) (S\$)</b>		200.85		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>903.80</b>		

INSPECTION

Date of Assignment:	14/01/2022	
Date Inspected:	17/01/2022 Inspected At:	Pegasus Engineering & Trading Pte Ltd (Kian Teck) 74 Kian Teck Road Singapore 628800
Estimated Period of Repair:	3.0 days	

**Adjuster:** CHEN TSUE YEE**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 24 Aug 2022)
<b>Parts:</b>	143	MAZDA 3 1.5 SEDAN AT EU6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLQ9508L)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	880.00 FL	*- FL
2	10		*FRONT BUMPER CLIPS	Not Necessary	40.00 FL	*- FL
3	1		*FRONT RADIATOR GRILLE	Not Necessary	215.00 FL	*- FL
4	8		*FRONT RADIATOR GRILLE RIVET	Not Necessary	40.00 FL	*- FL
5	1		*FRONT RADIATOR GRILLE TOP COVER	Crushed	340.00 FL	*285.80 FL
6	1		*FRONT RADIATOR GRILLE CHROME MOULDING (RHS)	Cracked	198.00 FL	*198.00 FL
7	1		*FRONT MAZDA LOGO	Not Necessary	65.00 FL	*- FL
8	1		*FRONT REINFORCEMENT COVER	Not Necessary	158.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>1,936.00</b>	<b>483.80</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	387.20	96.76
<b>Total Parts (\$\$)</b>	<b>1,548.80</b>	<b>387.04</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO KNOCKING AND PANEL BEATING	New	600.00	200.00
2	TO PUTTY & SPRAY PAINT ON THE AFFECTED AREAS	New	600.00	200.00
<b>Gross Labour Cost (S\$)</b>			<b>1,200.00</b>	<b>400.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >