

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/MSG22000517/KVF3E2

**Date:** 05/04/2022

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1001210564

**Claimant Vehicle No :** SMC319L

**Insured Vehicle No :** SKH786T

Date of Loss: 12/01/2022

Nature of Claim: TP

Claim No: 268194

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMC319L**

Make & Model: BMW X3 XDRIVE30I, 2.0 (A)

Engine No: F6221963B48B20B

Reg. Date: 26/06/2018 (Man. Year: 2018)

Chassis No: WBATR92060LE25547

Colour: Metallic Silver

Odometer: 53462 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 245/50 R19

Rear Tyre Size: 245/50 R19

Front Left Side: Michelin 9 mm

Rear Left Side: Michelin 9 mm

Front Right Side: Michelin 9 mm

Rear Right Side: Michelin 9 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,389.00	7,382.90	9,006.10	54.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,000.00	2,220.00	1,780.00	44.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>20,389.00</b>	<b>9,602.90</b>	<b>10,786.10</b>	<b>52.90</b>

### INSPECTION

Date of Assignment: 13/01/2022

Date Inspected: 14/01/2022 Inspected At:

Lim Yew Boo Spray Paint Co (HQ)  
Blk 10 Sin Ming Industrial Estate, #01-10  
Singapore 575645

Estimated Period of Repair: 7.0 days

**Adjuster:** KENNETH KONG

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 31 Mar 2022)
Parts:	M1-SUV	BMW X3 XDRIVE30I 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMC319L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEADLAMP ASSY/RH	Serviceable	4,281.00 FN	*- FN
2	1		*FRONT HEADLAMP LOWER BRACKET/RH	Serviceable	215.00 FN	*- FN
3	1		*FRONT FENDER/RH	Bent	1,225.00 FN	*938.00 FN
4	1		*FRONT FENDER INNER SHIELD/RH	Serviceable	213.00 FN	*- FN
5	10		*FRONT FENDER INNER SHIELD CLIPS	Not Necessary	50.00 FN	*- FN
6	1		*FRONT FENDER ARCH LINING/RH	Buckled	281.00 FN	*281.00 FN
7	10		*FRONT FENDER ARCH LINING CLIPS	Necessary	50.00 FN	*50.00 FN
8	1		*FRONT FENDER SIDE VENT/RH	Serviceable	115.00 FN	*- FN
9	1		*FRONT BUMPER LOWER SIDE SPOILER/RH	Serviceable	713.00 FN	*- FN
10	1		*FRONT DOOR/RH (WCP) (20%)	Bent	2,922.00 F	*1,854.00 F
11	1		*FRONT DOOR LOWER PROTECTOR/RH	Dented	183.00 FN	*183.00 FN
12	1		*FRONT DOOR WINDOW OUTER TOP CHANNEL/RH	Serviceable	185.00 FN	*- FN
13	1		*FRONT DOOR WINDOW FRAME GARNISH/RH	Serviceable	125.00 FN	*- FN
14	1		*REAR DOOR RUBBER/RH	Necessary	313.00 FN	*313.00 FN
15	1		*REAR DOOR/RH (WCP) (20%)	Bent	2,922.00 F	*1,854.00 F
16	1		*REAR DOOR LOWER PROTECTOR/RH	Dented	183.00 FN	*183.00 FN
17	1		*REAR DOOR WINDOW OUTER TOP CHANNEL/RH	Serviceable	185.00 FN	*- FN
18	1		*REAR DOOR WINDOW FRAME GARNISH/RH	Serviceable	125.00 FN	*- FN
19	1		*REAR DOOR RUBBER/RH	Necessary	313.00 FN	*313.00 FN
20	1		*FRONT BUMPER SENSOR	Serviceable	295.00 FN	*- FN
21	1		*FRONT DOOR WINDOW OUTER BOTTOM CHANNEL/RH	Serviceable	155.00 FN	*- FN
22	1		*FRONT RIM/RH	Dented	1,471.00 FS	*1,280.00 FS
23	1		*FRONT TYRE/RH (\$450) (80%)	Cut	650.00 FS	*360.00 FS
24	1		*REAR DOOR WINDOW OUTER BOTTOM CHANNEL/RH	Serviceable	155.00 FN	*- FN

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	17,325.00	7,609.00
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	936.00	226.10
Total Parts (\$\$)	16,389.00	7,382.90

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO APPLY RUST-PROOFING ON REPAIRED / REPLACED PANELS	New	280.00	90.00
2	TO CHECK & RECTIFY WIRING SYSTEM	New	120.00	30.00
3	TO RE-SET ABS SYSTEM & ERASE REGISTERED FAULT	New	150.00	100.00
4	TO CHECK WATER SEEPAGE (NPA)	New	0.00	0.00
5	LABOUR TO REPLACE THE SENSOR & CHECK SENSOR FUNCTIONS	New	120.00	0.00
6	TO REMOVE TYRE ENABLE TO REPLACE RIM & FIX SAME	New	120.00	20.00
7	TO CHECK COMPUTERISED WHEEL ALIGNMENT	New	120.00	60.00
8	TO REPAIR, PANEL BEAT, RE-ALIGN ON RIGHT FRT AFFECTED FRONT BONNET & LABOUR TO REPLACE THE ABOVE PARTS	New	1,200.00	700.00
9	TO PUTTY, PRIMER & SPRAY PAINT ON AFFECTED FRT BUMPER, FRT SENSOR, RIGHT FRT FENDER, FRT DOOR, REAR DOOR, REAR FENDER USING 2K PAINT	New	1,650.00	1,100.00
10	TO TRANSFER DAMAGE DOOR POWER WINDOW MECHANISM. RELATED PARTS & FITTING TO NEW DOOR	New	240.00	120.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,000.00</b>	<b>2,220.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >