



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLA 6961P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
2	FRONT WIPER ARM @\$160.00	SERVICEABLE	320.00	-
2	FRONT WIPER BLADE @\$65.00	O/S CUT	130.00	65.00
2	FRONT WIPER ARM LH COVER @\$15.00	CRACKED (1PC ONLY)	30.00	15.00
1	FRONT WINDSCREEN GLASS	CRACKED / SCRATCHED	925.00	925.00
2	ROOF MOULDING @\$385.00	DENTED	770.00	770.00
1	FRONT RH DOOR GLASS	SERVICEABLE	220.00	-
1	FRONT RH DOOR CHROME MOULDING	SERVICEABLE	195.00	-
1	FRONT LH DOOR GLASS	SERVICEABLE	220.00	-
1	FRONT LH DOOR CHROME MOULDING	SCRATCHED	195.00	195.00
1	REAR LH DOOR GLASS	SERVICEABLE	285.00	-
1	REAR LH DOOR CHROME MOULDING	SERVICEABLE	195.00	-
1	REAR LH OUTER GLASS	SERVICEABLE	245.00	-
1	REAR WINDSCREEN GLASS	SERVICEABLE	850.00	-
1	STAR LOGO - TRUNK	NECESSARY	58.00	58.00
1	EMBLEM - CLA180	NECESSARY	116.00	116.00
1	OUTER PILLAR MOULDING LH	SERVICEABLE	525.00	-
1	OUTER PILLAR MOULDING RH	DENTED	525.00	462.00
1	BONNET	BENT	1,800.00	1,702.00
	LESS 10% DISCOUNT		-760.40	-430.80
			6,843.60	3,877.20
<u>SPECIAL NETT ITEMS</u>				
1	FRONT WINDSCREEN GLASS SEALANT (SN)	NECESSARY	60.00	40.00
1	ROOF STICKER (SN)	NECESSARY	600.00	300.00
1	REAR SPOILER STICKER (SN)	NECESSARY	300.00	120.00
1	REAR LH QUARTER GLASS SEALANT (SN)	NOT NECESSARY	60.00	-
1	REAR WINDSCREEN GLASS SEALANT (SN)	NOT NECESSARY	60.00	-
1	TINTING FILM (SN)	NOT NECESSARY	800.00	-
			1,880.00	460.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO REMOVE AND REFIT FRONT WINDSCREEN GLASS.		150.00	120.00
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.	NOT NECESSARY	150.00	-
	TO REMOVE AND REFIT ROOF LINING TO CARRY OUT REPAIR ON ROOF PANEL.		220.00	100.00
	TO REMOVE AND REFIT DOOR GLASS X3 AND PILLAR MOULDING.	NOT NECESSARY	300.00	-
	TO REMOVE AND REFIT REAR LH QUARTER GLASS.	NOT NECESSARY	80.00	-
	TO KNOCK JACKOUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW ACCIDENT PARTS.		600.00	500.00
	SPRAY PAINTING ON AFFECTED & REPLACE PARTS.		2,000.00	1,700.00
			3,500.00	2,420.00
	GRAND TOTAL		12,223.60	6,757.20
	RECOMMENDED COST OF REPAIRS			6,757.20

Report Ref No. CS/UOI22000520/Kqf3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.