



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
UNITED OVERSEAS INSURANCE LTD 146 ROBINSON ROAD #02-01 UOI BUILDINGSINGAPORE 068909		Ref: CS/UOI22000520/Kqf3e2 Date: 23/06/2022 Code: UOI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	SLA 6961P
Policy No.		Coverage (\$)	0.00
Claim No.	L11D61732201	Excess (\$)	0.00
Assign From	CHAN LI SI	Assign Date	14/01/2022
2. Vehicle Particulars & Condition			
Make & Model	MERCEDES BENZ CLA180 (A)	c.c	1595
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	WDD1179422N280189	Colour	METALLIC SILVER
Odometer	103057 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/40 R18	GOODYEAR	7 mm
L/H Front Tyre	225/40 R18	GOODYEAR	7 mm
R/H Rear Tyre	225/40 R18	GOODYEAR	7 mm
L/H Rear Tyre	225/40 R18	GOODYEAR	7 mm
4. Description of Damages			
THE VEHICLE FOUND DAMAGED AT THE ROOF TOP, BONNET AND BODY PAINT WORK AT THE TIME OF INSPECTION. THE CAUSE AF DAMAGED DUE TO FALLEN CONCRETE CEMENT. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	17/12/2021	Inspection Date	14/01/2022
Survey held at	CITY AUTO PTE LTD BLK 8, SIN MING IND. ESTATE #01-60/62 Sector C SINGAPORE 575643.		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	