

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22000521/ENY3Q2**Date:** 13/12/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00111862103

**Claimant Vehicle
No :** SLB5142M**Insured Vehicle
No :** YN9175A

Date of Loss: 11/01/2022

Nature of Claim: TP

Claim
No: SNM22D200329/C02/CSC**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SLB5142M**

Make & Model: SKODA SUPERB, 1.8

Engine No: CHH298947

Reg. Date: 16/07/2019 (Man. Year: 2018)

Chassis No: TMBBD7NP9K7025694

Colour: Silver

Odometer: 32554 km

Engine Capacity: 1984 cc

Market Value/New Car
Price:

N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/50 R15

Rear Tyre Size: 195/50 R15

Front Left Side: Bridgestone 5 mm

Rear Left Side: Bridgestone 5 mm

Front Right Side: Bridgestone 5 mm

Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,372.13	3,840.65	2,531.48	39.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,680.00	4,040.00	1,640.00	28.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,052.13	7,880.65	4,171.48	34.61
+ GST 7.00/7.00% (S\$)	843.65	551.65	292.00	34.61
Nett Amount (S\$)	12,895.78	8,432.30	4,463.48	34.61

INSPECTION

Date of Assignment: 17/03/2022

Date Inspected: 19/01/2022 Inspected At:

Volkswagen Group Singapore Pte Ltd
247 ALEXANDRA ROAD
Singapore 159934

Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)
(EXCLUDE CHECK ITEMS S\$571.11 NETT)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Dec 2022)
Parts:	144	SKODA SUPERB 1.8 (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLB5142M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HOOD FRT BONNET	Dented	2,353.40 FS	*2,353.40 FS
2	1		*SOUND ABSO BONNET INSULATOR	*Check	107.27 FS	*- FS
3	10		*CLIP	*Check	23.60 FS	*- FS
4	1		*SKODA EMBL	Cut	63.90 FS	*63.90 FS
5	1		*COVER FOR FRT BUMPER	Repair	1,960.37 FS	*- FS
6	1		*SENSOR BRA	Necessary	45.94 FS	*45.94 FS
7	1		*SENSOR BRA	Necessary	45.94 FS	*45.94 FS
8	1		*SENSOR BRA	Necessary	45.94 FS	*45.94 FS
9	1		*SENSOR BRA	Necessary	45.94 FS	*45.94 FS
10	1		*2-PACK POLYURETHANE ADHES	Necessary	76.29 FS	*76.29 FS
11	1		*BONDING AGENT FOR PLASTIC	Necessary	68.71 FS	*68.71 FS
12	1		*BUFFER BUMPER FOAM	*Check	53.05 FS	*- FS
13	1		*GRILLE RADIATOR GRILLE	Cut	626.19 FS	*626.19 FS
14	1		*CONNECTING RADIATIR GRILLE TOP COVER	*Check	234.53 FS	*- FS
15	2		*RIVET	Necessary	4.12 FS	*4.12 FS
16	2		*PLUG	Necessary	2.26 FS	*2.26 FS
17	1		*COVER STRI RADIATOR GRILLE CHROM	Cut	382.02 FS	*382.02 FS
18	1		*COOLING AI CTR LOWER GRILLE	*Check	152.66 FS	*- FS
19	1		*NUMBER PLATE	Bent	80.00 FS	*80.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	6,372.13	3,840.65
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR	New	2,520.00	1,680.00
2	SPRAY PAINT	New	2,400.00	1,600.00
3	B&P DIAGNOSIS AND PROGRAMMING	New	480.00	480.00
4	B&P CHECK SHORT CIRCUIT /HARNESS REPAIR	New	280.00	280.00
Gross Labour Cost (\$\$)			5,680.00	4,040.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >