

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/GRB21007956/ETF3E2-1

**Date:** 27/01/2022

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447  
**Claimant Vehicle No :** SLK6312K **Insured Vehicle No :** SLL8219D  
Date of Loss: 26/07/2021 Nature of Claim: TP Claim No: MFL2021D0003212

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLK6312K**  
Make & Model: TOYOTA SIENTA, 1.5 G (A) Engine No: 2NR8590086  
Reg. Date: 23/01/2017 (Man. Year: 2016) Chassis No: NSP1707024423  
Colour: White Odometer: 90987 km  
Engine Capacity: 1496 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 185/55 R15 Rear Tyre Size: 185/55 R15  
Front Left Side: Bridgestone 4 mm Rear Left Side: Bridgestone 4 mm  
Front Right Side: Bridgestone 4 mm Rear Right Side: Bridgestone 4 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,803.31	3,590.67	4,212.64	53.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,840.00	1,720.00	1,120.00	39.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,643.31</b>	<b>5,310.67</b>	<b>5,332.64</b>	<b>50.10</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,250.00</b>		
<b>(S\$)</b>	10,643.31	4,250.00	6,393.31	60.07
<b>+ GST 7.00/7.00% (S\$)</b>	745.03	297.50	447.53	60.07
<b>Nett Amount (S\$)</b>	<b>11,388.34</b>	<b>4,547.50</b>	<b>6,840.84</b>	<b>60.07</b>

### INSPECTION

Date of Assignment: 14/01/2022  
Date Inspected: 27/07/2021 Inspected At: Fix Auto Pte Ltd (HQ)  
5 SOON LEE STREET, #01-61 PIONEER POINT  
Singapore 627607  
Estimated Period of Repair: 5.0 days

**Adjuster:** CHEN TSUE YEE

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 27 Jan 2022)
<b>Parts:</b>	M1-MPV	TOYOTA SIENTA 1.5 G (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLK6312K)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Necessary	120.70 FL	*120.70 FL
2	1		*REAR TAILGATE	Damaged	1,602.41 FL	*1,130.00 FL
3	2		*REAR TAILGATE DAMPERS	Not Necessary	482.58 FL	*- FL
4	2		*REAR TAILGATE LAMPS	Not Necessary	770.40 FL	*- FL
5	1		*REAR TAILGATE LOCK	Damaged	489.67 FL	*399.00 FL
6	1		*REAR TAILGATE LOGO	Necessary	58.50 FL	*58.50 FL
7	1		*REAR TAILGATE RUBBER	Necessary	291.61 FL	*291.61 FL
8	1		*REAR TAILGATE OPENING SWITCH	Intact	189.20 FL	*- FL
9	1		*REAR TAILGATE OUTER GARNISH	Damaged	257.30 FL	*257.30 FL
10	2		*REAR TAILLAMPS	Not Necessary	874.40 FL	*- FL
11	1		*REAR END PANEL	Damaged	820.65 FL	*820.65 FL
12	1		*REAR END PANEL INNER GARNISH	Damaged	221.50 FL	*180.00 FL
13	1		*REAR BUMPER	Damaged	788.70 FL	*455.00 FL
14	2		*REAR BUMPER BRACKETS	Not Necessary	197.00 FL	*- FL
15	1		*REAR BUMPER CENTRE PAD	Damaged	225.00 FL	*225.00 FL
16	2		*REAR BUMPER REFLECTORS	Not Necessary	190.00 FL	*- FL
17	2		*REAR BUMPER REFLECTOR OUTER GARNISHES	Damaged	361.00 FL	*361.00 FL
18	2		*REAR BUMPER SIDE RETAINERS	Necessary	128.80 FL	*128.80 FL
19	1		*REAR FLOOR PANEL	Intact	1,055.00 FL	*- FL
20	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
21	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
22	1		*SET REAR REVERSE SENSOR	Damaged	350.00 FS	*200.00 FS
23	1		*REAR REVERSE CAMERA	Not Necessary	480.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>10,084.42</b>	<b>4,697.56</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	2,281.11	1,106.89
<b>Total Parts (\$\$)</b>	<b>7,803.31</b>	<b>3,590.67</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, REFIT, REPLACED DAMAGED LAMPS AND CHECK UP REAR ELECTRICAL WIRING	New	80.00	30.00
2	TO REMOVE AND REFIT INNER GARNISHES, INNER TRIM TO ASSIST REPAIR	New	150.00	80.00
3	TO REMOVE AND REFIT REAR REVERSE SENSOR AND CAMERA	New	150.00	30.00
4	TO TRANSFER REAR TAILGATE MECHANISM AND WIRING ASSEMBLY TO ASSIST REPAIR	New	80.00	80.00
5	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	180.00	120.00
6	TO APPLY UNDERCOATING ON REPAIRED AND REPLACED PANEL	New	120.00	30.00
7	TO RESPRAY PAINTING INCLUDE POLISHING AND WAXING ON THE CHANGED BODY PARTS, REPAIRED PORTIONS WHERE CONSISTENT TO THE ACCIDENT	New	1,000.00	600.00
8	TO PROVIDE LABOUR CHARGES, WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS, REPAIR INCLUDING CUT AND WELD; RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,080.00	750.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,840.00</b>	<b>1,720.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >