



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:JANICE			Ref: CC4/ASM22000524/Apa3q2 Date: 18/05/2022 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SCK 8839B	Veh. Inspected	GY 985T
	Policy No.	GA552005	Coverage (\$)	0.00
	Claim No.	S2M03QXK	Excess (\$)	0.00
	Assign From		Assign Date	14/01/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	TOYOTA HIACE	c.c	2986
	Engine No.	HIDDEN	Year of Reg.	2004
	Chassis No.	LH1726123398	Colour	GREEN
	Odometer	880266 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	185 R14C	MICHELIN	6 mm
	L/H Front Tyre	185 R14C	MICHELIN	6 mm
	R/H Rear Tyre	185 R14C	MICHELIN	6 mm
	L/H Rear Tyre	185 R14C	MICHELIN	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	11/01/2022	Inspection Date	14/01/2022
	Survey held at	HD PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	