



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKM 1972P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER (CONSISTENT)	TORN	589.10	589.10
1	FRONT BUMPER REINFORCEMENT (CONSISTENT)	NOT NECESSARY	378.10	-
1	FRONT BUMPER SPONGE (CONSISTENT)	NOT NECESSARY	190.20	-
1	FRONT BUMPER SIDE RETAINER LH (CONSISTENT)	DAMAGED	171.30	65.00
1	FRONT BUMPER SENSOR LH (CONSISTENT)	DAMAGED	380.00	280.00
1	FRONT BUMPER LOWER GRILLE (CONSISTENT)	NOT NECESSARY	370.10	-
1	FRONT BUMPER FOG LAMP LH (CONSISTENT)	CRACKED	390.90	309.00
1	FRONT BUMPER FOG LAMP GARNISH /CHROME LH (CONSISTENT)	DEFORMED	289.10	88.00
1	FRONT GRILLE (CONSISTENT)	NOT NECESSARY	570.90	-
1	FRONT HEADLAMP LH (CONSISTENT)	CUT	2,723.10	1,675.00
1	FRONT HEADLAMP ECU LH (CONSISTENT)	NOT NECESSARY	987.10	-
1	FRONT FENDER LH (CONSISTENT)	NOT NECESSARY	789.10	-
1	FRONT FENDER INNER COWLING LH (CONSISTENT)	NOT NECESSARY	370.10	-
	LESS 25% DISCOUNT		-2,049.78	-751.53
			6,149.32	2,254.57
<u>SPECIAL NETT ITEMS</u>				
1	FRONT BUMPER CLIPS (SN) (CONSISTENT)	NECESSARY	80.00	30.00
1	FRONT FENDER INNER COWLING CLIPS (SN) (CONSISTENT)	NOT NECESSARY	60.00	-
1	FRONT GRILLE CLIPS (SN) (CONSISTENT)	NOT NECESSARY	50.00	-
			190.00	30.00
<u>LABOUR</u>				
	LABOUR FOR PANEL BEATING.		800.00	350.00
	LABOUR FOR SPRAYPAINTING.		600.00	250.00
	WIRING CHECK .		80.00	30.00
	TO APPLY TUFF COATING /RUST PROOF ACCIDENT AREAS .	NOT NECESSARY	300.00	-
	LABOUR FOR DIAGNOSE AND RESET ALL WARNING LIGHT.		600.00	150.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE FRONT BUMPER SENSOR .		100.00	50.00
			2,480.00	830.00
GRAND TOTAL			8,819.32	3,114.57
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,500.00

Report Ref No. CC4/ASM22000531/Aea3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.