



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJJ 1727J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR BOOT LID	TO REPAIR SEE LABOUR	2,522.00	-
1	REAR BOOT CHROME MOULDING	NECESSARY	296.00	145.00
1	REAR BOOT LOGO	NECESSARY	78.00	78.00
1	REAR BOOT "E200" EMBLEM	NECESSARY	88.00	88.00
1	REAR BOOT "9G-TRONIC" EMBLEM	NECESSARY	88.00	88.00
1	REAR BUMPER	CUT	2,094.00	2,094.00
1	REAR BUMPER LOWER DIFFUSER	CUT	655.00	485.00
1	REAR BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	817.00	-
2	REAR BUMPER SIDE RETAINERS	NECESSARY	96.00	96.00
1	REAR BUMPER CHROME MOULDING	DENTED	315.00	315.00
1	REAR BUMPER INNER GARNISH	CUT	215.00	215.00
2	REAR BUMPER SIDE BRACKETS	DAMAGED	144.00	144.00
2	REAR BUMPER PDC SENSORS	DAMAGED	650.00	430.00
	LESS 10% DISCOUNT		-805.80	-417.80
			7,252.20	3,760.20
<b>LABOUR</b>				
	TO REMOVE, REFIT, REPLACED DAMAGED LAMPS AND CHECK UP REAR ELECTRICAL WIRING.		80.00	20.00
	TO REMOVE AND REFIT INNER GARNISHES, INNER TRIM TO ASSIST REPAIR.		120.00	40.00
	TO REMOVE AND REFIT REAR REVERSE SENSOR.		150.00	30.00
	TO APPLY UNDERCOATING ON REPAIRED AND REPLACED PANEL.		80.00	30.00
	TO PROVIDE LABOUR CHARGES, WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS, REPAIR INCLUDING CUT AND WELD; RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF REAR BOOT LID AND REAR BUMPER REINFORCEMENT.		1,080.00	500.00

Report Ref No. CS3/LPC21009888/Vqf3e2-1



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RESPRAY PAINTING INCLUDE POLISHING AND WAXING ON THE CHANGED BODY PARTS, REPAIRED PORTIONS WHERE CONSISTENT TO THE ACCIDENT.		1,000.00	400.00
			2,510.00	1,020.00
GRAND TOTAL			9,762.20	4,780.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,800.00

Report Ref No. CS3/LPC21009888/Vqf3e2-1

THEVAN THOMAS KARTHIKESAVAN

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.