

# CL APPRAISER PTE LTD

24 Peshurst Place, Singapore 556440

Email: [clappraiser@yahoo.com](mailto:clappraiser@yahoo.com) Hp: 9068 8689 Fax: 6452 9783

Reg No: 201000228E

## VEHICLE INSPECTION REPORT

To: GN Jong Yuh Gwen Delyn  
C/o: SKM Garage & Trading LLP  
10 Kaki Bukit Road 2  
#03-22 First East Centre, Singapore 417868

Date : 5 October 2021  
Our ref : SKM/09/2101/TP

Accident Date : 13 September 2021  
Inspection Date : 27 September 2021  
Repairer Name : SKM Garage & Trading LLP  
10 Kaki Bukit Road 2  
#03-22 First East Centre, Singapore 417868

Type of Survey : Third Party

### PARTICULARS OF VEHICLE

Registration No	: SJJ 1727 J	Year / Capacity	: 2016 / 1991 cc
Make / Model	: Mercedes Benz E200 AMG	Colour	: Black
Chassis No	: WDD2130422A051249	Mileage	: 79916
Engine No	: 27492030678509		

### CONDITION OF TYRES

	Make	Size	Thread Balance	Rim
Front Nearside	: Dunlop	245/40 R19	5 mm	Sport
Front Offside	: Dunlop	245/40 R19	5 mm	Sport
Rear Nearside	: Dunlop	245/40 R19	5 mm	Sport
Rear Offside	: Dunlop	245/40 R19	5 mm	Sport

### GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the rear portion.  
(Details refer to the photographs attached)

Enclosed number of photographs: 58 copies

### REMARKS

This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis and we have not given authorization and instruction to the repairer to proceed with the repair.

### RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

3800

The repairer has agreed to undertake the job at a **Lump Sum of \$4,800.00** on a contractual basis.

Under normal circumstances, the repair period would be about 6 (Six) working days.

Vehicle Registration No.: SJJ 1727 J

Our Ref No.:

SKM/09/2101/TP

Qty	Description	Conditions	Repairer's Estimate	Revised Amount
-----	-------------	------------	---------------------	----------------

**SPARE PARTS - LIST ITEMS**

1	Rear boot lid	Repair	\$ 2,522.00	
1	Rear boot chrome moulding	Necessary	\$ 296.00	\$ 296.00 / 145
1	Rear boot logo	Necessary	\$ 78.00	\$ 78.00 /
1	Rear boot "E200" emblem	Necessary	\$ 88.00	\$ 88.00 /
1	Rear boot "9G-TRONIC" emblem	Necessary	\$ 88.00	\$ 88.00 /
1	Rear bumper	Damage	\$ 2,094.00	\$ 2,094.00 / Cut
1	Rear bumper lower diffuser	Damage	\$ 655.00	\$ 655.00 / 485 Cut
1	Rear bumper reinforcement	Repair	\$ 817.00	
2	Rear bumper side retainers	Necessary	\$ 96.00	\$ 96.00 /
1	Rear bumper chrome moulding	Damage	\$ 315.00	\$ 315.00 / 05
1	Rear bumper inner garnish	Damage	\$ 215.00	\$ 215.00 / Cut
2	Rear bumper side brackets	Damage	\$ 144.00	\$ 144.00 /
2	Rear bumper PDC sensors	Damage	\$ 650.00	\$ 650.00 / 430
			<b>\$ 8,058.00</b>	<b>\$ 4,719.00</b>
			<i>Less 10%</i> \$ 805.80	\$ 471.90
<b>Total Cost - List Items</b>			<b>\$ 7,252.20</b>	<b>\$ 4,247.10</b>

**Total cost of parts**

<b>\$ 7,252.20</b>	<b>\$ 4,247.10</b>
--------------------	--------------------

Vehicle Registration No.: SJJ 1727 J

Our Ref No.: SKM/09/2101/TP

S/No	Description	Repairer's Estimate	Revised Amount
	<b>Total cost of parts c/f</b>	<b>\$ 7,252.20</b>	<b>\$ 4,247.10</b>

### LABOUR

1	To remove, refit, replaced damaged lamps and check up rear electrical wiring	\$ 80.00	\$ 50.00 20
2	To remove and refit inner garnishes, inner trim to assist repair.	\$ 120.00	\$ 120.00 40
3	To remove and refit rear reverse sensor.	\$ 150.00	\$ 120.00 30
4	To apply undercoating on repaired and replaced panel.	\$ 80.00	\$ 30.00 ✓
5	To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld ; re-align body structure and damaged consistent to the accident.	\$ 1,080.00	\$ 750.00 500
6	To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.	\$ 1,000.00	\$ 660.00 400

**GRAND TOTAL**

<b>\$ 9,762.20</b>	<b>\$ 5,977.10</b>
--------------------	--------------------



Vehicle Registration No.: SJJ 1727 J

Our Ref No.: SKM/09/2101/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a **Lump Sum Repair Contract of : \$ 4,800.00**

3800

By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notified the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deemed to be valid.

Disclaimer

*The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.*

C L APPRAISER PTE LTD



Cheong KH  
Automotive Appraiser