

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/III22000535/UGA3Q2**Date:** 10/08/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MCV0008277  
**Claimant Vehicle No :** GBG8893B **Insured Vehicle No :** PA7806B  
 Date of Loss: 14/01/2022 Nature of Claim: TP Claim No: MCV2022D0000359

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBG8893B**  
 Make & Model: TOYOTA DYNA 150, 3.0 D 5MT (M) Engine No: 1KD2756604  
 Reg. Date: 29/11/2017 (Man. Year: 2017) Chassis No: JTFAT35Y60K209282  
 Colour: Silver Odometer: 154080 km  
 Engine Capacity: 2982 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 155 R12 (D)  
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6/6 mm  
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6/6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	14,266.10	2,685.85	11,580.25	81.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,150.00	1,710.00	3,440.00	66.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>19,416.10</b>	<b>4,395.85</b>	<b>15,020.25</b>	<b>77.36</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,500.00</b>		
<b>Nett Amount (S\$)</b>	<b>19,416.10</b>	<b>3,500.00</b>	<b>15,916.10</b>	<b>81.97</b>
<b>+ Car Rental (4.0 x S\$85.00/day) (S\$)</b>		340.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>3,847.45</b>		

INSPECTION

Date of Assignment: 14/01/2022  
 Date Inspected: 14/01/2022 Inspected At: Choo Motor Spray Painter (HQ)  
 1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki Bukit  
 Singapore 417883  
 Estimated Period of Repair: 4.0 days

**Adjuster:** MARCUS CHUA**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 21 Jul 2022)	
<b>Parts:</b>	N/A	TOYOTA DYNA 150 3.0 D 5MT (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBG8893B)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Dented / Bent	1,860.00 F	*1,615.30 FL
2	1		*REAR TAILGATE LOCK LATCHES	N/S Bent	760.00 F	*205.10 FL
3	1		*REAR TAILGATE LOCK LOWER L BRACKETS	N/S Bent	360.00 F	*145.10 FL
4	2		*REAR TAILGATE LOCK LOWER L BRACKET RUBBERS	Not Necessary	240.00 F	*- FL
5	1		*REAR TAILGATE DYNA STICKER	Necessary	80.00 F	*58.60 FL
6	1		*REAR TAILGATE TOYOTA STICKER	Necessary	281.00 F	*180.60 FL
7	1		*TAILLAMPS	N/S Cracked	900.00 F	*291.33 FL
8	2		*TAILLAMP HOUSING PANELS	Repair	360.00 F	*- FL
9	1		*REAR LICENCE PLATE BRACKET	Repair	345.00 F	*- FL
10	1		*REAR EXHAUST	Not Necessary	1,250.00 F	*- FL
11	1		*REAR EXHAUST MOUNTING	Not Necessary	85.00 F	*- FL
12	1		*REAR END PANEL	Bent	685.10 F	*685.10 FL
13	1		*REAR SPARE TYRE CARRIER & CHAIN	Not Necessary	680.00 F	*- FL
14	1		*DROPSIDE GATE PANEL N/S	Repair	2,290.00 F	*- FL
15	1		*DROPSIDE GATE PANEL O/S	Not Necessary	2,290.00 F	*- FL
16	1		*REAR TAILGATE INNER ALUMINIUM PLATE	Not Necessary	900.00 FS	*- FS
17	1		*SET REAR TAILGATE 70KM/H & 12 PAX STICKER	Necessary	50.00 FS	*50.00 FS
18	1		*SET REAR REVERSE SENSOR	Shorted	300.00 FS	*200.00 FS
19	1		*REAR LICENCE PLATE	Not Necessary	50.00 FS	*- FS
20	1		*SET REAR ALUMINIUM PLATE RIVET	Necessary	100.00 FS	*50.00 FS
21	1		*SET REAR CARGO DECK STOPPER RUBBER	Not Necessary	200.00 FS	*- FS
22	1		*REAR STEP BRACKET	Repair	200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>14,266.10</b>	<b>3,481.13</b>
<b>- List Item Discount on L Items 0.00/25.00% (\$\$)</b>	0.00	795.28
<b>Total Parts (\$\$)</b>	<b>14,266.10</b>	<b>2,685.85</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REPLACED REVERSE SENSOR	New	100.00	40.00
3	TO DISMANTLE & REPLACED REAR CARGO DECK	New	800.00	0.00
4	TO STRAIGHTEN & REALIGN CHASSIS	New	1,000.00	0.00
5	TO SPRAY RUST PROOFING	New	200.00	50.00
6	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,500.00	800.00
7	TO PUTTY & SPRAY PAINTING	New	1,500.00	800.00
<b>Gross Labour Cost (\$\$)</b>			<b>5,150.00</b>	<b>1,710.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >