

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22000538/AQF3Q2**Date:** 30/01/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNW00014042100
Claimant Vehicle No :	SJR6357T	Insured Vehicle No :	SLJ2887A
Date of Loss:	11/01/2022	Nature of Claim: TP	Claim No: SNM22D200299/C02/TAYHP

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJR6357T	Engine No:	G4FC9H264214
Make & Model:	KIA CERATO, 1.6 (A)	Chassis No:	KNAFH221395086993
Reg. Date:	02/07/2009 (Man. Year: 2009)	Odometer:	210583 km
Colour:	White		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Arivo 6 mm	Rear Left Side:	Arivo 6 mm
Front Right Side:	Arivo 6 mm	Rear Right Side:	Arivo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,448.39	4,253.07	4,195.32	49.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,780.00	1,800.00	1,980.00	52.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	12,228.39	6,053.07	6,175.32	50.50
Approved Total (Overridden) (\$\$)		4,800.00		
Nett Amount (\$\$)	12,228.39	4,800.00	7,428.39	60.75

INSPECTION

Date of Assignment:	14/01/2022	
Date Inspected:	13/01/2022 Inspected At:	Ace Autolution Pte Ltd (KAKI BUKIT) 13 Kaki Bukit Road 4, #03-29/30 Bartley Biz Centre Singapore 417807
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Jan 2023)
Parts:	143	KIA CERATO 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJR6357T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Dented	910.00 FL	*793.00 FL
2	2		*REAR BOOTLID HINGE LH & RH	Not Necessary	290.40 FL	*- FL
3	2		*REAR BOOTLID SPONGE LH & RH	Not Necessary	332.00 FL	*- FL
4	1		*REAR BOOTLID CERATO EMBLEM	Necessary	90.00 FL	*90.00 FL
5	1		*REAR BOOTLID FORTE EMBLEM	Necessary	80.00 FL	*80.00 FL
6	1		*REAR BOOTLID C&C EMBLEM	Necessary	86.00 FL	*86.00 FL
7	1		*REAR BOOTLID LOGO	Necessary	81.00 FL	*81.00 FL
8	1		*REAR BOOTLID INNER LOCK	Damaged	124.30 FL	*124.30 FL
9	1		*REAR BOOTLID WEATHERSTRIP	Cut	320.00 FL	*188.00 FL
10	1		*REAR BOOTLID INNER TRIM BOARD	Not Necessary	155.00 FL	*- FL
11	1		*REAR BOOTLID CHROME	Not Necessary	159.00 FL	*- FL
12	1		*REAR BUMPER	Deformed	795.00 FL	*698.00 FL
13	2		*REAR BUMPER SIDE RETAINER LH & RH	Necessary	167.20 FL	*82.00 FL
14	1		*REAR BUMPER INNER SPONGE	Not Necessary	155.00 FL	*- FL
15	1		*REAR BUMPER LOWER	Deformed	1,003.50 FS	*450.00 FS
16	1		*REAR BUMPER REINFORCEMENT	Distorted	350.00 FL	*350.00 FL
17	2		*REAR BUMPER REINFORCEMENT BRACKET LH & RH	Not Necessary	180.00 FL	*- FL
18	1		*REAR BUMPER TOP & LOWER BRACKET	Damaged	220.00 FL	*90.00 FL
19	1		*REAR END PANEL	Distorted	510.00 FL	*510.00 FL
20	1		*REAR END PANEL TOP GARNISH	Deformed	120.00 FL	*120.00 FL
21	1		*REAR SPARE TYRE PANEL	Repair	611.00 FL	*- FL
22	1		*REAR SPARE TYRE PANEL TOP COVER	Not Necessary	179.00 FL	*- FL
23	2		*REAR TAILLAMP LH & RH	Cut	1,042.00 FL	*600.00 FL
24	2		*REAR TAILLAMP LOWER BRACKET LH & RH	Not Necessary	299.20 FL	*- FL
25	2		*REAR TAILLAMP INNER SPONGE LH & RH	Not Necessary	116.00 FL	*- FL
26	1		*SET REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
27	1		*SET REAR CAR PLATE WITH HOLDER	Not Necessary	70.00 FS	*- FS
28	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
29	1		*REAR WINDSCREEN SEALANT	Not Necessary	100.00 FS	*- FS
30	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*60.00 FS
31	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	80.00 FS	*10.00 FS
32	1		*SET REAR BOOTLID INNER TRIM BOARD CLIPS	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,185.60	4,642.30
- List Item Discount on L Items 10.00/10.00% (\$\$)	737.21	389.23
Total Parts (\$\$)	8,448.39	4,253.07

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS AND REPLACE DAMAGED PARTS	New	1,600.00	800.00
2	TO SUPPLY PAINT MATERIALS ,EXPANDABLE ITEMS & PUTTY ,RESPRAY PAINT ON PARTS REPLACED	New	1,400.00	800.00
3	TO REMOVE AND REFIX WIRING AT DAMAGED AREAS	New	100.00	30.00
4	TO PERFORM ANTI RUST TREATMENT ON AFFECTED AREAS	New	200.00	60.00
5	TO REMOVE AND REPLACE REVERSE SENSORS AND CHECK FOR PROPER FUNCTIONS	New	120.00	50.00
6	TO REMOVE REAR BOOTLID MECHANISM	New	210.00	60.00
7	TO CONDUCT WATER SEPAGE TEST	New	150.00	0.00
Gross Labour Cost (S\$)			3,780.00	1,800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >