

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT AXA INSURANCE PTE LTD Ref: CS3/ASM22000540/Vty3e2 8 SHENTON WAY #24-01 AXA TOWER Date: 27/01/2022 SINGAPORE 068811 ATTN: KOH JANICE Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. SHD 4699S **SLE 202R** Veh. Inspected Policy No. VFX/P2419138 Coverage (\$) 0.00 Claim No. S2M03R1S Excess (\$) 0.00 **KOH JANICE Assign Date** 14/01/2022 Assign From **Vehicle Particulars & Condition** 2. **HONDA VEZEL 1.5X** 1496 Make & Model C.C HIDDEN 2016 Engine No. Year of Reg. RU11112437 **BLUE** Chassis No. Colour Odometer 36540 KM Steering IN ORDER **IN ORDER** STANDARD ALLOY RIM **Brakes** Modification GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 215/60 R16 DUNLOP 6 mm DUNLOP L/H Front Tyre 215/60 R16 6 mm 215/60 R16 DUNLOP R/H Rear Tyre 6 mm **DUNLOP** L/H Rear Tyre 215/60 R16 6 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. 5. **General Information** 07/01/2022 Inspect Date / Time 18/01/2022 ( 11:00 AM ) Accident Date SKM GARAGE & TRADING LLC Survey held at 10 KAKI BUKIT ROAD 2 #03-22 FIRST EAST CENTRE SINGAPORE 417868 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,000-\$2,000 5b. **Estimate Days of Repair** 

Report Ref No. CS3/ASM22000540/Vty3e2

**Inspected By** 

THEVAN THOMAS KARTHIKESAVAN

**ESTIMATED NORMAL PERIOD FOR REPAIR:** 

The

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser

3 Working Days