

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22000545/VVF3N2**Date:** 15/02/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00155432100	
Claimant Vehicle No :	SMA6338C	Insured Vehicle No :	GBA7579Y	
Date of Loss:	13/01/2022	Nature of Claim:	TP	Claim No: SNM22D200346/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMA6338C		Engine No:	2ZR0B47993
Make & Model:	TOYOTA PRIUS, 1.5 (A)		Chassis No:	ZVW400029175
Reg. Date:	14/06/2018 (Man. Year: 2018)		Odometer:	41020 km
Colour:	Brown			
Engine Capacity:	1797 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Wanli 5 mm	Rear Left Side:	Wanli 5 mm
Front Right Side:	Wanli 5 mm	Rear Right Side:	Wanli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,831.69	3,305.38	11,526.31	77.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,300.00	1,450.00	2,850.00	66.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	19,131.69	4,755.38	14,376.31	75.14
Approved Total (Overridden) (\$\$)		3,800.00		
Nett Amount (\$\$)	19,131.69	3,800.00	15,331.69	80.14

INSPECTION

Date of Assignment:	18/01/2022	Auto Bullox Pte Ltd (HQ) 53 UBI AVE 1, #01-19 PAYA UBI INDUSTRIAL PARK Singapore 408934
Date Inspected:	17/01/2022 Inspected At:	
Estimated Period of Repair:	4.0 days	

Adjuster: Thevan Thomas Karthikesavan**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Feb 2022)
Parts:	144	TOYOTA PRIUS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMA6338C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	995.45 FL	*602.56 FL
2	2		*REAR BUMPER REFLECTOR	Serviceable	384.48 FL	*- FL
3	1		*REAR BUMPER BRACKET CORNER (2 Pcs)	Necessary (1 Pc only)	170.52 FL	*85.26 FL
4	2		*REAR BUMPER ARM SUB-ASSY	Not Necessary	280.70 FL	*- FL
5	1		*REAR BUMPER REINFORCEMENT	Not Necessary	255.70 FL	*- FL
6	1		*U-SONIC SENDER (4 Pcs)	Cut (2 Pcs only)	701.60 FL	*200.00 FL
7	1		*SET U-SONIC SENDER BRACKET	Necessary	28.76 FL	*28.76 FL
8	1		*REAR BUMPER UNDER COVER GARNISH	Not Necessary	525.40 FL	*- FL
9	1		*REAR BUMPER LOWER LIP	Not Necessary	228.90 FL	*- FL
10	1		*TAILLAMP LED (2 Pcs)	Cracked (1 Pc only)	1,441.26 FL	*630.00 FL
11	2		*TAILLAMP LOWER BRACKET	Serviceable	269.20 FL	*- FL
12	2		*TAILLAMP INNER PANEL	Serviceable	572.80 FL	*- FL
13	1		*TAILGATE PANEL	Dented	1,276.80 FL	*980.00 FL
14	1		*TAILGATE GLASS	Cracked	1,376.40 FL	*1,050.00 FL
15	1		*TAILGATE GLASS SPONG TAPE/SEAL	Necessary	175.60 FL	*100.00 FL
16	1		*TAILGATE OUTER GARNISH	Serviceable	584.90 FL	*- FL
17	1		*TAILGATE OUTER BUTTON SWITCH SENSOR	Serviceable	396.74 FL	*- FL
18	1		*TAILGATE LOGO	Necessary	76.40 FL	*76.40 FL
19	1		*TAILGATE EMBLEM PRIUS	Necessary	83.20 FL	*83.20 FL
20	1		*TAILGATE EMBLEM HYBRID	Necessary	71.00 FL	*71.00 FL
21	2		*TAILGATE STOPPER	Serviceable	56.80 FL	*- FL
22	2		*TAILGATE HINGE	Serviceable	195.30 FL	*- FL
23	2		*TAILGATE DAMPER	Serviceable	95.00 FL	*- FL
24	1		*TAILGATE INNER TRIMBOARD	Serviceable	528.70 FL	*- FL
25	1		*SET TAILGATE INNER TRIMBOARD CLIPS	Necessary	55.00 FL	*30.00 FL
26	1		*TAILGATE INNER LOCK	Serviceable	468.52 FL	*- FL
27	1		*TAILGATE LOCK CATCHER	Serviceable	119.42 FL	*- FL
28	1		*TAILGATE WEATHER STRIP	Serviceable	374.85 FL	*- FL
29	1		*REAR END PANEL	Serviceable	781.40 FL	*- FL
30	1		*REAR END PANEL TOP GARNISH	Serviceable	478.85 FL	*- FL
31	1		*REAR ANTENNA SENSOR	Serviceable	175.40 FL	*- FL
32	1		*REAR FLOOR PANEL	Serviceable	1,087.64 FL	*- FL
33	1		*REAR FLOOR PANEL TOP BOARD	Serviceable	679.20 FL	*- FL
34	2		*DECK FLOOR COVER	Serviceable	393.60 FL	*- FL
35	2		*REAR FENDER INNER TRIM	Serviceable	994.76 FL	*- FL
36	1		*SET REAR FENDER INNER TRIM GARNISH CLIPS	Serviceable	55.00 FL	*- FL
37	1		*REAR EXHAUST BOX	Serviceable	1,086.70 FL	*- FL
38	1		*REAR EXHAUST CHROME MUFFLER	Serviceable	197.82 FL	*- FL
39	2		*REAR EXHAUST MOUNTING	Serviceable	193.08 FL	*- FL
40	2		*TAILGATE SIDE TRIM	Serviceable	203.40 FL	*- FL
41	1		*SET REAR BUMPER CLIPS	Necessary	66.00 FL	*30.00 FL
42	1		*SET REAR NUMBER PLATE W/GARNISH	Serviceable	55.00 FS	*- FS
43	1		*REAR WINDSCREEN SOLAR FILM	Cut	680.00 FS	*180.00 FS
44	1		*REAR WINDSCREEN PRIMER & CLEANER	Necessary	100.00 FS	*50.00 FS

Report was unsubmitted during this print-out.

2/15/22, 4:10 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*60.00 FS
46	1		*REAR WINDSCREEN INNER SEAL	Necessary	60.00 FS	*40.00 FS
47	1		*REAR WINDSCREEN SEALANT	Repeated	60.00 FS	*- FS
48	1		*REAR END PANEL SEALANT	Not Necessary	80.00 FS	*- FS
49	1		*REAR FLOOR PANEL SEALANT	Not Necessary	80.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					19,377.25	4,297.18
- List Item Discount on L Items 25.00/25.00% (S\$)					4,545.56	991.80
Total Parts (S\$)					14,831.69	3,305.38
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,REPLACE,RE-ALIGN & INSTALL AFFECTED REAR DAMAGED AREAS	New	1,400.00	500.00
2	TO PUTTY,PREP & RE-SPRAY ON AFFECTED REAR DAMAGED AREAS.(REAR BUMPER,TAILGATE,END PANEL,REAR FENDERS,SPARE TYRE PANEL)	New	1,500.00	600.00
3	TO REMOVE & TRANSFER REAR TAILGATE COMPONENTS TO FACILITATE REPAIRS	New	150.00	60.00
4	TO REMOVE & REFIT REAR INTERIOR FLOOR COMPONENTS TO FACILITATE REPAIRS	New	150.00	50.00
5	TO REMOVE & INSTALL REAR WINDSCREEN GLASS TO FACILITATE REPAIRS	New	150.00	120.00
6	TO REMOVE & INSTALL REAR EXHAUST PIPE TO FACILITATE REPAIRS	New	150.00	0.00
7	TO MEASURE,DRILL HOLES ON REPLACED REAR BUMPER,TO RE-POSITION & INSTALL REVERSE SENSOR	New	150.00	40.00
8	TO CONDUCT WATER SEEPAGE TEST	New	120.00	20.00
9	TO DISCONNECT REAR WIRE HARNESS,HYBRID ELECTRICAL COMPONENTS TO FACILITATE REPAIRS	New	250.00	0.00
10	TO APPLY UNDERCOATING ON THE AFFECTED DAMAGED AREAS	New	280.00	60.00
Gross Labour Cost (S\$)			4,300.00	1,450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >