

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/III22000553/KEA3Q2**Date:** 08/06/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MPC0003593  
**Claimant Vehicle No :** SHF741T **Insured Vehicle No :** SLC97M  
 Date of Loss: 13/01/2022 Nature of Claim: TP Claim No: MPC2022D0000492

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHF741T**  
 Make & Model: RENAULT LATITUDE, 2.0 L DCI AUTO D/AB 4DR (A) Engine No: M9R8839C002976  
 Reg. Date: 30/06/2016 (Man. Year: 2015) Chassis No: VF1ABL15AUC282727  
 Colour: Metallic White/Red Odometer: 471425 km  
 Engine Capacity: 1995 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16  
 Front Left Side: Sailun 8 mm Rear Left Side: Sailun 8 mm  
 Front Right Side: Sailun 8 mm Rear Right Side: Sailun 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	8,062.84	3,570.61	4,492.23	55.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,580.00	1,330.00	6,250.00	82.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>15,642.84</b>	<b>4,900.61</b>	<b>10,742.23</b>	<b>68.67</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,900.00</b>		
<b>(S\$)</b>	15,642.84	3,900.00	11,742.84	75.07
<b>+ GST 7.00/7.00% (S\$)</b>	1,095.00	273.00	822.00	75.07
<b>Nett Amount (S\$)</b>	<b>16,737.84</b>	<b>4,173.00</b>	<b>12,564.84</b>	<b>75.07</b>
<b>+ Loss of Use (7.0 x S\$40.00/day) (S\$)</b>		280.00		
<b>+ Car Rental (7.0 x S\$81.32/day) (S\$)</b>		569.24		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>5,029.69</b>		
<b>Global Sum Settlement (S\$)</b>		<b>5,020.00</b>		

INSPECTION

Date of Assignment: 14/01/2022  
 Date Inspected: 17/01/2022 Inspected At: Trans-cab Auto Services Pte Ltd  
 No 2 Ang Mo Kio Street 63  
 Singapore 569111  
 Estimated Period of Repair: 3.0 days

**Adjuster:** KENNETH KONG**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 25 Apr 2022)

**Parts:** 143 RENAULT LATITUDE 2.0 L DCI AUTO D/AB 4DR (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SHF741T)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Bent	561.70 FL	*561.70 FL
2	1		*BUMPER LOWER REAR	Serviceable	411.90 FL	*- FL
3	1		*BUMPER BRACKET CTR REAR	Serviceable	98.10 FL	*- FL
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	82.10 FL	*- FL
5	1		*BUMPER REFLECTOR RH	Cracked	16.60 FL	*16.60 FL
6	1		*BUMPER RETAINER RH REAR	Serviceable	59.80 FL	*- FL
7	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	80.80 FL	*- FL
8	1		*BUMPER RETAINER LH REAR	Serviceable	54.20 FL	*- FL
9	1		*BUMPER BEAM REAR	Bent	547.80 FL	*547.80 FL
10	1		*OUTER PANEL REAR (END PANEL)	Repair	745.80 FL	*- FL
11	1		*OUTER PANEL REAR (END PANEL)TRIM	Serviceable	404.56 FL	*- FL
12	1		*TAILLAMP LH	Serviceable	401.40 FL	*- FL
13	1		*TAILLAMP RH	Cracked	401.40 FL	*401.40 FL
14	1		*BOOT REAR	Bent	1,677.20 FL	*1,677.20 FL
15	1		*BOOT BADGE RENAULT	Necessary	82.40 FL	*82.40 FL
16	1		*BOOT BADGE	Necessary	95.80 FL	*95.80 FL
17	1		*BOOT HINGE LH	Repair	254.20 FL	*- FL
18	1		*BOOT HINGE RH	Repair	254.20 FL	*- FL
19	1		*BOOT STRUT LH	Serviceable	145.10 FL	*- FL
20	1		*BOOT STRUT RH	Serviceable	145.10 FL	*- FL
21	1		*BOOT LOCK	Repair	246.60 FL	*- FL
22	1		*BOOT LOCK CATCH	Repair	41.70 FL	*- FL
23	1		*BOOT FINISHER	Serviceable	344.70 FL	*- FL
24	1		*SET PARKING AID	Shorted	700.00 FS	*400.00 FS
25	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
26	1		*FENDER CLIP	Not Necessary	60.00 FS	*- FS
27	1		*SET BUMPER BRACKET CTR CLIP	Not Necessary	33.00 FS	*- FS
28	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
29	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
30	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
31	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
32	1		*SET BUMPER LOWER REAR CLIP	Not Necessary	66.00 FS	*- FS
33	1		*REAR BOOT STICKER TRANS-CAB	Necessary	80.00 FS	*30.00 FS
34	1		*REAR BOOT STICKER 6555-3333	Necessary	80.00 FS	*30.00 FS
35	2		*WINDSCREEN SEALANT	Not Necessary	150.00 FS	*- FS
36	1		*WINDSCREEN MOULDING	Not Necessary	200.00 FS	*- FS
37	1		*WINDSCREEN INNER SPONGE SEAL	Not Necessary	130.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>8,778.16</b>	<b>3,908.90</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	715.32	338.29
<b>Total Parts (\$)</b>	<b>8,062.84</b>	<b>3,570.61</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,000.00	500.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	3,000.00	660.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	30.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
5	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
6	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
7	TO DROP REAR EXHAUST BOX ,RENEW THE SAME ,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	0.00
8	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
9	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00
10	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
11	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
<b>Gross Labour Cost (\$)</b>			<b>7,580.00</b>	<b>1,330.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >