

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG22000555/GTCE2

**Date:** 30/05/2022

### REFERENCE

Insured/Claimant:	LOW CHEE WAI	Policy No:	7210147665		
Date of Loss:	07/01/2022	Nature of Claim:	OD	Claim No:	4810903430SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SND1573U		
Make & Model:	AUDI Q3 SPORTBACK, 1.4 TFSI S TRONIC (17) (A)	Engine No:	CZDC48931
Reg. Date:	09/12/2021 (Man. Year: 2021)	Chassis No:	WAUZZZF30M1155311
Colour:	Blue	Odometer:	1939 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$175,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	215/65 R17	Rear Tyre Size:	215/65 R17
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,145.00	5,058.48	2,086.52	29.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,052.00	3,472.00	3,580.00	50.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>14,197.00</b>	<b>8,530.48</b>	<b>5,666.52</b>	<b>39.91</b>
<b>- Excess (S\$)</b>	<b>400.00</b>	<b>400.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>13,797.00</b>	<b>8,130.48</b>	<b>5,666.52</b>	<b>41.07</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>965.79</b>	<b>569.13</b>	<b>396.66</b>	<b>41.07</b>
<b>Nett Amount (S\$)</b>	<b>14,762.79</b>	<b>8,699.61</b>	<b>6,063.18</b>	<b>41.07</b>

### INSPECTION

Date of Assignment:	14/01/2022		
Date Inspected:	13/01/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days		

**Adjuster:** XING GUO QIANG

**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER - RH	Buckled	1,286.00 FS	*1,028.80 FS
2	1		*FRONT FENDER BRACE - RH	Not Necessary	88.00 FS	*- FS
3	1		*FRONT FENDER BRACKET - RH	Not Necessary	32.00 FS	*- FS
4	1		*FRONT FENDER CLOSING ELEMENT - RH	Not Necessary	33.00 FS	*- FS
5	1		*FRONT WHEEL HOUSING LINER - RH (NPA)	Not Necessary	0.00 FS	*- FS
6	2		*FRONT WHEEL ARCH COVER - LH / RH	Scratched	536.00 FS	*428.80 FS
7	1		*FRONT DOOR - RH	Bent	2,805.00 FS	*2,244.00 FS
8	1		*FRONT DOOR OUTER SEAL - RH	Necessary	166.00 FS	*125.60 FS
9	1		*FRONT DOOR ATTACHMENT PARTS	Not Necessary	157.00 FS	*- FS
10	1		*FRONT DOOR CATCH - RH	Not Necessary	120.00 FS	*- FS
11	1		*FRONT DOOR HINGES HALVE - RH UPPER	Not Necessary	46.00 FS	*- FS
12	1		*FRONT DOOR HINGES HALVE - RH LOWER	Not Necessary	46.00 FS	*- FS
13	1		*FRONT DOOR LOWER MOLDING COVER - RH	Scratched	268.00 FS	*214.40 FS
14	1		*ALUMINIUM RIM	Cut	1,262.00 FS	*1,009.60 FS
15	1		*SUNDRIES	Necessary	300.00 FS	*7.28 FS
					<b>Total Parts (\$\$)</b>	<b>7,145.00 5,058.48</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	0.00
2	TO REMOVE AND TRANSFER RHS FRONT DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	400.00	400.00
3	TO DISMANTLE AND REINSTALL FRONT BUMPER. TO RENEW RHS FRONT FENDER AND RHS FRONT DOOR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	3,200.00	1,500.00
4	TO RESPRAY RHS FRONT FENDER, RHS FRONT DOOR AND HINGES	New	2,500.00	1,100.00
5	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>7,052.00</b>	<b>3,472.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >