

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	SOMPO INSURAN	CE SINGAPORE PL		Ref:	CS3/SMO22000557/Utf3e2
	50 RAFFLES PLAC TOWER SINGAPO	CE #03-03 SINGAPORE LAND RE 048623		Date:	25/01/2022
				Code:	SMO
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	GBK 273Y	Veh. Inspected	t	SLH 8442X
	Policy No.		Coverage (\$)		0.00
	Claim No.	CMTD2200184/THE	Excess (\$)		0.00
	Assign From	MELVIN YE YONG KANG	Assign Date		14/01/2022
2.	Vehicle Particulars & Condition				
	Make & Model	HONDA VEZEL HYBRID (A)	c.c		1496
	Engine No.	HIDDEN	Year of Reg.		2016
	Chassis No.	RU31209705	Colour		GREY
	Odometer	113733 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		SPORTS RIM
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	215/60 R16	MICHELIN		6 mm
	L/H Front Tyre	215/60 R16	MICHELIN		6 mm
	R/H Rear Tyre	215/60 R16	MICHELIN		6 mm
	L/H Rear Tyre	215/60 R16	MICHELIN		6 mm
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.				
5.	General Information				
	Accident Date	13/01/2022	Inspect Date /	Time	17/01/2022 (12:50 PM)
	Survey held at	A S AUTO SERVICE			
	NO 1 KAKI BUKIT #01-106 SINGAPORE 417883				
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,500-\$3,000				
5b.	Estimate Days of Repair				
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:		5 Worki	ing Days

Report Ref No. CS3/SMO22000557/Utf3e2

Inspected By

CHUA KANG SENG Licensed Appraiser K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser