

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJK 2805E

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT HEADLAMP RH	CRACKED	1,003.70	953.60
1	FRONT BUMPER	DENTED	881.50	645.10
1	FRONT BUMPER RETAINER RH	NECESSARY	50.30	50.30
1	FRONT FENDER RH	DENTED	786.95	698.00
1	FRONT FENDER INNER SHIELD RH	BENT	158.50	158.50
1	FRONT FENDER SIGNAL LAMP RH	DISTORTED	34.50	34.50
1	FRONT QUARTER GLASS MOULDING	NECESSARY	110.50	110.50
1	FRONT KNUCKLE ARM RH	SERVICEABLE	406.80	-
1	FRONT W BEARING RH	BROKEN	120.60	120.60
1	FRONT LOWER ARM RH	BENT	477.70	421.90
1	FRONT SHOCK ABSORBER RH	SERVICEABLE	408.50	-
	LESS 25% DISCOUNT		-1,109.89	-798.25
			3,329.66	2,394.75
	SPECIAL NETT ITEMS			
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	50.00	30.00
1	SET FRONT FENDER INNER SHIELD CLIP (SN)	NECESSARY	50.00	30.00
1	FRONT RIM RH (SN)	SCRATCHED	750.00	400.00
1	FRONT TYRE RH (SN)	SERVICEABLE	400.00	-
			1,250.00	460.00
	<u>LABOUR</u>			
	CHECK WIRING AND LIGHTNING SYSTEM.		60.00	30.00
	COMPUTERIZE AND CHECK WHEEL ALIGNMENT.		200.00	60.00
	REMOVE & REPLACE FRONT UNDERCARRIAGE.		200.00	60.00
	PANEL BEATING ON AFFECTED AREAS.		1,000.00	550.00
	SPRAY PAINTING ON AFFECTED AREAS.		1,000.00	550.00
	APPLY ANTI RUST ON AFFECTED AREAS.		150.00	50.00
			2,610.00	1,300.00
	GRAND TOTAL		7,189.66	4,154.75

Report Ref No. CS/SMR22000558/Vqy3m4



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		3,000.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/SMR22000558/Vqy3m4



THEVAN THOMAS KARTHIKESAVAN

**Asst. Automotive Assessor** 



**ANG BRYAN TANI** 

**Automotive Assessor / Investigator**