

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22000559/ATF3N2**Date:** 09/05/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00172682101

**Claimant Vehicle
No :** GBK632U**Insured
Vehicle No :** SMP2320A

Date of Loss: 12/01/2022

Nature of Claim: TP

Claim
No: SNM22D200310/C02/TOHHS**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **GBK632U**

Make & Model: TOYOTA DYNA 1.5T, 3.0 (A)

Engine No: 1KD2864848

Reg. Date: 29/11/2019 (Man. Year: 2019)

Chassis No: JTFAT35Y70K214202

Colour: White

Odometer: 123274 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/70R15C

Rear Tyre Size: 155R12C

Front Left Side: Habilead 6 mm

Rear Left Side: Tourador 6 mm

Front Right Side: Habilead 6 mm

Rear Right Side: Tourador 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,556.40	6,960.15	4,596.25	39.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,380.00	2,400.00	980.00	28.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	14,936.40	9,360.15	5,576.25	37.33
Approved Total (Overridden) (\$\$)		7,500.00		
Nett Amount (\$\$)	14,936.40	7,500.00	7,436.40	49.79

INSPECTION

Date of Assignment: 14/01/2022

Date Inspected: 14/01/2022

Inspected At: Hiap Hong Motor Repair
2 Kaki Bykit Avenue 2, #02-13
Singapore 417921

Estimated Period of Repair: 8.0 days

Adjuster: ADRIAN LING**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 09 May 2022)	
Parts:	N/A	TOYOTA DYNA 1.5T 3.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBK632U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent	748.90 F	*748.90 FL
2	2		*FRONT BUMPER BRACKET	Bent	344.00 F	*344.00 FL
3	2		*FRONT BUMPER SIDE GRILLE COVER	Not Necessary	124.00 F	*- FL
4	1		*FRONT GRILLE	Missing	438.80 F	*438.80 FL
5	1		*FRONT GRILLE LOGO	Necessary	76.20 F	*76.20 FL
6	2		*HEADLAMP	Cracked	1,631.00 F	*1,631.00 FL
7	1		*FRONT PANEL	Dented	1,194.40 F	*1,194.40 FL
8	1		*DYNA EMBLEM	Necessary	68.20 F	*68.20 FL
9	2		*FRONT CORNER PANEL	Repair	596.00 F	*- FL
10	1		*WIPER PANEL	Dented	563.40 F	*563.40 FL
11	1		*WIPER PANEL NOZZLE	O/s Cracked	117.20 F	*58.60 FL
12	1		*WIPER MOTOR	Not Necessary	637.80 F	*- FL
13	1		*WIPER LINKAGE	Cracked	387.70 F	*387.70 FL
14	1		*WIPER ARM	O/s Cut	229.00 F	*114.50 FL
15	1		*FRONT WINDSCREEN MOULDING	Necessary	285.10 F	*285.10 FL
16	1		*AIR CON SUCTION PIPE	Dented	295.40 F	*295.40 FL
17	1		*AIR CON DISCHARGE PIPE	Dented	289.50 F	*289.50 FL
18	1		*AIR CON BLOWER	Cracked	1,335.10 F	*1,335.10 FL
19	1		*AIR CON EVAPORATOR	Cracked	1,289.40 F	*1,289.40 FL
20	1		*FRONT CHASSIS CROSSMEMBER	Not Necessary	785.30 F	*- FL
21	1		*FRONT NUMBER PLATE	Bent	30.00 FS	*30.00 FS
22	1		*FRONT GRILLE CLIPS	Necessary	30.00 FS	*30.00 FS
23	1		*FRONT WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,556.40	9,240.20
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	2,280.05
Total Parts (\$\$)	11,556.40	6,960.15

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,200.00	900.00
2	SPRAY PAINTING	New	1,200.00	900.00
3	WIRING	New	50.00	30.00
4	TO SPRAY TUFFCOAT	New	150.00	80.00
5	TO REMOVE FRONT WINDSCREEN	New	180.00	120.00
6	TO REMOVE AIR CON SYSTEM	New	250.00	150.00
7	TO REMOVE DASHBOARD	New	350.00	220.00
Gross Labour Cost (\$\$)			3,380.00	2,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >