

TP China.
Deise.

GBK632U. 2019 Nov
Toyota Dyna 2982CC
JT FAT3SY70K214202

Front Number Plate.	Bent	30(SN) /
Front Bumper	Bent	748.90 /
Front Bumper Bracket x02	Bent	172x2 = 344. /
Front Bumper Side Grille Cover x02	HP new	62x2 = 124. X
Front Grille	Missing	438.80. /
Front Grille Logo	} new	76.20. /
Front Grille clips.		30(SN). /
Headlamp x02	Cracked	815.5 x 2 = 1631. /
Front Panel	Dented	1194.40. /
Dyna Emblem.	New	68.20 /
Front Corner Panel x02	Repair	298x2 = 596 X.
Wiper Panel.	Dented	563.40 /
Wiper Panel Nozzle x02	RH could	58.60 58.6 x 2 = 117.20
Wiper motor	HP new	631.80 X

GBK632U.

Wiper Linkage. ^{could}
Wiper Arm x 02 RH at

Front Windscreen Moulding. } New

Front Windscreen Sealant.

Air Con Suction Pipe } Dented

Air Con Discharge Pipe

Air Con Blower } Cracked

Air Con Evaporator

Front Chassis Crossmembers. ^{NP}
_{MR}

387.70 —
 $114.5 \times 2 = 229$ 114.50

285.10 —

60(SN) —

295.40 —

285.50 —

1335.10 —

1289.40 —

785.30. X.

9120.20.

6840.155

S.N: 120

GBK632U.

Panel Beating

Spray Painting.

Wiring.

To spray buff coat

To remove front windscreen.

To remove air con system.

To remove dashboard.

~~1200~~ 900
~~1200~~ 900
~~50~~ 30

2400 ~~150~~ 80

~~180~~ 120

~~250~~ 150.

~~350~~ 220

total: 9360.15

1/8: 7.5K.
08 Days

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

7.5K

08 Days