2/14/22, 2:11 PM Adjuster Report

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI22000563/TQCN2

**Date:** 14/02/2022

**REFERENCE** 

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No: MM000752

Claimant Vehicle Curposex

No: SHB6286Y Insured Vehicle No: SLQ4889U

Date of Loss: 07/01/2022 Nature of Claim: TP Claim No: M2200292

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SHB6286Y

Make & Model: TOYOTA PRIUS TAXI, 1.8 (A) Engine No: 2ZR2F59988

Reg. Date: 05/12/2019 (Man. Year: 2019) Chassis No: JTDKB3FU603089666

Colour: Blue Odometer: 330518 km

Engine Capacity: 1798 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Good

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15
Front Left Side: West Lake 6 mm Rear Left Side: West Lake 6 mm
Front Right Side: West Lake 6 mm
West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,396.08	774.90	621.18	44.49
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,270.00	630.00	640.00	50.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,677.08	1,415.90	1,261.18	47.11
+ GST 7.00/7.00% (S\$)	187.40	99.11	88.29	47.11
Nett Amount (S\$)	2,864.48	1,515.01	1,349.47	47.11

**INSPECTION** 

Date of Assignment: 17/01/2022 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)

ComfortDelGro Engineering Pte Ltd (Loyang)

Date Inspected: 10/01/2022 Inspected At: 59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

2/14/22, 2:11 PM Adjuster Report

## **REPAIR DETAILS**

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 14 Feb 2022)

Parts: 144 TOYOTA PRIUS TAXI 1.8 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SHB6286Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### **Recommended Parts**

No.	Qty	Part No	. Particulars	Condition	Repairer's	Reference	Amount
1	1		*REAR BUMPER	Deformed	458.60 FL	-	*458.60 FL
2	1		*REAR BUMPER LOWER COVER	Deformed	552.60 FL	-	*552.60 FL
3	1		*REAR BUMPER REINFORCEMENT	Not Necessary	318.80 FL	-	*- FL
4	10		*REAR BUMPER CLIP	Necessary	22.00 FL	-	*22.00 FL
5	1		*BOOTLID EMBLEM PRIUS	Not Necessary	60.08 FL	-	*- FL
6	1		*BOOTLID EMBLEM HYBRID	Not Necessary	52.40 FL	-	*- FL
7	1		*REVERSE SENSOR	Not Necessary	135.70 FS	-	*- FS
8	1		*COMFORT LOGO APP	Not Necessary	40.00 FS	-	*- FS
9	1		*COMFORT DELGRO LOGO /TEL NUMBER STICKER	Not Necessary	60.00 FS	-	*- FS
10	1		*BUMPER TOW COVER	Not Necessary	82.70 FL	-	*- FL
F=Fra	anchise	part. S=Sp	cNett. L=ListItemDisc.				
				Sub Total (S\$)	1,782.88	1,033.20	
			- List Item Discount on L Items 25	.00/25.00% (S\$)	386.80	258.30	
				Total Parts (S\$)	1,396.08		774.90

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

No	Qty	Particulars		Repairer's	Amount
Misc	ellan	eous Items			
1	1	OD/TP Case (Insurer)		11.00	11.00
			Sub Total (S\$)	11.00	11.00

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	<u>our Items</u>			
1	PANEL BEATING	New	550.00	350.00
2	SPRAY PAINTING	New	600.00	250.00
3	REMOVE/RFIX REVERSE SENSOR	New	60.00	30.00
4	TUFF COATING	New	60.00	0.00
		Gross Labour Cost (S\$)	1,270.00	630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >