

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EQI22000564/TTF3E2

Date: 06/05/2022

REFERENCE

Handling Insurer: EQ Insurance Company Ltd

Policy No:

Claimant Vehicle No : SJJ741Z

Insured Vehicle No : SKD6181U

Date of Loss: 14/01/2022

Nature of Claim: TP

Claim No: DM22HO00075

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJJ741Z**

Make & Model: HONDA FIT, 1.3 G (A)

Engine No: L13A4096578

Reg. Date: 01/09/2008 (Man. Year: 2008)

Chassis No: GE61086749

Colour: Black

Odometer: 132597 km

Engine Capacity: 1339 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55 R15

Rear Tyre Size: 195/55 R15

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,485.15	1,427.15	1,058.00	42.57
Miscellaneous Items	40.00	0.00	40.00	100.00
Labour	1,430.00	790.00	640.00	44.76
Paintwork Labour	820.00	750.00	70.00	8.54
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,775.15	2,967.15	1,808.00	37.86
+ GST 7.00/7.00% (S\$)	334.26	207.70	126.56	37.86
Nett Amount (S\$)	5,109.41	3,174.85	1,934.56	37.86

INSPECTION

Date of Assignment: 14/01/2022 Present Location:

Kan Fook Sing Motor Workshop (Defu)

Date Inspected: 17/01/2022 Inspected At:

Kan Fook Sing Motor Workshop (Defu)

No. 61 Defu Lane 12

Estimated Period of Repair: 6.0 days

Singapore 539147

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$765.25 NETT)

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 May 2022)
Parts:	144	HONDA FIT 1.3 G (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJJ741Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN PILLAR RH (WCP)	Repair	280.00 F	*- F
2	1		*FRONT WINDSCREEN MOUOLDING (WCP)	Not Necessary	45.00 F	*- F
3	1		*FRONT FENDER RH (WCP)	Bent	95.00 F	*95.00 F
4	1		*FRONT FENDER SHIELD RH (WCP)	Deformed	38.00 F	*38.00 F
5	10		*FRONT FENDER SHIELD CLIP (WCP)	Necessary	20.00 F	*20.00 F
6	1		*FRONT DOOR RH (WCP)	Bent	340.00 F	*340.00 F
7	1		*FRONT DOOR HINGE TOP RH (WCP)	Bent	30.00 F	*30.00 F
8	1		*FRONT DOOR HINGE LOWER RH (WCP)	Bent	30.00 F	*30.00 F
9	1		*FRONT DOOR CHECKER RH (WCP)	*Check	40.00 F	*- F
10	1		*FRONT DOOR RUBBER RH (WCP)	Necessary	45.00 F	*45.00 F
11	1		*FRONT DOOR LOCK RH (WCP)	*Check	180.00 F	*- F
12	1		*FRONT DOOR REGULATOR RH (WCP)	*Check	95.00 F	*- F
13	1		*FRONT DOOR OUTER MOULING RH (WCP)	Deformed	58.00 F	*58.00 F
14	1		*FRONT DOOR FAME STICKER RH (WCP)	Necessary	30.00 F	*30.00 F
15	1		*FRONT DOOR SIDE MIRROR RH (WCP)	*Check	220.00 F	*- F
16	1		*FRONT SIDE MIRROR RH (WCP)	Cracked	35.00 F	*35.00 F
17	1		*REAR DOOR RH (WCP)	Bent	420.00 F	*420.00 F
18	1		*REAR DOOR FAME STICKER RH (WCP)	Necessary	20.00 F	*20.00 F
19	1		*REAR DOOR HINGE TOP RH (WCP)	Repair	30.00 F	*- F
20	1		*REAR DOOR HINGE LOWER RH (WCP)	Repair	30.00 F	*- F
21	1		*FRONT DOOR OUTER HANDLE RH (WCP)	Distorted	80.00 F	*80.00 F

F=Franchise part.

Sub Total (\$\$)	2,161.00	1,241.00
+ Margin on L,N Items 15.00/15.00% (\$\$)	324.15	186.15
Total Parts (\$\$)	2,485.15	1,427.15

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	FRONT WINDSCREEN GUM (Not Necessary)	40.00	0.00
Sub Total (\$\$)			40.00	0.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	SPRAYPAINTING CHARGES	New	820.00	750.00
Labour Items				
2	TO CHECK WIRING SYSTEM	New	30.00	30.00
3	TO CHECK ALIGNMENT	New	80.00	80.00
4	TO TRANSFER DOOR MECHANICISM TO NEW DOOR	New	80.00	80.00
5	TO REMOVE/REFIT FRONT WINDSCREEN GLASS	New	100.00	0.00
6	TO REMOVE/REFIT CUSHION, CARPET AND ETC *Check	New	150.00	0.00
7	TO REMOVE/REFIT DASHBOARD	New	240.00	0.00
8	TO REMOVE ALL NECESSARY AFEFCTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	New	750.00	600.00
Gross Labour Cost (\$\$)			2,250.00	1,540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >