

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT (SUPPLEMENTARY #1)

**Our File No:** CS/EQI22000564/TTF3E2

**Date:** 06/05/2022

### REFERENCE

Handling Insurer: EQ Insurance Company Ltd

Policy No:

**Claimant Vehicle No :** SJJ741Z

**Insured Vehicle No :** SKD6181U

Date of Loss: 14/01/2022

Nature of Claim: TP

Claim No: DM22HO00075

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJJ741Z**

Make & Model: HONDA FIT, 1.3 G (A)

Engine No: L13A4096578

Reg. Date: 01/09/2008 (Man. Year: 2008)

Chassis No: GE61086749

Colour: Black

Odometer: 132597 km

Engine Capacity: 1339 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	300.00	300.00	0.00	0.00
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>300.00</b>	<b>300.00</b>	<b>0.00</b>	<b>0.00</b>
<b>+ GST 7.00/7.00% (S\$)</b>	21.00	21.00	0.00	0.00
<b>Nett Amount (S\$)</b>	<b>321.00</b>	<b>321.00</b>	<b>0.00</b>	<b>0.00</b>
<b>+ Previous Recommendations (S\$)</b>		0.00		
<b>Nett Liability (S\$)</b>		<b>321.00</b>		

### INSPECTION

Date of Assignment: 14/01/2022

Present Location:

Kan Fook Sing Motor Workshop (Defu)

Date Inspected: 17/01/2022

Inspected At:

Kan Fook Sing Motor Workshop (Defu)

No. 61 Defu Lane 12

Singapore 539147

Estimated Period of Repair: 6.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 May 2022)
Parts:	144	HONDA FIT 1.3 G (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJJ741Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	FRONT RIM RH (CUT)	300.00	300.00
<b>Sub Total (\$\$)</b>			<b>300.00</b>	<b>300.00</b>

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >