

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunos Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS/ICS22000567/GVF3N2**Date:** 17/03/2022**REFERENCE**

Insured/Claimant:	DU NINI	Policy No:	MPC21A00043604	
Date of Loss:	12/01/2022	Nature of Claim:	OD	Claim No: DMPC2200016H/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFR8000G		
Make & Model:	TOYOTA HARRIER 2.0, 2.0 PREMIUM AT AIRBAG 2WD (A)	Engine No:	3ZRC004933
Reg. Date:	12/05/2017 (Man. Year: 2017)	Chassis No:	ZSU600106307
Colour:	Maroon	Odometer:	28464 km
Engine Capacity:	1986 cc		
Market Value/New Car Price:	S\$92,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55R18	Rear Tyre Size:	235/55R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,439.20	6,568.10	1,871.10	22.17
Miscellaneous Items	85.00	85.00	0.00	0.00
Labour	3,880.00	2,530.00	1,350.00	34.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	12,404.20	9,183.10	3,221.10	25.97
- Excess (\$\$)	750.00	0.00	750.00	100.00
(\$\$)	11,654.20	9,183.10	2,471.10	21.20
+ GST 7.00/7.00% (\$\$)	815.79	642.82	172.97	21.20
Nett Amount (\$\$)	12,469.99	9,825.92	2,644.07	21.20

INSPECTION

Date of Assignment:	14/01/2022	
Date Inspected:	17/01/2022	Inspected At: Ricardo Auto Centre Pte Ltd (HQ) 160 Sin Ming Drive, #02-02, Sin Ming AutoCity Singapore 575722
Estimated Period of Repair:	6.0 days	

Adjuster: XING GUO QIANG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 16 Mar 2022)		
Parts:	N/A	TOYOTA HARRIER 2.0 2.0 PREMIUM AT AIRBAG 2WD (A) (Model not available in database)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SFR8000G)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Tail gate (WCP)	Buckled	500.00 F	*500.00 F
2	1		*Tail gate plate - HARRIER (WCP)	Necessary	28.00 F	*28.00 F
3	1		*Tail gate TOYOTA LOGO (WCP)	Necessary	25.00 F	*25.00 F
4	1		*Tail gate lock (WCP)	Cut	260.00 F	*260.00 F
5	1		*Rear bumper (WCP)	Repair	450.00 F	*- F
6	1		*Rear bumper sponge (WCP)	Not Necessary	50.00 F	*- F
7	1		*Bonnet lock (WCP)	Bent	60.00 F	*60.00 F
8	1		*Bonnet hinges LH (WCP)	Bent	40.00 F	*40.00 F
9	1		*Bonnet hinges RH (WCP)	Bent	40.00 F	*40.00 F
10	1		*Bonnet (WCP)	Bent	450.00 F	*450.00 F
11	1		*Front bumper reinforcement upper (WCP)	Bent	100.00 F	*100.00 F
12	1		*Front bumper reinforcement (WCP)	Bent	165.00 F	*165.00 F
13	1		*Front bumper sponge, centre (WCP)	Deformed	50.00 F	*50.00 F
14	1		*Front bumper sponge LH (WCP)	Cracked	25.00 F	*25.00 F
15	1		*Front bumper sponge RH (WCP)	Cracked	25.00 F	*25.00 F
16	1		*Front bumper (WCP)	Cracked	250.00 F	*280.00 F
17	1		*Front bumper lower grille (WCP)	Deformed	95.00 F	*95.00 F
18	1		*Front bumper lower lid (WCP)	Not Necessary	110.00 F	*- F
19	1		*Front bumper side retainer LH (WCP)	Not Necessary	40.00 F	*- F
20	1		*Front bumper side retainer RH (WCP)	Not Necessary	40.00 F	*- F
21	1		*Radiator grille (WCP)	Cracked	180.00 F	*180.00 F
22	1		*Radiator top cover (WCP)	Deformed	140.00 F	*140.00 F
23	10		*Radiator top cover clips (WCP)	Necessary	15.00 F	*15.00 F
24	1		*Front support panel (WCP)	Repair	280.00 F	*- F
25	1		*Brace panel (WCP)	Bent	90.00 F	*90.00 F
26	10		*Front bumper clips (WCP)	Not Necessary	15.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
27	1		*Headlamp LH (WCP)	Cracked	900.00 F	*900.00 F
28	1		*Headlamp RH (WCP)	Cracked	900.00 F	*900.00 F
29	4		*Radiator grille clips (WCP)	Not Necessary	6.00 F	*- F
30	1		*Aircon condenser (WCP)	Bent	480.00 F	*480.00 F
31	1		*Radiator assy (WCP)	Bent	500.00 F	*500.00 F
32	1		*Horn LH (WCP)	Not Necessary	45.00 F	*- F
33	1		*Horn RH (WCP)	Not Necessary	45.00 F	*- F
34	1		*Sensor, temperature (WCP)	Not Necessary	50.00 F	*- F
35	1		*Front fender LH (WCP)	Repair	300.00 F	*- F
36	1		*Front fender RH (WCP)	Repair	300.00 F	*- F
<u>Supplementary #1</u>						
37	1		*Radiator support garnish RH (big) (WCP)	Deformed	35.00 F	*35.00 F
38	1		*Radiator support garnish LH (small) (WCP)	Deformed	25.00 F	*25.00 F
39	1		*Radiator support garnish LH (big) (WCP)	Deformed	45.00 F	*45.00 F
40	1		*Fog lamp cover LH (WCP)	Cut	48.00 F	*48.00 F
41	1		*Rear windscreen glass moulding lower (WCP)	Necessary	40.00 F	*40.00 F
42	1		*Rear windscreen glass moulding side LH (WCP)	Necessary	25.00 F	*25.00 F
43	1		*Rear windscreen glass moulding side RH (WCP)	Necessary	25.00 F	*25.00 F
44	1		*Front support panel - center (WCP)	Bent	150.00 F	*150.00 F
45	1		*Bonnet moulding (WCP)	Missing	110.00 F	*110.00 F
<u>Supplementary #2</u>						
46	1		*Supply & replace rear bumper sensor (including painting to body colour)		120.00 F	*120.00 F

F=Franchise part.

Sub Total (\$)	7,672.00	5,971.00
+ Margin on L,N Items 10.00/10.00% (\$)	767.20	597.10
Total Parts (\$)	8,439.20	6,568.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	Front number plate with holder (Missing)	45.00	45.00
Supplementary #1				
2	1	To supply windscreen sealant (Necessary)	40.00	40.00
Sub Total (\$\$)			85.00	85.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	To cut, weld & straighten front portion & rear portion of car caused by accident. Adjust & replace damage parts.	New	1,500.00	800.00
2	To focus headlamp	New	30.00	30.00
3	To service aircon, top up gas & recharge system.	New	120.00	120.00
4	To transfer tailgate mechanism	New	80.00	60.00
5	To calibrate & reset auto back door	New	150.00	0.00
6	Computerize wheel alignment	New	80.00	0.00
7	To spray paint on front & rear repaired areas	New	1,800.00	1,400.00
Supplementary #1				
Labour Items				
8	To remove back windscreen glass enable to replace new tailgate and fix same.	New	120.00	120.00
Gross Labour Cost (\$\$)			3,880.00	2,530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >