



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBP 1064B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FORK SET	BENT	800.00	399.00
1	FORK T UNDER BRACKET	BENT	400.00	180.00
1	STEERING CONE	NECESSARY	250.00	50.00
1	FRONT SPORT RIM	TO REPAIR SEE LABOUR	700.00	-
1	FRONT DISC BRAKE	SERVICEABLE	280.00	-
1	TYRE SHAFT	SERVICEABLE	150.00	-
1	HANDLE BAR	BENT	400.00	175.00
1	HANDLE BAR END	SCRATCHED	150.00	60.00
1	MIRROR SET	SCRATCHED	180.00	120.00
1	BRAKE LEVER (R)	SCRATCHED	200.00	45.00
1	HEAD LAMP	CRACKED	950.00	311.00
1	HEAD LAMP STAY	CRACKED	350.00	90.00
1	HEAD LAMP UNDER COVER	CRACKED	50.00	50.00
1	SIGNAL LIGHT	CRACKED	280.00	165.00
1	RIGHT FAIRING INNER COVER	NOT NECESSARY	180.00	-
1	LEFT FAIRING INNER COVER	NOT NECESSARY	180.00	-
1	INNER PANEL	CUT	450.00	195.00
1	RIGHT PANEL COVER	NOT NECESSARY	350.00	-
1	LEFT PANEL COVER	NOT NECESSARY	350.00	-
1	FUEL TANK COVER	SERVICEABLE	280.00	-
1	RADIATOR COVER	SCRATCHED	180.00	92.50
1	EXHAUST COVER	SCRATCHED	150.00	60.00
1	FRONT FOOTREST COVER	DISTORTED	250.00	120.00
1	FOOTREST UNDER COVER	SCRATCHED	220.00	130.00
1	LEFT FOOTREST UNDER COVER	SERVICEABLE	220.00	-
1	MAINSTAND	TO REPAIR SEE LABOUR	330.00	-
1	COVERSET FULL	CRACKED / SCRATCHED	850.00	450.00
1	REAR BOX	SCRATCHED	500.00	150.00
1	FRONT MUD GUARD INNER COVER	BENT	180.00	75.00

Report Ref No. CS/AGI22000569/Vtf3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR FOOTREST	SCRATCHED	150.00	75.00
1	BRAKE LEVER	SERVICEABLE	200.00	-
	LESS 10% DISCOUNT		-	-299.25
			10,160.00	2,693.25
	<b>LABOUR</b>			
	PRESS BODY.		600.00	100.00
	LABOUR.INCLUSIVE OF THE REPAIR OF FRONT SPORT RIM AND MAINSTAND.		700.00	200.00
			1,300.00	300.00
	<b>GRAND TOTAL</b>		<b>11,460.00</b>	<b>2,993.25</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>2,300.00</b>

Report Ref No. CS/AGI22000569/Vtf3n2

THEVAN THOMAS KARTHIKESAVAN

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.