

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22000573/VPA3Q2**Date:** 14/04/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900168045-02
Claimant Vehicle No :	GBB2096B	Insured Vehicle No :	GBE3594H
Date of Loss:	15/01/2022	Nature of Claim:	TP
		Claim No:	4613157288SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBB2096B	Engine No:	1KD1867021
Make & Model:	TOYOTA HIACE, 3.0 D (M)	Chassis No:	JTFHT02P700032245
Reg. Date:	26/09/2008 (Man. Year: 2008)	Odometer:	259860 km
Colour:	Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	Falken 5 mm	Rear Left Side:	Falken 5 mm
Front Right Side:	Falken 5 mm	Rear Right Side:	Falken 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,306.92	5,417.22	1,889.70	25.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,010.00	1,670.00	340.00	16.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,316.92	7,087.22	2,229.70	23.93
Approved Total (Overridden) (S\$)		5,500.00		
(S\$)	9,316.92	5,500.00	3,816.92	40.97
+ GST 7.00/7.00% (S\$)	652.18	385.00	267.18	40.97
Nett Amount (S\$)	9,969.10	5,885.00	4,084.10	40.97
+ Loss of Use (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		6,621.45		
Global Sum Settlement (S\$)		6,600.00		

INSPECTION

Date of Assignment:	17/01/2022	
Date Inspected:	17/01/2022 Inspected At:	Ryder Auto Pte Ltd (HQ) 2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit Singapore 417921
Estimated Period of Repair:	5.0 days	

Adjuster: Thevan Thomas Karthikesavan**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	656.20 FL	*656.20 FL
2	1		*REAR BUMPER O/S & N/S RETAINER	Necessary	182.70 FL	*182.70 FL
3	4		*REAR CENTRE BRACKET	Repair	80.00 FL	*- FL
4	1		*REAR TAILGATE	Bent	1,925.90 FL	*1,925.90 FL
5	1		*REAR TAILGATE WEATHERSTRIP	Cut	320.00 FL	*320.00 FL
6	1		*REAR TAILGATE INNER TRIM	Serviceable	210.00 FL	*- FL
7	1		*REAR TAILGATE TOYOTA EMBLEM	Necessary	82.00 FL	*60.00 FL
8	1		*REAR TAILGATE GARNISH	Cut	310.40 FL	*289.00 FL
9	1		*REAR TAILGATE LOCK (UPPER)	Jammed	172.00 FL	*172.00 FL
10	1		*REAR TAILGATE LOCK (LOWER)	Serviceable	81.50 FL	*- FL
11	1		*REAR TAILGATE LOCK ACTUATOR	Jammed	365.60 FL	*365.60 FL
12	1		*REAR O/S & N/S TAIL LAMP	Cracked	891.20 FL	*791.60 FL
13	1		*REAR END PANEL (OUTER)	Dented	596.00 FL	*596.00 FL
14	1		*REAR END PANEL GARNISH CHROME	Repair	210.50 FL	*- FL
15	1		*REAR WINDSCREEN	Cracked	1,556.80 FL	*1,115.20 FL
16	2		*REAR REG NO.PLATE LAMP	Cracked (1 PCS ONLY)	185.40 FL	*58.00 FL
17	1		*REAR SPARE WHEEL TYRE BRACKET	Bent	210.50 FL	*172.10 FL
18	1		*REAR CARPET	Serviceable	295.20 FL	*- FL
19	10		*REAR BUMPER CLIPS	Necessary	30.00 FS	*20.00 FS
20	6		*REAR TAILGATE INNER TRIM CLIPS	Necessary	24.00 FS	*12.00 FS
21	1		*REAR TAILGATE 70KMPH EMBLEM	Necessary	15.00 FS	*10.00 FS
22	6		*REAR TAILGATE MOULDING CLIPS	Necessary	24.00 FS	*12.00 FS
23	1		*REAR WINDSCREEN SOLAR FILM	Not Necessary	150.00 FS	*- FS
24	1		*REAR WINDSCREEN MOULDING	Necessary	120.00 FS	*60.00 FS
25	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
26	1		*REAR REG NO.PLATE	Bent	35.00 FS	*35.00 FS
27	1		*SET REAR REVERSE SENSOR	Cut	280.00 FS	*200.00 FS
28	1		*REAR REVERSE CAMERA	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	9,389.90	7,093.30
- List Item Discount on L Items 25.00/25.00% (\$)	2,082.98	1,676.08
Total Parts (\$)	7,306.92	5,417.22

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE DAMAGED PARTS ,STRAIGHTEN & WELDING	New	800.00	800.00
2	TO SPRAY PAINTING	New	600.00	600.00
3	TO REMOVE & REPLACE REAR WINDSCREEN	New	140.00	120.00
4	TO REMOVE AND REPLACE REAR REVERSE CAMERA	New	100.00	0.00
5	TO REMOVE AND REFIT REAR TAIL GATE	New	80.00	40.00
6	TO REMOVE AND REPLACE REAR TAIL GATE ALUMINIUM	New	80.00	40.00
7	TO REMOVE AND REFIT REAR UPHOLSTERY TO FACILITATE REPAIR	New	80.00	30.00
8	TO CHECK WIRING	New	80.00	20.00
9	TO RE-SEAL ANTI-RUST	New	50.00	20.00
Gross Labour Cost (\$\$)			2,010.00	1,670.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >