

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22000575/VEA3Q2**Date:** 08/04/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900170689-02
Claimant Vehicle No :	SMQ2070R	Insured Vehicle No :	SMP5728M
Date of Loss:	14/01/2022	Nature of Claim:	TP
		Claim No:	3090624623SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMQ2070R		
Make & Model:	TOYOTA NOAH HYBRID, 1.8 X CVT (A)	Engine No:	2ZR2D02700
Reg. Date:	01/11/2019 (Man. Year: 2019)	Chassis No:	ZWR800376067
Colour:	Black	Odometer:	206208 km
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,986.52	7,695.79	6,290.73	44.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,720.00	2,270.00	1,450.00	38.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,706.52	9,965.79	7,740.73	43.72
Approved Total (Overridden) (S\$)		8,000.00		
(S\$)	17,706.52	8,000.00	9,706.52	54.82
+ GST 7.00/7.00% (S\$)	1,239.46	560.00	679.46	54.82
Nett Amount (S\$)	18,945.98	8,560.00	10,385.98	54.82
+ Car Rental (6.0 x S\$95.00/day + 7.00% GST) (S\$)		609.90		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		9,206.35		
Global Sum Settlement (S\$)		9,200.00		

INSPECTION

Date of Assignment:	17/01/2022	
Date Inspected:	17/01/2022 Inspected At:	Ryder Auto Pte Ltd (HQ) 2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit Singapore 417921
Estimated Period of Repair:	5.0 days	

Adjuster: Thevan Thomas Karthikesavan**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	1,583.20 FL	*1,025.00 FL
2	10		*REAR BUMPER CLIPS	Necessary	30.00 FS	*20.00 FS
3	2		*REAR BUMPER SCREW	Necessary	30.00 FS	*20.00 FS
4	1		*REAR BUMPER O/S & N/S REFLECTOR	O/S Cracked	247.10 FL	*123.50 FL
5	1		*REAR BUMPER O/S & N/S RETAINER	O/S Necessary	208.60 FL	*100.00 FL
6	1		*SET REAR BUMPER REVERSE SENSOR	Cut	956.20 FL	*200.00 FL
7	1		*REAR BUMPER TOW COVER	Serviceable	70.50 FL	*- FL
8	2		*REAR BUMPER O/S & N/S TOP GARNISH	Distorted	561.80 FL	*360.00 FL
9	8		*REAR BUMPER O/S & N/S TOP GARNISH CLIPS	Necessary	24.00 FS	*12.00 FS
10	1		*REAR TAIL GATE	Dented	2,434.50 FL	*1,416.35 FL
11	1		*REAR TAIL GATE INNER TRIM	Cut	725.80 FL	*495.80 FL
12	8		*REAR TAIL GATE INNER TRIM CLIPS	Necessary	24.00 FS	*20.00 FS
13	1		*REAR HYBRID EMBLEM	Necessary	88.20 FL	*88.20 FL
14	1		*REAR TAIL GATE EMBLEM	Necessary	121.20 FL	*67.60 FL
15	1		*REAR TAIL GATE MOULDING CHROME	Cut	856.50 FL	*773.80 FL
16	1		*REAR TAIL GATE LOCK UPPER	Jammed	251.70 FL	*251.70 FL
17	1		*REAR TAIL GATE LOCK ACTUATOR	Not Necessary	765.30 FL	*- FL
18	1		*REAR TAIL GATE WEATHERSTRIP	Cut	424.00 FL	*299.20 FL
19	1		*REAR END PANEL	Dented	645.20 FL	*590.00 FL
20	1		*REAR END PANEL INNER TRIM	Cut	292.50 FL	*148.00 FL
21	1		*REAR END PANEL INNER TRIM CLIPS (6 PCS)	Necessary	30.00 FS	*20.00 FS
22	1		*REAR O/S & N/S FENDER INNER TRIM	O/S Bent	1,765.20 FL	*681.00 FL
23	1		*REAR BOOT FLOOR PANEL (NPA)	Repair	0.00 FL	*- FL
24	1		*REAR O/S & N/S TAIL LAMP PANEL (O/S)	Bent	390.00 FL	*390.00 FL
25	2		*REAR O/S & N/S TAIL LAMP	Scratched	1,635.60 FL	*1,562.00 FL
26	1		*REAR WINDSCREEN MOULDING	Necessary	220.00 FS	*100.00 FS
27	1		*REAR WINDSCREEN SEALANT	Necessary	120.00 FS	*60.00 FS
28	1		*SOLAR FILM	Serviceable	200.00 FS	*- FS
29	1		*REAR CARPET	Cut	810.50 FL	*350.00 FL
30	1		*REAR CARPET COVER	Dented	81.60 FL	*81.60 FL
31	1		*REAR ANTENNA	Cut	221.60 FL	*165.00 FL
32	1		*REAR O/S FENDER INNER TRIM HOLDER BRACKET	Cracked	45.60 FL	*45.60 FL
33	1		*REAR FLOOR BOARD	Bent	710.70 FL	*710.70 FL
34	1		*REAR BLOWER	Serviceable	1,851.60 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	18,422.70	10,177.05
- List Item Discount on L Items 25.00/25.00% (\$\$)	4,436.18	2,481.26
Total Parts (\$\$)	13,986.52	7,695.79

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE DAMAGED PARTS ,STRAIGHTEN & WELDING	New	1,400.00	1,000.00
2	TO SPRAY PAINTING	New	1,200.00	900.00
3	TO REMOVE AND REFIT REAR WINDSCREEN	New	200.00	120.00
4	TO REMOVE AND REPLACE REAR REVERSE SENSOR	New	80.00	20.00
5	TO REMOVE AND REFIT MECHANISM & MOTOR	New	80.00	30.00
6	TO REMOVE AND REFIT UPHOLSTERY TO FACILITATE REPAIR	New	180.00	50.00
7	TO REMOVE AND REPLACE REAR TAIL GATE	New	180.00	60.00
8	TO RESEAL ANTI RUST	New	100.00	40.00
9	TO RESET ELECTRICAL SYSTEM	New	250.00	30.00
10	TO CHECK WIRING	New	50.00	20.00
Gross Labour Cost (\$\$)			3,720.00	2,270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >