

2 Kaki Bukit Ave 2, #02-100 Singapore 417921

Email: info@lkh.com.sg

ESTIMATE WORK ORDER

Acknowledged by Repairs

Signature

Model

TOYOTA NOAH HYBRID

11112019

SMP5728M(AIG)

Veh# : SMQ2070R

Accident Date : 14/1/2021

Location : CTE TOWARDS SLE BETONG ANG MO KIO AVE 1

3P:

ThomOLhhauto.com
82235769
17/1/22 1530
5 days wp

h/No.	Qty	Description	Unit \$	S/Nett \$	Nett \$
1	1 pc	Rear bumper			
2	10 pcs	Rear bumper clips	1,583.20		
3	2 pcs	Rear bumper screw		30.00	20
4	2 pcs	Rear bumper o/s & n/s reflector SVC		30.00	20
5	2 pcs	Rear bumper o/s & n/s retainer SVC	247.10		
6	1 set	Rear bumper reverse sensor	208.60		
7	1 pc	Rear bumper tow cover	256.20		
8	2 pcs	Rear bumper o/s & n/s top garnish	70.50		
9	8 pc	Rear bumper o/s & n/s top garnish clips	561.80		
10	1 pc	Rear tail gate		24.00	12
11	1 pc	Rear tail gate inner trim	2434.50		
12	8 pcs	Rear tail gate inner trim clips	725.80		
13	1 pc	Rear HYBRID emblem	32.00	50	20
14	1 pc	Rear tail gate emblem	88.20		
15	1 pc	Rear tail gate moulding chrome	121.20		
16	1 pc	Rear tail gate lock upper	856.50		
17	1 pc	Rear tail gate lock actuator	251.70		
18	1 pc	Rear tail gate weather strip	765.30		
19	1 pc	Rear end panel	424.00		
20	1 pc	Rear end panel inner trim	645.20		
21	6 pcs	Rear end panel inner trim clips	292.50		
22	2 pcs	Rear o/s & n/s fender inner trim XI ds		30.00	20
23	1 pc	Rear boot floor panel	1,765.20		
24	2 pcs	Rear o/s & n/s tail lamp panel XI o/s			
25	2 pcs	Rear o/s & n/s tail lamp	1,635.60		
26	1 pc	Rear windscreen moulding		220.00	100
27	1 pc	Rear windscreen sealant		120.00	60
28	1 pc	Solar film		200.00	
		Sub Total:	13,665.10	654.00	0.00
			25%	0%	10%
		After Less %:	10,248.83	654.00	0.00
		Labour			
1		To dismantle damaged parts, straighten & welding.	1,400.00		
2		To spray painting.	1,200.00		
3		To remove and refit rear windscreen	200.00		
4		To remove and replace rear reverse sensor.	80.00		
5		To remove and refit mechanism & motor	80.00		
6		To remove and refit upholstery to facilitate repair	180.00		
7		To remove and replace rear tail gate	180.00		
8		To re seal anti rust.	100.00		
9		To re set electrical system.	250.00		
10		To check wiring.	50.00		
		Sub Total:	3,720.00		
		Total:	14,622.83		
		After Less 30%:	11,698.26		

DT 1025
nec
nec
Cra 123.5
nec 100
Cut 200
XSVc
DES 360
nec
DT 1416.35
Cut 445.9
nec
nec 67.6
Cut 233.9
XJWH
XNN
Cut 294.2
125 390
Cut/BF 149
nec
BT 691
XR
bt 390
Sec 1562
nec
nec
SVC

1600
120
20
30
30
60
40
30
20

Chan

Chan San Choon
Director
DipEng, AAE, MIM, MSAE(Aust)



SMQ2070R ESTIMATEPg1



2 Kaki Bukit Ave 2, #02 19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

SUPPLEMENTARY ESTIMATE OF REPAIR

Veh# : SMQ2070R

Model: TOYOTA NOAH HYBRID

Accident Date : 14/1/2021

1/11/2019

Location : CTE TOWARDS SLE BEFORE ANG MO KIO AVE 1

3P: SMP5728M(AIG)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Rear carpet	810.50		
2	1 pc	Rear carpet cover	81.6		
3	1 pc	Rear antenna	221.6		
4	1 pc	Rear o/s fender inner trim holder bracket	45.60		
5	1 pc	Rear floor board	710.70		
6	1 pc	Rear blower	1,851.60		
		Sub Total:	3,721.60	0.00	0.00
			25%	0%	10%
		After Less %:	2,791.20	0.00	0.00
		Total:		2,791.20	
		After Less 20%:		2,232.96	

✓ Cat 350
✓ DT
✓ Cat 165
✓ 109
✓ BT
X SUC

Chan San Choon
Director
DipEng, AAE MIMI,MSAE(Aust)



8778 1999
24 hr accident call



ESTIMATE OF REPAIR

Veh# : SMQ2070R

Model: TOYOTA NOAH HYBRID
1/11/2019

Accident Date : 14/1/2021

Location : CTE TOWARDS SLE BEFORE ANG MO KIO AVE 1

3P: SMP5728M(AIG)

Thucan@Lhhauto.com
82235769
17/1/22 1530
Lclays wp

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Rear bumper	1,583.20		
2	10 pcs	Rear bumper clips		30.00	20
3	2 pcs	Rear bumper screw		30.00	20
4	2 pcs	Rear bumper o/s & n/s reflector	247.10		
5	2 pcs	Rear bumper o/s & n/s retainer	208.60		
6	1 set	Rear bumper reverse sensor	956.20		
7	1 pc	Rear bumper tow cover	70.50		
8	2 pcs	Rear bumper o/s & n/s top garnish	561.80		
9	8 pc	Rear bumper o/s & n/s top garnish clips		24.00	12
10	1 pc	Rear tail gate	2434.50		
11	1 pc	Rear tail gate inner trim	725.80		
12	8 pcs	Rear tail gate inner trim clips		32.00	
13	1 pc	Rear HYBRID emblem	88.20		
14	1 pc	Rear tail gate emblem	121.20		
15	1 pc	Rear tail gate moulding chrome	856.50		
16	1 pc	Rear tail gate lock upper	251.70		
17	1 pc	Rear tail gate lock actuator	765.30		
18	1 pc	Rear tail gate weather strip	424.00		
19	1 pc	Rear end panel	645.20		
20	1 pc	Rear end panel inner trim	292.50		
21	6 pcs	Rear end panel inner trim clips		30.00	
22	2 pcs	Rear o/s & n/s fender inner trim	1,765.20		
23	1 pc	Rear boot floor panel			
24	2 pcs	Rear o/s & n/s tail lamp panel			
25	2 pcs	Rear o/s & n/s tail lamp	1,635.60		
26	1 pc	Rear windscreen moulding		220.00	100
27	1 pc	Rear windscreen sealant		120.00	60
28	1 pc	Solar film		200.00	50
		Sub Total:	13,665.10	654.00	0.00
			25%	0%	10%
		After Less %:	10,248.83	654.00	0.00
		Labour			
1		To dismantle damaged parts, straighten & welding.		1,400.00	600
2		To spray painting.		1,200.00	600
3		To remove and refit rear windscreen		200.00	120
4		To remove and replace rear reverse sensor.		80.00	20
5		To remove and refit mechanism & motor		80.00	30
6		To remove and refit upholstery to facilitate repair		180.00	30
7		To remove and replace rear tail gate		180.00	60
8		To re seal anti rust.		100.00	40
9		To re set electrical system.		250.00	30
10		To check wiring.		50.00	20
		Sub Total:		3,720.00	
		Total:		14,622.83	
		After Less 20%:		11,698.26	

Lutan

Chan San Choon
Director
DipEng, AAE MIMI,MSAE(Aust)

