



Your Ref : SNM22D200155/C01/TANKW

Date: 09th Mar 2022

Our Ref : CS4/CTI22000578/Evy3e2

M/s China Taiping Insurance (S) Pte Ltd

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SGT 48A
ACCIDENT ON 23/12/2021**

Instruction was received to inspect the vehicle Reg. No. SGT 48A. The inspection was conducted on 17/01/2022 at the premises of M/s Goldbell Engineering Pte Ltd, 10 Tuas Ave 18, Singapore 638894.

The following vehicle information was recorded:

Registration Number	: SGT 48A
Make/Model	: Toyota Picnic Auto W/o Roof Rack
Year of Registration	: 2009
Body Colour	: Silver
Chassis Number	: JTEGH23B200026417
Engine Capacity	: 1998 cc
Speedometer Reading	: Not Available

The vehicle sustained damages at the front portion, undercarriage and interior. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 50,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 22,828.00)
Nett Liability	<u>S\$ 27,172.00</u> =====

Vehicle Inspected By:



CHEN TSUE YEE
Automotive Assessor



K.K.LAU
MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.