

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22000579/AQY3N2**Date:** 23/03/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00069762100

Claimant Vehicle No : SMH8547R**Insured Vehicle No :** GBK3616Y

Date of Loss: 13/01/2022

Nature of Claim: TP

Claim No: SNM22D200365/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMH8547R**

Make & Model: HONDA SHUTTLE HYBRID, 1.5 (A)

Engine No: LEB7105972

Reg. Date: 12/02/2019 (Man. Year: 2018)

Chassis No: GP72004617

Colour: Red

Odometer: 149242 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60 R15

Rear Tyre Size: 195/60 R15

Front Left Side: West Lake 6 mm

Rear Left Side: West Lake 6 mm

Front Right Side: West Lake 6 mm

Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,292.96	5,452.00	6,840.96	55.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,850.00	1,970.00	880.00	30.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	15,142.96	7,422.00	7,720.96	50.99
Approved Total (Overridden) (\$\$)		5,900.00		
(\$\$)	15,142.96	5,900.00	9,242.96	61.04
+ GST 7.00/7.00% (\$\$)	1,060.01	413.00	647.01	61.04
Nett Amount (\$\$)	16,202.97	6,313.00	9,889.97	61.04

INSPECTION

Date of Assignment: 14/01/2022

Date Inspected: 17/01/2022

Inspected At:

8 KAKI BUKIT AVE 4

#06-31 PREMIER @ KAKI BUKIT

REPAIRER: HUA HONG PTE LTD

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 22 Mar 2022)	
Parts:	N/A	HONDA SHUTTLE HYBRID 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMH8547R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	2,101.00 FL	*1,050.00 FL
2	10		*FRONT BUMPER CLIPS	Necessary	50.00 FL	*30.00 FL
3	1		*FRONT BUMPER SIDE RETAINER (LH/RH)	O/s Damaged	88.20 FL	*44.10 FL
4	1		*FRONT BUMPER TOWING COVER	Missing	57.00 FL	*57.00 FL
5	1		*FRONT BUMPER REINFORCEMENT	Dented	594.00 FL	*420.00 FL
6	1		*FRONT BUMPER UNDERCOVER	Torn	600.60 FL	*220.00 FL
7	1		*FRONT BUMPER GARNISH (RH)	Not Necessary	87.00 FL	*- FL
8	1		*FRONT FENDER (RH)	Dented	1,035.20 FL	*452.00 FL
9	1		*FRONT FENDER INNERSHIELD (RH)	Torn	241.00 FL	*168.00 FL
10	10		*FRONT FENDER INNERSHIELD CLIPS	Necessary	50.00 FL	*30.00 FL
11	1		*FRONT FENDER LOGO (HYBRID)	Necessary	131.80 FL	*65.00 FL
12	1		*FRONT FENDER QUARTER GLASS (RH)	Cut	581.40 FL	*581.40 FL
13	1		*FRONT DOOR (RH)	Repair	1,697.40 FL	*- FL
14	1		*FRONT DOOR STICKER (RH)	Necessary	135.00 FL	*60.00 FL
15	1		*FRONT DOOR WINDOW OUTER MOULDING (RH)	Not Necessary	226.80 FL	*- FL
16	1		*FRONT DOOR SIDE MIRROR ASSY (RH)	Damaged	1,147.40 FL	*695.00 FL
17	1		*FRONT DOOR SIDE MIRROR COVER (RH)	Cracked	165.00 FL	*85.00 FL
18	1		*FRONT HEADLAMP (RH)	Cracked	3,473.40 FL	*2,250.00 FL
19	1		*FRONT HEADLAMP BRACKET (RH)	Cracked	121.50 FL	*45.00 FL
20	1		*FRONT GRILLE BASE	Not Necessary	790.00 FL	*- FL
21	1		*FRONT GRILLE OUTER CHROME TOP	Not Necessary	725.00 FL	*- FL
22	1		*FRONT GRILLE OUTER CHROME BOTTOM	Not Necessary	441.40 FL	*- FL
23	1		*FRONT GRILLE EMBLEM	Not Necessary	82.20 FL	*- FL
24	1		*WASHER TANK	Deformed	256.40 FL	*125.00 FL
25	1		*SEALANT	Not Necessary	40.00 FS	*- FS
26	1		*FRONT RIM (RH)	Cut	350.00 FS	*350.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,268.70	6,727.50
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,975.74	1,275.50
Total Parts (\$\$)	12,292.96	5,452.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE AND CHANGE FRONT BUMPER,FRONT FENDER (RH),FRONT REINFORCEMENT,FRONT DOOR (RH),FRONT SIDE MIRROR (RH),FRONT HEADLAMP (RH),KNOCKING FRONT FENDER INNER PANEL (RH)	New	1,200.00	800.00
2	TO PERFORM WIRE CHECKING	New	50.00	30.00
3	TO DISMANTLE & REPLACE FRONT DOOR (RH) MECHANISM AND FITTING TO NEW DOOR	New	80.00	80.00
4	TO REMOVE & REPLACE NEW FRONT DOOR QUARTER GLASS (RH)	New	120.00	60.00
5	TO SPRAY FRONT BUMPER,FRONT FENDER (RH),FRONT REINFORCEMENT,FRONT DOOR (RH),FRONT FENDER INNER PANEL (RH),FRONT SIDE MIRROR COVER (RH)	New	1,400.00	1,000.00
Gross Labour Cost (\$\$)			2,850.00	1,970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >