

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22000581/BQY3E2**Date:** 09/02/2023REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00106952100
Claimant Vehicle No :	SKB8387R	Insured Vehicle No :	GBK5478R
Date of Loss:	10/01/2022	Nature of Claim:	TP
		Claim No:	SNM22D200277/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKB8387R	Engine No:	G4FC8U565668
Make & Model:	HYUNDAI AVANTE, 1.6 (A)	Chassis No:	KMH DU41BR9U647990
Reg. Date:	24/01/2009 (Man. Year: 2008)	Odometer:	207311 km
Colour:	Red		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Hankook 5 mm	Rear Left Side:	Hankook 5 mm
Front Right Side:	Hankook 5 mm	Rear Right Side:	Hankook 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,942.40	2,650.32	3,292.08	55.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,950.00	1,760.00	1,190.00	40.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,892.40	4,410.32	4,482.08	50.40
Approved Total (Overridden) (S\$)		3,550.00		
(S\$)	8,892.40	3,550.00	5,342.40	60.08
+ GST 8.00/8.00% (S\$)	711.39	284.00	427.39	60.08
Nett Amount (S\$)	9,603.79	3,834.00	5,769.79	60.08

INSPECTION

Date of Assignment:	14/01/2022	
Date Inspected:	17/01/2022	Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	7.0 days	

Adjuster: Lim Teow Guan**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Feb 2023)
Parts:	143	HYUNDAI AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKB8387R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEAD LAMP RH	Broken	455.00 FL	*455.00 FL
2	1		*FRONT HEAD LAMP LOWER BRACKET RH	Broken	67.20 FL	*67.20 FL
3	1		*FRONT SUPPORT PANEL	Broken	928.90 FL	*783.00 FL
4	1		*FRONT GRILLE	Cracked	245.00 FL	*245.00 FL
5	1		*FRONT GRILLE EMBLEM	Necessary	37.50 FL	*37.50 FL
6	1		*FRONT BUMPER	Dented	530.20 FL	*494.00 FL
7	2		*FRONT BUMPER SIDE RETAINER	Necessary	76.80 FL	*76.80 FL
8	1		*FRONT BUMPER INNER SPONGE	Broken	144.90 FL	*144.90 FL
9	1		*FRONT SHOCK ABSORBER RH	Not Necessary	450.00 FL	*- FL
10	1		*FRONT SHOCK ABSORBER MOUNTING RH	Not Necessary	344.00 FL	*- FL
11	1		*FRONT KNUCKLE ARM RH	Not Necessary	504.40 FL	*- FL
12	1		*FRONT WHEEL BEARING RH	Not Necessary	269.60 FL	*- FL
13	1		*FRONT WHEEL BEARING HUB RH	Not Necessary	390.60 FL	*- FL
14	1		*FRONT LOWER ARM RH	Not Necessary	496.60 FL	*- FL
15	1		*FRONT BALL JOINT	Not Necessary	165.00 FL	*- FL
16	1		*FRONT FENDER RH	Dented	650.30 FL	*525.00 FL
17	1		*FRONT FENDER INNER SHIELD RH	Torn	172.00 FL	*172.00 FL
18	1		*FRONT RIM RH (LOCAL REPAIR)	Cut	700.00 FS	*200.00 FS
19	1		*FRONT TYRE RH	Not Necessary	350.00 FS	*- FS
20	1		*FRONT BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
21	1		*FRONT FENDER INNER SHIELD CLIP	Necessary	100.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	7,128.00	3,250.40
- List Item Discount on L Items 20.00/20.00% (\$)	1,185.60	600.08
Total Parts (\$)	5,942.40	2,650.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING CHARGE	New	120.00	0.00
2	REMOVE AND RENEW AIRCON CONDENSER AND REFILL GAS	New	150.00	80.00
3	CHECK WHEEL ALIGNMENT	New	80.00	80.00
4	LABOUR CHARGE STRAIGHTEN REPAIR FRONT DAMAGE PORTION, CUT, WELDING	New	1,500.00	1,000.00
5	RESPRAYING PAINTING	New	1,000.00	600.00
6	TUFF KOTE	New	100.00	0.00
Gross Labour Cost (\$\$)			2,950.00	1,760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >