

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22000582/KTY3N2
Date: 23/06/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00127052101
Claimant Vehicle No :	SKC9853A	Insured Vehicle No :	SLM2086D
Date of Loss:	06/01/2022	Nature of Claim:	TP
		Claim No:	SNM22D200173/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKC9853A	Engine No:	LEA1004084
Make & Model:	HONDA CR-Z 1.5L MT, 1.5 Beta (A)	Chassis No:	ZF11004081
Reg. Date:	21/10/2011 (Man. Year: 2010)	Odometer:	108683 km
Colour:	Metallic Pearl White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45ZR17	Rear Tyre Size:	225/45ZR17
Front Left Side:	Habilead 2 mm	Rear Left Side:	Habilead 4 mm
Front Right Side:	Habilead 2 mm	Rear Right Side:	Habilead 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,190.36	1,702.24	5,488.12	76.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,970.00	880.00	4,090.00	82.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	12,160.36	2,582.24	9,578.12	78.77
Approved Total (Overridden) (\$\$)		2,050.00		
	12,160.36	2,050.00	10,110.36	83.14
+ GST 7.00/7.00% (\$\$)	851.23	143.50	707.73	83.14
Nett Amount (\$\$)	13,011.59	2,193.50	10,818.09	83.14

INSPECTION

Date of Assignment:	14/01/2022	
Date Inspected:	17/01/2022 Inspected At:	BH Auto Services Pte Ltd (Sin Ming) Blk 1 Sin Ming Industrial Estate Sector C, #01/111/113/115/117 Singapore 575636
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

THE REPAIRER IS INFORMED ON THE REVISED AMOUNT BUT NOT AGREED WITH OUR RECOMMENDATION

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 23 Jun 2022)**Parts:** 144 HONDA CR-Z 1.5L MT 1.5 Beta (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SKC9853A)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEAD LIGHT RH	Cut	1,205.00 FL	*1,081.00 FL
2	1		*FRONT GRILLE	Serviceable	225.70 FL	*- FL
3	1		*HEAD LIGHT RETAINERS RH	Distorted	35.00 FL	*35.00 FL
4	1		*FRONT BUMPER	Mtg Cracked	770.50 FL	*680.20 FL
5	1		*FRONT BUMPER RETAINERS	Serviceable	18.00 FL	*- FL
6	1		*FRONT FENDER RH	Repair	580.00 FL	*- FL
7	1		*HONDA EMBLEM	Necessary	27.50 FL	*27.50 FL
8	1		*FRONT SIDE FENDER COWLING RH	Cracked	116.60 FL	*116.60 FL
9	1		*FRONT BUMPER BOTTOM LID RH	Serviceable	21.40 FL	*- FL
10	1		*FRONT ABSORBER RH	Serviceable	367.60 FL	*- FL
11	1		*LOWER ARM RH	Serviceable	608.40 FL	*- FL
12	1		*DRY SHAFT RH	Repair	1,338.50 FL	*- FL
13	1		*STABLIZING LINK RH	Serviceable	81.90 FL	*- FL
14	1		*WHEEL BEARING RH	Not Necessary	131.80 FL	*- FL
15	1		*SUPPORT PANEL	Repair	689.50 FL	*- FL
16	1		*BONNET	Repair	872.10 FL	*- FL
17	1		*FRONT REINFORMENT BAR	Repair	249.40 FL	*- FL
18	1		*TIE ROD RH	Serviceable	90.30 FL	*- FL
19	1		*TIE ROD END RH	Serviceable	144.50 FL	*- FL
20	1		*TOP STOPPER RH	Serviceable	25.90 FL	*- FL
21	1		*DUST COVER RH	Serviceable	27.40 FL	*- FL
22	1		*BUSH RH	Serviceable	43.90 FL	*- FL
23	1		*FRONT RIM RH (LOCAL REPAIR)	Scratched	768.64 FS	*150.00 FS
24	1		*FRONT TYRE RH	Serviceable	285.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	8,724.54	2,090.30
- List Item Discount on L Items 20.00/20.00% (S\$)	1,534.18	388.06
Total Parts (S\$)	7,190.36	1,702.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	ANTI-RUST COATING	New	320.00	0.00
2	PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS,PANEL BEAT,CUT & WELD IF NECESSARY AND ALIGN ALL PANEL AND REINSTALL ALL DAMAGED PARTS	New	2,000.00	400.00
3	PROVIDE SKILL LABOUR & MATERIAL TO PUTTY ALL DAMAGED PARTS & PANEL & TO RESPRAY WITH 2K PAINT WITH OVEN SPRAY BOOTH FACILITIES	New	2,000.00	400.00
4	PROVIDE SKILL LABOUR TO DISCONNECT AND CHECK ELECTRICAL WIRING	New	150.00	20.00
5	PROVIDE LABOUR SKILL TO CHECK UNDERCARRIAGE,REMOVAL AND REPLACEMENT	New	300.00	0.00
6	PROVIDE SKILL LABOUR FOR WHEEL ALIGNMENT	New	200.00	60.00
Gross Labour Cost (\$\$)			4,970.00	880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >