

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKD 9450Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT EMBOSS NUMBER PLATE (SN)	BENT	83.00	83.00
1	SUNDRIES (SN)	NECESSARY	150.00	150.00
1	FRT BUMPER TOWING HINGE FLAP (SN)	NOT NECESSARY	54.30	-
1	FRT BUMPER LICENCE PLATE BASE PRIME (SN)	BROKEN	82.95	82.95
1	FRT BUMPER CARRIER COVER (SN)	NOT NECESSARY	38.10	-
1	FRT BUMPER (PDC) (SN)	BROKEN	1,993.70	1,993.70
1	FRT BUMPER CTR GRID (SN)	BROKEN	88.85	88.85
1	FRT BUMPER CARRIER (SN)	NOT NECESSARY	921.50	-
1	FRT BUMPER LH SHOCK ABSORBER (SN)	NOT NECESSARY	73.75	-
1	FRT BUMPER RH SHOCK ABSORBER (SN)	NOT NECESSARY	73.75	-
1	GRILLE LEFT (SCHWARZ) (SN)	CUT	191.85	191.85
1	GRILLE RIGHT (SCHWARZ) (SN)	CUT	191.85	191.85
2	EMBLEM GROMMET (SN)	NECESSARY	1.90	1.90
1	BMW EMBLEM 82MM (SN)	CUT	72.85	72.85
4	PDC SENSOR (SN)	NOT NECESSARY	1,484.80	-
1	FRT BUMPER RH MOUNT LATERAL (SN) (ADDITIONAL)	BROKEN	20.95	20.95
1	RH DIRECTION INDICATOR LIGHT WHITE (SN) (ADDITIONAL)	BROKEN	524.60	524.60
			6,048.70	3,402.50
	<u>LABOUR</u>			
	REPLACE FRONT BUMPER INCLUDE ATTACHMENT ETC AND REPAIR BONNET.		2,125.00	1,275.00
	PAINTING FRONT BUMPER AND BONNET.		2,336.00	2,102.00
	TO CHECK ELECTRICAL WIRING SYSTEM AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENT OF HEADLIGHTS.		177.00	168.00
	TO REMOVE OLD PDC ASSEMBLY, REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION.		177.00	168.00
			4,815.00	3,713.00
	GRAND TOTAL		10,863.70	7,115.50

Report Ref No. CS/LPC22000586/Evf3e2



Page No.:2 of 2

RECOMMENDED COST OF REPAIRS			7,115.5	0
-----------------------------	--	--	---------	---

Report Ref No. CS/LPC22000586/Evf3e2



Automotive Assessor



ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser