

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22000593/KTY3Q2**Date:** 01/04/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00043612100

**Claimant Vehicle
No :** FBE9404J**Insured
Vehicle No :** GBL2012R

Date of Loss: 13/01/2022

Nature of Claim: TP

Claim
No: SNM22D200389/C02/TOHHS**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **FBE9404J**

Make & Model: YAMAHA T135, 135cc

Engine No: 5YP302787

Reg. Date: 12/11/2010 (Man. Year: 2010)

Chassis No: 5YP302787

Colour: Black

Odometer: 28943 km

Engine Capacity: 135 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 70/90 R17

Rear Tyre Size:

80/90 R17

Front Left Side: Maxxis 4 mm

Rear Left Side:

Maxxis 4 mm

Front Right Side: 0 mm

Rear Right Side:

0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,119.10	516.90	3,602.20	87.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	920.00	110.00	810.00	88.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,039.10	626.90	4,412.20	87.56
Approved Total (Overridden) (S\$)		450.00		
(S\$)	5,039.10	450.00	4,589.10	91.07
+ GST 7.00/7.00% (S\$)	352.74	31.50	321.24	91.07
Nett Amount (S\$)	5,391.84	481.50	4,910.34	91.07

INSPECTION

Date of Assignment: 17/01/2022

Date Inspected: 23/02/2022 Inspected At:

Thiam Heng Huat Pte Ltd (SIN MING)
176 SIN MING DRIVE, #05-14
Singapore 575721

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 31 Mar 2022)	
Parts:	N/A	YAMAHA T135 135cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBE9404J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEAD LAMP	Serviceable	150.00 FL	*- FL
2	1		*HEAD LAMP COWLING	Serviceable	75.00 FL	*- FL
3	1		*HEAD LAMP GARNISH	Serviceable	95.00 FL	*- FL
4	1		*FRONT TYRE	Serviceable	150.00 FL	*- FL
5	1		*FRONT WHEEL RIM	Serviceable	280.00 FL	*- FL
6	1		*FRONT WHEEL FENDER	Serviceable	65.00 FL	*- FL
7	1		*HEAD LAMP BRACKET	Repair	25.00 FL	*- FL
8	1		*FRONT COWLING	Dented / Cracked	70.00 FL	*70.00 FL
9	1		*FRONT COWLING LOGO	Necessary	18.00 FL	*18.00 FL
10	1		*SPEEDOMETER	Serviceable	315.00 FL	*- FL
11	1		*FRONT BRAKE DISC	Serviceable	85.00 FL	*- FL
12	1		*FRONT BRAKE CALIPER	Serviceable	265.00 FL	*- FL
13	1		*ERP UNIT	Serviceable	160.00 FL	*- FL
14	1		*SIDE FAIRING -LH	Serviceable	145.00 FL	*- FL
15	1		*SIDE FAIRING -RH	Cracked	145.00 FL	*145.00 FL
16	1		*SIDE FAIRING LOGO	Not Necessary	18.00 FL	*- FL
17	1		*FRONT SIGNAL LAMP LH	Serviceable	35.00 FL	*- FL
18	1		*FRONT SIGNAL LAMP RH	Serviceable	35.00 FL	*- FL
19	1		*CLUTCH LEVER	Serviceable	28.00 FL	*- FL
20	1		*SET BALANCER	Serviceable	50.00 FL	*- FL
21	1		*HANDLE BAR	Serviceable	85.00 FL	*- FL
22	1		*SET MIRROR	Serviceable	60.00 FL	*- FL
23	1		*SET FRONT FOOT	O/S Bent	56.00 FL	*28.00 FL
24	2		*REAR FOOT REST	Serviceable	56.00 FL	*- FL
25	1		*GEAR PEDAL	Serviceable	38.00 FL	*- FL
26	1		*MAIN STAND	Repair	45.00 FL	*- FL
27	1		*SWING ARM	Serviceable	295.00 FL	*- FL
28	1		*SWING ARM SHAFT	Serviceable	35.00 FL	*- FL
29	1		*ENGINE SIDE COVER	Serviceable	185.00 FL	*- FL
30	1		*FRONT FORK ASSY LH	Serviceable	140.00 FL	*- FL
31	1		*FRONT FORK ASSY RH	Serviceable	140.00 FL	*- FL
32	1		*FRONT FORK BRACKET	Repair	80.00 FL	*- FL
33	1		*REAR WHEEL FENDER	Serviceable	75.00 FL	*- FL
34	1		*REAR EXHAUST /MUFFLER	Repair	320.00 FL	*- FL
35	1		*REAR EXHAUST COVER	Dented	180.00 FL	*180.00 FL
36	1		*BOX CARRIER (BRACKET)	Bent	120.00 FS	*120.00 FS
37	1		*TOP BOX	Serviceable	200.00 FS	*- FS
38	1		*REAR LICENCE PLATE	Serviceable	20.00 FS	*- FS
39	1		*FORK OIL	Not Necessary	20.00 FS	*- FS
40	4		*FORK SEAL	Not Necessary	40.00 FS	*- FS
41	1		*SET STICKER	Not Necessary	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,519.00	561.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	399.90	44.10
Total Parts (\$\$)	4,119.10	516.90

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING SERVICE	New	50.00	0.00
2	TO REALIGN REAR WHEEL SWITH ARM AND CHASSIS	New	100.00	0.00
3	TO CHECK WIRING SYSTEM	New	30.00	10.00
4	TO REMOVE AND REFIX REAR BOX AND BRACKET	New	40.00	20.00
5	TO DISMANTLE /RENEW ACCIDENT DAMAGED PORTION .TO PANEL BEAT ,RESHAPE ,STRAIGHTEN ,ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS	New	400.00	80.00
6	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY AFFECTED AREA /PANEL	New	300.00	0.00
Gross Labour Cost (\$\$)			920.00	110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >