

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22000594/UEA3Q2**Date:** 06/09/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900252329
Claimant Vehicle No :	GBF2249G	Insured Vehicle No :	SMQ6606U
Date of Loss:	11/01/2022	Nature of Claim:	TP
		Claim No:	5479079550SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBF2249G		
Make & Model:	TOYOTA DYNA 150, 3.0 D (M)	Engine No:	1KD2594475
Reg. Date:	03/08/2016 (Man. Year: 2016)	Chassis No:	JTFAT35Y20K206220
Colour:	White	Odometer:	285024 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	155 R12 (D)
Front Left Side:	Tourador 6 mm	Rear Left Side:	Tourador 6/6 mm
Front Right Side:	Tourador 6 mm	Rear Right Side:	Tourador 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,637.35	240.67	1,396.68	85.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,080.00	700.00	380.00	35.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,717.35	940.67	1,776.68	65.38
+ GST 7.00/7.00% (S\$)	190.21	65.85	124.36	65.38
Nett Amount (S\$)	2,907.56	1,006.52	1,901.04	65.38
+ Car Rental (2.0 x S\$100.00/day + 7.00% GST) (S\$)		214.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,222.52		

INSPECTION

Date of Assignment:	17/01/2022		
Date Inspected:	17/01/2022	Inspected At:	Tan Lim Motor Pte Ltd (Defu) 1 Defu Lane 6 Singapore 539365
Estimated Period of Repair:	2.0 days		

Adjuster: MARCUS CHUA**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE LID	Repair	1,067.00 FL	*- FL
2	1		*TAILGATE LID LOCK	Not Necessary	136.40 FL	*- FL
3	1		*TAILGATE LID TOYOTA STICKER	Not Necessary	224.70 FL	*- FL
4	1		*TAILGATE LID DYNA STICKER	Necessary	55.80 FL	*55.80 FL
5	2		*TAILGATE LID STOPPERS	Not Necessary	57.40 FL	*- FL
6	1		*TAILGATE LID STEP PANEL	Repair	238.70 FL	*- FL
7	1		*N/S REAR LAMP	Cracked	309.80 FL	*265.10 FL
8	1		*TAILGATE LID 70 KM/H STICKER	Not Necessary	35.00 FS	*- FS
9	1		*TAILGATE LID 13 PAX STICKER	Not Necessary	35.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					2,159.80	320.90
- List Item Discount on L Items 25.00/25.00% (S\$)					522.45	80.23
Total Parts (S\$)					1,637.35	240.67
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	80.00	20.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	500.00	380.00
3	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	500.00	300.00
Gross Labour Cost (\$\$)			1,080.00	700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >