



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKT 5764K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT FENDER LH (SN)	DENTED	954.00	954.00
1	FRONT FENDER ATTACHMENT PARTS (SN)	NOT NECESSARY	75.00	-
1	FRONT FENDER BRACKET-LH (SN)	NOT NECESSARY	46.00	-
1	FRONT FENDER BRACE-LH (SN)	NOT NECESSARY	107.00	-
6	POP RIVET (SN)	NECESSARY	23.00	22.80
1	FRONT FENDER BRACKET-LH (SN)	NOT NECESSARY	31.00	-
1	FRONT FENDER CLOSING ELEMENT-LH (SN)	NOT NECESSARY	37.00	-
1	FRONT WHEEL HOUSING LINER-LH (SN)	NOT NECESSARY	183.00	-
1	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS (SN)	NOT NECESSARY	93.00	-
1	WING MIRROR MOUNTING-LH (SN)	NOT NECESSARY	1,130.00	-
1	WING MIRROR CAP-LH (SN)	TO REPAIR SEE LABOUR	180.00	-
1	WING MIRROR GLASS (SN)	NOT NECESSARY	239.00	-
1	REAR DOOR-LH (SN)	DENTED	3,265.00	3,265.00
1	REAR DOOR BUNGS-LH (SN)	NECESSARY	5.00	4.50
1	REAR DOOR OUTER SEAL-LH (SN)	NECESSARY	179.00	178.50
1	BONDING AGENT (SN)	NOT NECESSARY	51.00	-
1	CLEANING SOLUTION (SN)	NOT NECESSARY	74.00	-
1	APPLICATOR (SN)	NOT NECESSARY	8.00	-
1	REAR DOOR ATTACHMENT PARTS (SN)	NOT NECESSARY	134.00	-
1	REAR DOOR CATCH-LH (SN)	NOT NECESSARY	94.00	-
1	REAR LID LOCK ACTUATOR (SN)	NOT NECESSARY	1,478.00	-
1	STONE CHIP (SN)	NOT NECESSARY	180.00	-
1	SUNDRIES (SN)	NECESSARY	350.00	5.40
			8,916.00	4,430.20
	<u>LABOUR</u>			
	TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.		360.00	360.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM,TO REMOVE AND RENEW LHS WING MIRROR ASSY.		280.00	280.00
	TO REMOVE AND TRANSFER LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES.INSPECT FOR DAMAGES.		350.00	350.00
	TO REMOVE AND REINSTALL REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS.TO RENEW REAR CAMERA ASSY.	NOT NECESSARY	280.00	-
	TO DISMANTLE AND REINSTALL FRONT BUMPER.TO RENEW LHS FRONT FENDER AND LHS REAR.TO REPAIR LHS SILL PANEL.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED.INCLUSIVE OF THE REPAIR OF WING MIRROR CAP-LH.		2,400.00	2,100.00
	TO RESPRAY LHS FRONT FENDER,LHS WING MIRROR COVER,LHS REAR DOOR AND LHS SILL PANEL.		3,500.00	1,700.00
	TO CARRY OUT DIAGNOSTIC CHECK.		192.00	192.00
			7,362.00	4,982.00
GRAND TOTAL			16,278.00	9,412.20
RECOMMENDED COST OF REPAIRS				9,412.20

Report Ref No. CS/SMR22000596/Etf3n2

CHEN TSUE YEE

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.